02868



Locate well correctly

DEPARTMENT OF THE INTERIOR
OFFICE OF INDIAN AFFAIRS
In cooperation with
THE GEOLOGICAL SURVEY

8453

SUPPLEMENTAL WELL RECORD

NOTE.—This supplemental well record of the deepening, plugging back, altering of casing, etc., done on the well since the previous record was filed must be submitted in DUPLICATE to the Superintendent or his agent not later than 15 days after work is completed as provided in section 18 of Operating Regulations approved July 7, 1925.

Company operating: Phillips Petroleum Company

Office address: Bartlesville, Oklahoma

Lessor: Osage Indian Nation (M.S. Norman)

Well No. 17 Sec. 11 Twp. 27N Rge. 8E County: Osage

Located in ____ ¼ NE ¼, 1296 Ft. S of North line and 1266 Ft. W of East line

Date previous record filed: December, 1928 Original depth last reported: December, 1928

Reason for doing work: Increase Production Present total depth: 3040'

Commenced work: ____, 19____ Completed work: February 16, 1929

List below all work done on well, such as redrilling, deepening record, alteration of casing in well, type of plugs used in plugging back, shooting record, and preparation of well for repressuring an area, etc. Give results of operation.

Drilled well for repressure. Started taking gas on February 16, 1929.

~~[illegible]~~ repressure

Date: January 2, 1932 Signed: C.L. Montgomery

Address of agent: R.F.D. #1, Box 1-A, Ken, Okla. Agent's title: District Superintendent

This page is for the condition of the well at above date and constitutes a complete and correct record of all work done thereon. A information may be placed on reverse side.

U. S. GOVERNMENT PRINTING OFFICE: 1934