OK 3549

Fansteel - Muskogee, OK

Received call from Jerry Block, OWRB
405-271-2541

He inspected lagoon onsite - It is unlined and he suspected groundwater contamination.

Lab man furnished results from analysis of sample from monitoring well on-site. Information was demanded back by plant manager. Mr. Block remembers some of values, however, and says that groundwater sample showed pH of 1.2 → 2.2, NH_3 and fluorides greater than 200 ppm.

If have any other questions, it is best to call him on Mondays or Fridays.

Larry Wright
2-2-81 @ 3:00 PM

195951