From: Edwards, Shaun LT
Sent By: Shaun.L.Edwards@uscg.mil
To: Richard Franklin
Subject: RE: LST1166
Date: 03/10/2010 09:07 AM

You can ride out with a couple of my guys. They will be departing here at 0800. PPE is PFD, steel toed boots, hard hat, gloves, flashlight.

LT Edwards
503-240-2566

-----Original Message-----
From: Franklin.Richard@epamail.epa.gov [mailto:Franklin.Richard@epamail.epa.gov]
Sent: Wednesday, March 10, 2010 8:31 AM
To: Edwards, Shaun LT
Subject: Re: LST1166

Thanks Shaun. Tomorrow would be good for viewing the vessel if it works for your guys. Let me know what ppe, etc you require and best time and meeting place. I guess just steel toed boots, pfd?

----- Original Message -----
From: "Edwards, Shaun LT" [Shaun.L.Edwards@uscg.mil]
Sent: 03/10/2010 08:07 AM PST
To: Richard Franklin
Subject: RE: LST1166

I think tomorrow would be the only day to go to the LST if you are able. I can get a couple of the guys to take you out there.

We sent the data up last week to Chris Fields.

LT Edwards
503-240-2566

-----Original Message-----
From: Franklin.Richard@epamail.epa.gov [mailto:Franklin.Richard@epamail.epa.gov]
Sent: Tuesday, March 09, 2010 4:03 PM
To: Edwards, Shaun LT
Subject: LST1166

Hey Shaun,

Is it possible to go see the vessel this week?

Also, were ya'll able to pull together the validated sampling data
and/or report on disposal options for the Ocean Dumping Program? If so,
I'd like to get it to them before the meeting.

Thanks

Richard Franklin
Federal On-Scene Coordinator
U.S. EPA Region 10
Oregon Operations Office
805 SW Broadway, Suite 500
Portland, OR 97205

Office: (503) 326-2917
Cell: (503) 475-4178