From: Richard Franklin
To: villa.clifford@epa.gov; field.chris@epa.gov; heister.dan@epa.gov
Subject: Fw: LST 1166 list
Date: 04/22/2010 06:11 PM
Attachments: LST 1166 cleanup list.doc

Please see below, and forward any comments. I will not look expect comments until Monday or Tuesday since folks are taking admin leave to honor Carl and de-stress. I'll be looking at this by Monday.

Richard Franklin
Federal On-Scene Coordinator
U.S. EPA Region 10
Oregon Operations Office
805 SW Broadway, Suite 500
Portland, OR 97205

Office: (503) 326-2917
Cell: (503) 475-4178

----- Forwarded by Richard Franklin/R10/USEPA/US on 04/22/2010 06:07 PM -----

From: Jonathan Freedman/R10/USEPA/US
To: Tristen Gardner/R10/USEPA/US@EPA, Richard Franklin/R10/USEPA/US@EPA
Date: 04/22/2010 06:00 PM
Subject: LST 1166 list

Richard and Tristen: The last two weeks have been an unanticipated drill that we just finished yesterday at 5:00 pm. Here is a draft list for your review. I could not locate the photos after I looked at them a week ago. Tristen, I must have downloaded them to a temp file and lost them.

I still don't know what we tell the USCG about the PCBs. Tristen, I thought you said wiring and intact paint could be left in place. That would satisfy the general permit. Please advise.

Jonathan Freedman (206) 553-0266
USEPA, Region 10
Sediment Management Program
1200 Sixth Avenue, Suite 900
ETPA - 083
Seattle WA 98101
freedman.jonathan@epa.gov

FAX: (206) 553-1775