From: Jonathan Freedman
To: Mary Queitzsch
Subject: Fw: LST 1166 list
Date: 04/23/2010 10:35 AM
Attachments: LST 1166 cleanup list.doc

Jonathan Freedman (206) 553-0266
USEPA, Region 10
Sediment Management Program
1200 Sixth Avenue, Suite 900
ETPA - 083
Seattle WA 98101
freedman.jonathan@epa.gov
FAX: (206) 553-1775

----- Forwarded by Jonathan Freedman/R10/USEPA/US on 04/23/2010 10:41 AM -----

From: Jonathan Freedman/R10/USEPA/US
To: Tristen Gardner/R10/USEPA/US@EPA, Richard Franklin/R10/USEPA/US@EPA
Date: 04/22/2010 06:00 PM
Subject: LST 1166 list

Richard and Tristen: The last two weeks have been an unanticipated drill that we just finished yesterday at 5:00 pm. Here is a draft list for your review. I could not locate the photos after I looked at them a week ago. Tristen, I must have downloaded them to a temp file and lost them.

I still don't know what we tell the USCG about the PCBs. Tristen, I thought you said wiring and intact paint could be left in place. That would satisfy the general permit. Please advise.

Jonathan Freedman (206) 553-0266
USEPA, Region 10
Sediment Management Program
1200 Sixth Avenue, Suite 900

ETPA - 083
Seattle WA 98101
freedman.jonathan@epa.gov
FAX: (206) 553-1775