Arkansas Department of Environmental Quality
Hazardous Waste Division
P.O. Box 8913, Little Rock, AR 72219-8913
Telephone: (501) 682-0833

SDMS Document ID
2002659

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Form Approved. OMB No. 2050-0039

AR-2-99

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: MTR000006742
Manifest Document No.: 00506
2. Page 1 of 2
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Environmental Protection Agency
999 18th St. Suite 500 8-EPR-ER
Denver, CO 80202-2466

4. Generator's Phone (303) 312-6808

A. State Manifest Document Number: AR-1120972
B. State Generator's ID

5. Transporter 1 Company Name: Able Clean-up Technologies
6. US EPA ID Number: WAH000011254
C. State Transporter's ID: H-
D. Transporter's Phone: 509-466-5255

7. Transporter 2 Company Name: Triad Transport
8. US EPA ID Number: OKD981588791
E. State Transporter's ID: H- 377
F. Transporter's Phone: 800-324-1139

9. Designated Facility Name and Site Address
Ensco, Inc.
309 American Circle
El Dorado, AR 71730
10. US EPA ID Number: ARD069748192
G. State Facility's ID
H. Facility's Phone: 870-863-7173

11. US DOT Description *(Including Proper Shipping Name, Hazard Class and ID Number)*	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Corrosive Liquids, acidic, inorganic, n.o.s., 8, UN 3264, PG II (Muriatic Acid, Sulfuric Acid)	001	DM	00068	P	D002
b. Waste Oxidizing liquids, corrosive, n.o.s., 5.1, UN 3098, PG II (Oxidizing Acids)	001	DM	00054	P	D001,D002
c. RQ, Waste Toxic Solids, inorganic, n.o.s., 6.1, UN 3288, PG II (Herbicide,Pesticide)	001	DM	00050	P	NA
d. Waste Nitric Acid, other than fuming red w/ not more than 70%, 8, UN 2031, PG II	001	DM	00072	P	D002

J. Additional Description for Materials Listed Above
11a. WMDS # 1331797 11b. WMDS # 1331797
11c. WMDS # 1331797 11d. WMDS # 1331797

if no alternate TSDF, return to generator US 1279

K. Emergency Response Information:
11a. RQ 100/ ERG 154
11b. RQ 100/ ERG 140
11c. RQ 10 / ERG 151
11d. RQ 100/ ERG 157

15. Special Handling Instructions and Additional Information
Report any accidental "RQ" discharge to the National Response Center at 800-424-8802 or 911 emergency. Emergency contact is Kipp Silver at 509-466-5255.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packaged, marked, and labeled/placarded, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Jude Habea
Signature: Jude Habea for EPA Region 8
Month Day Year: 09 13 00

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jason Cocke
Signature:
Month Day Year: 09 13 00

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul Wadlow for Triad
Signature:
Month Day Year: 09 15 00

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Brenda Davis
Signature: Brenda Davis
Month Day Year: 10 01 00

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

NOTICE: THE ORIGINAL AND NOT LESS THAN TWO (2) COPIES MUST MOVE WITH THE HAZARDOUS WASTE SHIPMENT. ONCE DELIVERED, THE TREATMENT/STORAGE/DISPOSAL FACILITY MUST RETURN THIS ORIGINAL COPY TO THE GENERATOR.

RECEIVED
00 OCT 10 PM 1:45
PAER/BF
PROGRAM

ensco

FORM #FS-UHWM
([redacted])

UNIFORM HAZARDOUS WASTE MANIFEST
(Continuation Sheet)

21. Generator's US EPA ID No.: MTR000006742
Manifest Document No.: 00506
22. Page: 2 of 2
Information in the shaded areas is not required by Federal law.

23. Generator's Name: Environmental Protection Agency
999 18th St. Suite 500 8-EPR-ER
Denver, CO 80202-2466

L. State Manifest Document Number: AR-1120972
M. State Generator's ID:

24. Transporter 1 Company Name: Able Clean-up Technologies
25. US EPA ID Number: WAH000011254
N. State Transporter's ID:
O. Transporter's Phone: 509-466-5255

26. Transporter 3 Company Name: Triad Transport
27. US EPA ID Number: OKD981588791
P. State Transporter's ID: 377
Q. Transporter's Phone: 800-324-1139

	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	HM	29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	Waste Flammable Liquids, n.o.s., 3, UN 1993, PG III (Paint Thinner,Gasoline)	X	001	DM	00098	P	D001
b.	Waste Corrosive Liquids, basic, inorganic, n.o.s., 8, UN 3266, PG III (Scale Remover, Caustic Soda Beads)	X	001	DM	00070	P	D002
c.	Waste Oxidizing Solid, n.o.s., 5.1, UN 1479, PG II (Granular Chlorine)	X	001	DF	00015	P	D001
d.	RQ, Environmentally Hazardous Substance, solid, n.o.s., 9, UN 3077, PG III (Polychlorinated biphenyls) OSD 6-30-00	X	001	DM	00203	P	NA
e.	RQ, Waste Corrosive Liquids, acidic, inorganic, n.o.s., 8, UN 3264, PG II (Phosphoric Acid, Sulfuric Acid)	X	001	DF	00285	P	D002
f.	RQ, Waste Corrosive Liquids, Acidic, inorganic, n.o.s., 8, UN 3264, PG II (Phosphoric Acid, Sulfuric Acid)	X	001	DF	00217	P	D002
g.	RQ, Waste Sulfuric Acid, greater than 51%, 8, UN 1830, PG II	X	001	DF	00145	P	D002
h.	RQ, Mercury contained in manufactured articles, 8, UN 2809, PG III (Flourescent Light Tubes)	X	001	DM	00080	P	~~D002~~ JC, D009
i.	RQ, Mercury contained in manufactured articles, 8, UN 2809, PG III (Flourescent Light Tubes)	X	001	DM	00176	P	~~D002~~ JC, D009

GENERATOR

S. Additional Descriptions for Materials Listed Above
28a.b.c. WMDS # 1331797 28h.i. WMDS # 1331773
28d. WMDS # 1331774
28e.f. WMDS # 09875
28g. WMDS # 09873

T. Handling Codes for Wastes Listed Above

32. Special Handling Instructions and Additional Information
28a. RQ 100/ ERG 128 28b. RQ 100/ ERG 154 28c. RQ 100/ ERG 140
28d. RQ 1/ ERG 171 28e. RQ 100/ ERG 154 28f. RQ 100/ ERG 154
28g. RQ 100/ ERG 137 28h. RQ 1/ ERG 172 28i. RQ 1/ ERG 172

TRANSPORTER

33. Transporter 3 Acknowledgement of Receipt of Materials
Printed/Typed Name: For IRM Jerry Sauterson
Signature:
Date: Month Day Year 09 21 00

34. Transporter ____ Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

35. Discrepancy Indication Space

RECEIVED

00 OCT 10 PM 1:45

PAER/BF
PROGRAM