Giant Resource Recovery – Sumter, Inc.

755 Industrial Road ◆ PO Box 1755 ◆ Sumter, SC 29151 ◆ Phone: (803) 773-1400 ◆ Fax: (803) 773-7423

Fed Ex Tracking Number: 7949 0744 8486

March 6, 2013

Office of Enforcement and Compliance Assurance
Office of Federal Activities
International Compliance Assurance Division (2254A)
Environmental Protection Agency
1200 Pennsylvania Avenue, NW.
Washington, DC 20460

Re: Giant Resource Recovery
EPA ID No. SCD036275626
Manifests for Imported Hazardous Waste
MTN: 000161409GRR

Dear Sir/Madam:

As required by 40 CFR 264.71(a)(3), Giant Resource Recovery provides the attached copies of manifests for hazardous waste received from foreign sources at our Sumter, South Carolina facility. The contents of the attachment are based on guidance received from the EPA following the July 7, 2010 effective date of the revised regulation. If you have any questions or require additional information, please contact Sheila Buckman Environmental Compliance Manager, at (803) 773-1400.

Sincerely,

Maria T Pike

Maria T Pike
Records/Manifest Manager
Giant Resource Recovery - Sumter
o: 803-773-1400 x212
c: 803-720-4641
f: 803-773-7423

received
SDH 3/11/2013

FACSIMILE COVER SHEET

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
OFFICE OF FEDERAL ACTIVITIES
INTERNATIONAL COMPLIANCE AND ASSURANCE DIVISION
1200 PENNSYLVANIA AVENUE., N.W., Rm.6144
MAIL CODE 2254A
WASHINGTON, D.C. 20460

PHONE NUMBER: 202-564-7111
FAX NUMBER: 202-564-0025

TO: Cecil Hopper

OFFICE: Giant Resources Recovery- Sumter
Giant Resource Recovery - Attalla

PHONE NUMBER: _____

FAX NUMBER: 803-775-4145
256-538-1836
843-376-2529

FROM: Jean Shaw
Import/Export Program

DATE: MAY 2 4 2012

OF PAGES:
(including cover)

COMMENTS:

2

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

OFFICE OF
ENFORCEMENT AND COMPLIANCE
ASSURANCE

May 24, 2012

CECIL HOPPER
GIANT RESOURCE RECOVERY-SUMTER, INC.
755 INDUSTRIAL ROAD, P.O. BOX 1755
SUMTER, SC 29151

Re: Foreign Notice ID: 525984
EPA Notice ID: 004872/5I/12

Dear CECIL HOPPER:

Under the requirements in 40 CFR §§ 264.71(a)(3) and 265.71(a)(3) owners and operators of hazardous waste treatment, storage, and disposal facilities receiving hazardous waste from a foreign source must submit a copy of documentation confirming EPA's consent to the import of the hazardous waste at the same time they submit a copy of the RCRA hazardous waste manifest within thirty (30) days of each import shipment's delivery.

This letter serves as EPA's import consent documentation for the export of (See Below) from FIELDING CHEMICAL TECHNOLOGIES, INC., 3575 MAVIS ROAD, MISSISSAUGA, ON, CANADA to GIANT RESOURCE RECOVERY-SUMTER, INC., 755 INDUSTRIAL ROAD, P.O. BOX 1755, SUMTER, SC. Shipments may occur under EPA's consent to the notice from May 24, 2012, to May 23, 2013. This waste will be subject to all applicable federal and state laws and regulations.

Waste Stream 1:

Waste Description:
EPA Waste Code:
DOT Shipping Name: Solids containing flammable liquid, n.o.s.
DOT Hazard Class: 4.1
DOT I.D. No. UN3175
Total Volume to be Exported: 500000 Kilograms
Estimated Frequency: 25 loads Annually

EPA is providing this letter and attachment for your potential use and recordkeeping because your facility is listed as a receiving facility or interim receiving facility in the attached notification. If your facility is not required to submit a copy of the import consent documentation along with the RCRA hazardous waste manifest under §§ 264.71(a)(3) or 265.71(a)(3) during the period of consent listed above, then you may discard this letter and attachment.

The EPA Waste Import and Export Tracking System ID assigned to this notice is 004872/5I/12.

If you have any questions regarding this correspondence, please contact Jean Shaw at telephone: 202-564-7111, telefax: 202-564-0025, or email: shaw.jean@epa.gov.

Sincerely,

Jean Shaw
for Robert G. Heiss, Director
International Compliance Assurance Division
Office of Federal Activities

cc: Stanley Tam
Regional Coordinator, Region 4

392215

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: SCD036275626
2. Page 1 of 1
3. Emergency Response Phone: 803-773-1400
4. Manifest Tracking Number: 000161409 GRR

5. Generator's Name and Mailing Address (Importer)
GIANT RESOURCE RECOVERY - SUMTER, INC
755 INDUSTRIAL ROAD PO BOX 1755
SUMTER, SC 29150
Generator's Phone: 803-773-1400

Generator's Site Address (if different than mailing address) (Foreign Generator)
FIELDING CHEMICAL TECHNOLOGIES
3549 MAVIS ROAD
MISSISSAUGA, ON, L5C 1T7
GEORGINA LACKO
905-281-4636

6. Transporter 1 Company Name: FREEHOLD CARTAGE INC
U.S. EPA ID Number: NJD054126164

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address
GIANT RESOURCE RECOVERY - SUMTER, INC
755 INDUSTRIAL ROAD PO BOX 1755
SUMTER, SC 29150
Facility's Phone: 803-773-1400
U.S. EPA ID Number: SCD036275626

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
RQ X	1. UN3175, WASTE SOLIDS CONTAINING FLAMMABLE LIQUID, N.O.S. (CONTAINS ACETONE), 4.1, PGII Secondary Emergency Response #803-773-1400	80	PM			F001	F002	F003
						F005	D001	D035
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
A. SE-124650-F001

If undeliverable, contact generator
BROKER NAME GHY International

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Carman Jones
Signature: [signature]
Month Day Year: 02 15 13

16. International Shipments ☒ Import to U.S. ☐ Export from U.S. Port of entry/exit: Lewiston NY
Transporter signature (for exports only):
Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Paula Roe
Signature: Paula Roe
Month Day Year: 02 15 13
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
11.1 = 32850 12.1 = P
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H141 2. 3. 4. 5

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Robert Sellers
Signature: [signature]
Month Day Year: 02 26 13

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

From: (803) 773-1400
Maria Pike/Records Mgr
Giant Resource Recovery
755 INDUSTRIAL ROAD

SUMTER, SC 29150

Origin ID: USCA

FedEx Express

J13101212190326

Ship Date: 06MAR13
ActWgt: 0.5 LB
CAD: 4731944/INET3370

Delivery Address Bar Code

SHIP TO: (202) 272-0167 BILL SENDER

Office of Enforcement & Compliance
US Environment Protection Agency
1200 PENNSYLVANIA AVE NW RM 6144

WASHINGTON, DC 20460

Ref #
Invoice #
PO #
Dept #

MON - 11 MAR AA
EXPRESS SAVER

TRK# 0201 7949 0744 8486

SA RDVA

20460
DC-US
DCA

518G2/DCF8/93AB

After printing this label:
1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.
Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com.FedEx will not be responsible for any claim in excess of $100 per package, whether the result of loss, damage, delay, non-delivery,misdelivery,or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim.Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental,consequential, or special is limited to the greater of $100 or the authorized declared value. Recovery cannot exceed actual documented loss.Maximum for items of extraordinary value is $1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

6 of 6