wipe & air samples came back
one fixture that Kendall tested is not below the threshold yet
9300 > kendalls test conf samples > 29
240 13

air samples in restricted rooms → all came back higher after cleaning fixtures, HEPA vac, surface cleaning
mg/m³

260 ng/m³	Room II	(was 88 ng/m³ originally)
180	annex	
390		
430		
480		
630	Room A - Annex building (Adolesc mont.)	

Kendall → at the end of the day school is responsible for cleaned ballasts

McKinstreet → came into the building to check unit ventilators
separate exhaust system
re-balanced both systems and ensured operational efficiency
- all completed prior to February sampling
  - were operating at design capacity at time of Feb test
- main air mixing chambers were ~~tested~~ cleaned prior to test
- will clean side chambers and exterior chamber in summer

Carmen Santos -
Greener Cleanups → included in Karen Schuermans package

Joanie - Sky Valley -
~~360~~ 360-804-2570
let her know if did NOT receive Mannix email

6/20/16
VM Portland Oil filters → Montana, transporting Oil
406-606-1456

VM Eileen Natoli
415-273-7481
PCBs in Bldg materials - wants better understanding of repair/renov. requirements

VM Bret Berglund SLR
Lena - MLP
soil management Plan
want to sample in June
any objections?
907-563-2128

✓ Mark Logan - UW

6/27/16 Trish - Silverton, OR
Shop property & garage
replaced all ballast - pulled them down & put in wax bag in garage
Yesterday she got all of the ballasts
7 total
none leaking 5 have date stamps I-90
2 76, 78
corroded label
no tarry liquid, but it's cracked & she can see the gasthoo