AIRCRAFT ACCIDENT REPORT
OPNAV FORM 3750-1A (Rev. 3-63) Page 1

SPECIAL HANDLING REQUIRED in accordance with Para. 66, OPNAV INSTRUCTION 3750.6, effective [illegible]

OPNAV REPORT 3750-1

PART I. GENERAL

SECTION A. IDENTIFICATION

1. AIRCRAFT ACCIDENT BOARD APPOINTED BY: Commanding Officer VF-32	2. SERIAL NO.: 2-66A	3. DTG (LOCAL) OF MISHAP: 131348N JULY	4. MODEL AIRCRAFT: F4B	5. BUREAU NUMBER: 151019
6. TO: Commander, Naval Aviation Safety Center		9. LOCATION OF MISHAP: Approx. 3/4 mi/300° REL CVA42 CLASSIFIED		10. DAMAGE: ALPHA
7. VIA: Carrier Air Wing ONE CO USS ROOSEVELT (CVA-42) Commander Second Fleet COMNAVAIRLANT	8.	11. TIME OF DAY: DAY	12. TIME IN FLIGHT: 0+07	13. FLIGHT CODE: 146
		14. CLEARED FROM: CVA-42	TO: CVA-42	
		15. TYPE CLEARANCE: VFR	16. ARS-LED: 300 Unknown KCAS	17. A/C WEIGHT: E. 46,000
18. BRIEF DESCRIPTION OF MISHAP: Uncontrolled Collision With Water			19. ELEVATION AT TIME OF MISHAP: A.L. 0 TERRAIN 0	

20. LIST MODEL, BUNO, SERIALS, DUPLICATE BUNO, CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete OPNAV Form 3750-1 for each A/C): N/A

SECTION B. CONTRIBUTING FACTORS

✓	FACTOR	✓	FACTOR	✓	FACTOR
	1. PILOT ERROR IN TECHNIQUE/JUDGMENT		9. SERVICING PERSONNEL		17. WEATHER
	2. PILOT DEVIATION FROM NATOPS PROCEDURES		10. LANDING SIGNAL OFFICER		18. DESIGN AIRCRAFT
	3. PILOT INCORRECT OPERATION OF A/C SYSTEM		11. OTHER PERSONNEL (Specify)		19. DESIGN CREW EQUIPMENT
	4. PILOT OTHER (Specify)		12. ADMINISTRATIVE		20. DESIGN OTHER (Specify)
	5. CREW		13. FACILITIES-RUNWAY, OVERRUN TAXIWAY, FLIGHT DECK		21. ROLLING/PITCHING DECK ROUGH SEAS
	6. MAINTENANCE PERSONNEL		14. FACILITIES-NAV AIDS, LANDING AIDS (IGA, GCA, ILS, MPN/R/T)		22. MATERIAL FAILURE/MALFUNCTION
	7. MAINTENANCE SUPERVISORY PERSONNEL		15. FACILITIES-CATAPULT, ARRESTING GEAR (Ship or field)	X	23. UNDETERMINED
	8. SUPERVISORY OTHER (Specify)		16. FACILITIES OTHER (Specify)		24. OTHER (Specify)

SECTION C. PERSONNEL DATA

1. NAME (Last, first, & middle initial)	2. RANK/RATE	3. NAVY SERVICE NO.	4. DESIG-NATOR	5. BRANCH OF SERVICE	6. AGE	7. YEARS CAT DEA	8. DRAFT	9. POSITION	10. FLIGHT CODE
PILOT (at controls at time of mishap) DeARMOND, R. C., Jr.	LTJG	(b) (6) [redacted]		USN	24	1/2	PILOT	Front Cockpit	A
CO-PILOT (identify & submit separate page 1)									

PILOT EXPERIENCE IN HOURS

ITEM			ITEM		
11. ALL MODELS		423.6	17. CV LANDINGS DAY/NIGHT	ALL	30 / 10
				IN MODEL	23 / 10
12. ALL MODELS IN LAST 12 MONTHS		283.9	18. FCLP LANDINGS LAST 6 MONTHS DAY/NIGHT	ALL	69 / 162
				IN MODEL	69 / 162
13. ALL MODELS IN LAST 3 MONTHS		78.9	19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED	ALL	5.3 / 0
				IN MODEL	5.3 / 0
14. ALL SERIES THIS MODEL	A/C	117.3	20. NIGHT HOURS LAST 3 MONTHS	ALL	30.2 /
	OPT/OPP	N/A		IN MODEL	30.2 /
15. ALL SERIES THIS MODEL LAST 12 MONTHS	A/C	117.3	21. TOTAL HOURS IN JETS (if jet mishap) HELOS (if helo mishap)		393.7
	OPT/OPP	N/A			
16. ALL SERIES THIS MODEL LAST 3 MONTHS	A/C	78.9	22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL	DATE	6 July 1966
	OPT/OPP	N/A		DURATION	1.8
23. DATE/GRADE LAST NATOPS STANDARDIZATION CHECK: Completed F4B Replacement VF-101, 15 JUN 66			24. TYPE INSTRUMENT CARD		STAN

OTHER PERSONNEL

25. NAME (Last, first, & middle initial)	26. Rate	27. Rank/Grade	28. Designator or Rating	29. Navy Service No.	30. Unit	31. Seat	32. Draft	33. Position
ATWOOD, J. E.		LT	USNR	(b) (6) [redacted]	VF-32	A	RIO	RC

OP 02F