EPA Region 5 Records Ctr.
247895

Belvidere IL to sample lagoon (9 hr) (PCS 2784)
1100, depart TAT office; 1700, arrive at TAT office.
0730 to ~~15~~ 16 1730, 10 hr worked Thomas P. Graan

6/20/90 Wednesday. In Chicago TAT office. Continued work on Ingram-Richardson SA. 0730 to 1630, 8 hours worked Thomas P. Graan

6/21/90 Thursday. In Chicago TAT office. Worked on writing + graphics for Ingram-Richardson SA (2746) 0730 to 1600, 8 hr worked

1600 Going on emergency response. Two unidentified drums in Wooddale. TATM Papp also present

1620 Pick up OSC Faryan at EPA headquarters.

1730 Arrive at site. Wood Dale police have site secured. Two drums are at the end of a dead end road (River Road). DuPage County Wood Dale Fire Dept, Bensenville FD, EMS personnel present. About 20 to 30 gallons of liquid are on the ground near the two drums. The drums are on their side. OSC

1800 ~~1800~~ Faryan and TAT approach drums in level B. The liquid is a reddish brown color. No readings above background with HNu, CGI, HCN monitor, + radiation meter. The bung is open on one of the drums (OSC Faryan labels it D1). OSC directs TAT to take a sample of the drum. The bung hole is oriented towards the top and the liquid is at the bottom edge of the bung hole. The liquid is oily and brownish. TAT uses a drum thief to collect one 16 oz sample.

1550 Maercorp arrives with ~~one RM and~~ TG two techs

1630 Maccorp brought two Chlor-n-oil kits (0-50ppm). Samples from the ground and drum D1 are both negative

1635 OSC Fayat directs Maccorp to overpack the two drums. Overpacking is begun.



1900 Maccorp crew is using hand pumps supplied by TAT to transfer the liquid in D1 to another drum. D1 is to heavy to move from its present location.

RAY ZUCK, 607 RIVER STREET, Wood Dale, IL resident, called 1430 # Wood Dale Fire Dept.

OSOWSKI, Edward, IEPA was present at scene. He was the person that supplied the ChlorNoil kits. ChlorNoil results are follows: sample from ground was negative; sample from drum D1 was inconclusive because sample emulsified.

Salt Creek is approx. 50-100 TO 1000 ft west of site

1925 Maccorp runs out of air. And doesn't have respirator cartridges. Wood Dale FD will refill

their bottles. Maccorp had no shovels, no spill pads, no caution tape.

1940 OSC Fagan directs Maccorp to end activities for the day. Cleanup will resume tomorrow at 0800. One TAT is required.
Drum D2 is in an overpack and just contains sludge.

2015 Fire dept returns with filled air bottles

2025 Maccorp crew resumes cleanup activities.

Maccorp Equipment Log Job # IL 550

2	Breathing air bottles
1	55 gal OPT
2	Scott 5 min pk
1	cascade
1	50 lb Oil dry
2	PVC 3X suit
2	PVC 4X suit
4	4X Tyveks
1	BO 15
1	BO 13
4	Airline breathing
4	Drum liners
2	85 gal OP
1	wrapper
1	crescent wrench

2045 Contents of D1 have been emptied into overpack. Crew member spilling KOH gone because his air line was punctured.

2115 MAecorp advised to have samples
from each of the two drum ran.
D1 → is to be ran for: 1) PCBs + Pesticides
(oily liquid) 2) Run incineration parameters
4) TCLP ← 3) Run fuel scan
D2 → which contains sludge is to be
run for: 1) PCBs + Pesticides
2) TCLP metal + organics
24-48 hr turn around time. STANDARD
Deliverable package.
Equipment MAecorp is to bring on
6/22/90 — 5 x 55 gallon open tops
— 2 overpacks
— 5 to 6 bags of spill dimpers
— HAZ. waste stickers
— drum cart with ramp
to load drums into truck.
D2 sample - Appears to be a fatty like texture,
mostly a thick sludge.
2135 Maecorp departs site. OSC & TAT depart site.
Drums remain on site, overpacked & covered with tarpaulin
2205 Drop OSC Foryan off at his home
2300 TATM Papp dropped off at his home
2330 TATM Grass arrives at home
0730 to 2330, 15.5 hr worked, T Thomas P. Grass

6/27/90 Friday. Driving to Wood Dale Drums. Weather: 11 M 60's,
moderate rain, light breeze.
0600 TAT Grass departs home.
0800 Arrive at site. Maecorp crew and OSC Foryan have not

	get arrived. The weather yesterday afternoon was mid 70's, partly cloudy, no breeze.
0815	OSC Fagan arrives on site
0818	Maecorp crew arrives on site. Truck with 3 crew members
0840	Fourth Maecorp crew member arrives
0841	OSC Fagan calls Maecorp to arrange Analytical. Wants 48 hr turnaround. Orders incineration parameters + TCLP metals on 2 samples.
0845	Crew members using absorbent pads to mop up oil that is now on top of a small puddle of rainwater. Crew working in level C
0945	Crew finished mopping up liquid on puddle. Now loading drums onto truck: One overpack with liquid from D-1; one empty drum (D4); one overpack with drum D2 (sludge); ~~two~~ 6 drums of PPE + pads.
0950	OSC Fagan says project ceiling is now $5000
1030	Drums have been loaded onto Maecorp truck and are now being transferred to Wood Dale Ely facilities for temporary storage.
temporary Storage location	City of Wood Dale North Facility 269 W. Larsen Park Wood Dale, IL 60191 708-766-5132 CRAIG WRIGHT SUPERVISOR
1100	Maecorp crew departs.
1115	OSC and TAT depart.
1200	Arrive at TAT office. Restock vehicle + return to parking garage
1300	Arrive back at TAT office