UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAX000121564
2. Manifest Document No.:
3. Generator's Name and Mailing Address: PETROLEUM TESTING SERVICE, 12051 RIVERA RD, SANTA FE SPRINGS CA 90670
4. Generator's Phone: (813) 698 0081
5. Transporter 1 Company Name: OMEGA RECOVERY SERVICES
6. US EPA ID Number: CAD042245001
7. Transporter 2 Company Name: NA
8. US EPA ID Number: NA
9. Designated Facility Name and Site Address: OMEGA, 12504 E. WHITTIER BLVD, WHITTIER CA 90602
10. US EPA ID Number: CAD042245001

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt./Vol.
a. ~~[illegible]~~ FLAMMABLE TOLUENE UN 1294 WASTE METHYLENE CHLORIDE UN 1593 FLAMMABLE LIQUID NOS UN 1294	6	DM	6x55	G
b. NA				
c. NA				
d. NA				

15. Special Handling Instructions and Additional Information: GLOVES

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name	Signature	Date Month Day Year
JOANN L BARKER	[signature]	2 19 86

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month Day Year
ISAAC Woods Jr	Isaac Woods Jr	2 19 86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name	Signature	Date Month Day Year
STEVEN SIMPSON	[signature]	02 19 86

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)