Mary Kautz

- LUSTs @ Boeing Field.
- Prior releases.

Probably listed separately.

Flume abandonment - Slip 4.

- Sediments below the flume
- Wood in flume.

- PCB contamination ~~of~~ by oil?
  ↓
  cement potential
  mix concrete w/ gravel @ several locations?

SCL 04065

CTY0049071

SEA289550