rec'd 8/8/83

P&WA
East Hartford Consolidated

D.E.P. Map Comments

RCRA RECORDS CENTER
FACILITY Pratt & Whitney Main St
I.D. NO. CTD990672081
FILE L.C. R-1B
OTHER RDMS #2743

DROP

X Permitting of solvent reclaim area?
X How does state treat P&WA on exclusion for elementary neutralization and waste water treatment? P&WA is a non-commercial off-site facility. (Consistency e.g. EWR & CTC)

keep all 8 tanks

Part A

X Indicate provisions to separate hazardous waste for easy access and incident mitigation
✓ Enclose letter stating that S/I on original Part A is not a regulated unit (Document) — Include

Facility Description

✓ The barrel/transporter pad near CWIP is not indicate on topo map. — Include

Inspection procedures

✓ Identify type of specific problem to look for: waste feet cutoffs — complete inspection checklist for incinerat
✓ Inspection of emergency equipment?

review their inspection of emer. equip.

5.

Containment Systems
X Impervious base and containment for containers, and still in solvent reclaim area.

Tanks
✓ Indicate tank ages, liquid level indicators ~ add

Incinerator
✓ Hazardous waste determination on incinerator ash, Hv metals, disposition ~ is it HW?, were does it go.. add

Personnel training
✓ Identification of high hazard areas ~ add.

Closure Plan
- Reference that three storage areas are combined into types: containers and tanks. - addressed
- Disposition of rinsed tank; container? ~ add
- Incinerator ash ~ disposition