See Gabor Szabo 9/29/86

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAN 0010 051551910 | Manifest Document No. | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Sigmacast Corp.
1925 S. Charlie Industry, Calif.

4. Generator's Phone (818) 965-2457

A. State Manifest Document Number: 85534672

B. State Generator's ID: CAX000055590

5. Transporter 1 Company Name: Omega Recvoery Services | 6. US EPA ID Number: CAD 04 - 245001

C. State Transporter's ID: 701737

D. Transporter's Phone: 213/698 0991

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: CAD 042245901

G. State Facility's ID

H. Facility's Phone: 213/698-0991

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. Waste Flammable Liquid NOS UN 1993 Flammable Liquid (RINSE)	014	DM	700	G	211
b. Waste Flammable Liquid NOS UN 1993 Flammable Liquid (ETCH)	005	DM	250	G	211
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.
Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002 b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: MARK GARCIA | Signature: Mark Garcia | Month Day Year: 1/01/86

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr. | Signature: Isaac Woods Jr. | Month Day Year: 1/01/86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month Day Year

19. Discrepancy Indication Space
CAX II

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19

Printed/Typed Name: FRANK FORD | Signature: Frank Ford | Month Day Year: 1/01/92 86

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000 Sacramento CA 95812

04/27/2000 "ORIGINAL MANIFEST COPY"

Shipper 17309

04/27/87

State of California--Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CIALX 001 001 5 55 90 — Manifest Document No.

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Sigma Cast Corp.
1925 S. Charley, Industry, CA 91748

4. Generator's Phone (818) 965-2457

A. State Manifest Document Number: 86544265

B. State Generator's ID: CAX000055590

5. Transporter 1 Company Name: Omega Recovery Services

6. US EPA ID Number: C AD 04 2 245 0 01

C. State Transporter's ID: 802785

D. Transporter's Phone: 213/698-0991

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10. US EPA ID Number: C A D04 2 245 001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Flammable Liquid NOS Flammable (Rinse) Liquid UN 1993	005	DM	1240	G	
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: MARK GARCIA — Signature: Mark Garcia — Month Day Year: 04/28/87

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ISAAC Woods Jr — Signature: Isaac Woods Jr — Month Day Year: 04/28/87

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name: FRANK FORD — Signature: Frank Ford — Month Day Year: 04/28/87

GENERATOR — TRANSPORTER — FACILITY

86544265

DHS 8022 A (11/85)
(EPA 8700—22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To P O Box 3000, Sacramento CA 95812

05/31/2001 "ORIGINAL MANIFEST COPY"

Revised Manifest Summary Report

SIGMA CASTING CORPORATION
SIGMA CASTING CORPORATION

Manifest Date	Bates#	Manifest#	Quantity	Units	Gallons	Code	# Trips	Assessed (gl) Volume	
		86534672		7923	LBS		CMP		
12/05/1984		83004207		3669.6	LBS		CMP		
12/19/1984		83004210		3336	LBS		CMP		
02/12/1985		84426272		22935	LBS		CMP		
07/03/1985		84426278		24769.8	LBS		CMP		
10/15/1985		84426284		16971.9	LBS		CMP		
02/25/1986		84720077		17430.6	LBS		CMP		
06/04/1986		86534434		12510	LBS		CMP		
09/02/1986		86534578		12927	LBS		CMP		
02/12/1987		86544110		6255	LBS		CMP		
04/28/1987		86544265		2293.5	LBS		CMP		
06/03/1987		87114049		3336	LBS		CMP		

Total Records: 12 Default Volume: 0 Total Waste Volume: 67.1787