7-29-82
~~WA 4718~~
ID 0961
NO DATE
1b

Arrcom Corp. - Drexler alias
Warren Bingham - owner
Pt A submitted by ~~Allen~~ W. Alan Pickett - Bingham didn't know
Wally Drexler
Pickett signed as owner/operator
& said Drexler Enterprises owned it
have ISS - but inactive
Bissell
since 60's
waste oil - dust control
solvents non-halogenated - ignitable
Bingham not letting Drexler on-site
oil on ground, oil ponding
→ Athena - PCB sample - polyethylene gloves melting
Mike - sump sample
→ samples being expedited
over soul source aquifer
house ~ 50 yds - horse pasture in between
no records on-site - FBI has
Rathdrum ~2 miles N of Coeur d'Alene
big tank leaking
bad taste in mouth
Bingham - "ignorant, duped, lots of expenses - no lease $ - trying to re-lease

USEPA RCRA
3009254

use caution in dealing / Bingham - "doesn't seem to be all there" - medications?
trying to get records from FBI
US Atty / Moore
trying to get manifests from Jim Malm
Jim Malm wants to be involved - 3 other sites in Wa + waste crossing his line
esp sampling
Ken Babin - Idaho Dept of Hlth - C'd A
Montana OO - EPA involved - waste from Montana to Drefler
Environsafe involved - seem to have good handle on it
EST
Mike Ving
Feigner talking to Findley
warning letter will probably be written - but who to?

67,000 gal tank
10 yd^3 wastepile

1,250,000 gal/yr (D001) ignitably
20,000 gal/yr F003 spent non-halogenated solvents
5,000 gal/yr F005 "
5 yd^3/yr F005 "
* residue (sand, metals, sludge, paint) filter from all products