WA2917
4/14/86
4e

WEEKLY TANK INSPECTION REPORT

The following tanks were inspected for corrosion, leaking valves, seams or manholes.

FILE COPY

TANK #	OK	NEEDS REPAIR	TANK #	OK	NEEDS REPAIR
90	✓		105	✓	
91	—		106	✓	
92	—		107	✓	
93	—		108	✓	
94	✓		109	✓	
95	—		110	✓	
96	✓		111	✓	
97	✓		112	✓	
98	✓		113	—	
99	✓		114	✓	
100	✓		115	—	PINHOLE LEAK BELOW MANWAY
101	—		116	✓	
102	—		117	✓	
103	—		118	O/S	
104	—		165	✓	

Small tank yard berms OK ✓ NEEDS REPAIR

DIESEL YARD berms OK ✓ NEEDS REPAIR

Big yard berms OK ✓ NEEDS REPAIR

ADDITIONAL COMMENTS FOAM PUMPS RAN 1/2 HR. TK 115 BEING REPAIRED - PINHOLE LEAK APPEARED 4-11-86 ON SECOND SHIFT - TK EMPTIED & READY FOR REPAIRS

Reported for the week of April 14 1986

Signed Bob Moody

USEPA RCRA
3012704