WA 2917
4/26/86
4c

DAILY LOG BOOK

DATE 4 26 86

OPERATOR CKP

TIME: ~~0700~~ 0930

1030	99 to	102 MAX gpm metro OK BS&W on 99# 4%
	grav is	26.5... gage 26-9 1/8 =
1045	Can not	strip 105 or 107 to 110 using roper for oil sale
	going	to sale oil till End of shift
1100	pumping	pit to 97 Red # metro Rooks good
1118	Sampled	112# for treatment also dropping H2O from 105 + 110#
1200	98 to	metro at 14-6 1/2 99 At 25-3 1/8 moved 1-6" 9
1345	Gage on	99# 20-11" Even 1203 Barrels sold so far 98 at 13-4 1/2
1345	metro	looks good pumping pit to 97 with 2" diapharm pump
1345	still	dropping H2O from 105# + 110 water draw w/ pump 2
1410	metro	ok oil sale ok pit still pumping good H2O
1450	Secured	Oil sale to PNO also secured 105 + 100 water d
1455	gaged	99# at 19-1 1/2 metro Rooks good
1520	Secured	air Compressor plus 98 to metro pumping pit
	with	roper / going to complete paper work on oil sale
1530	pit	all the way down all Valves secure
	no	spill or Contamination gone home CKP
		4-28-86
0800	LINE	UPS & Gauges Dropping 98 to metro
0830	HARBOR	oil in with Coolant to #112

FILE COPY

USEPA RCRA
3012706

DAILY LOG BOOK

DATE 4-28-86

OPERATOR MR CL CKP

TIME:

0800	Gauges	& Line-ups Red 97, white 98, Blue 96
	Ind 99	- Dropping 98 to metro & Pumping MDO Yar
0830	Harbor	oil in with coolant to #112
0930	Sampled	Tank 105# Top 16" + 107 Top 16" Spinning Samples ex
0935	105#	0.4% Top 16" 107# 20% all Solids To 16"
0935	Started	Stirring pipe alleys To pit + dropping 107 H2O To pi
0940	going To	Take Top 32" of 105# 3 Spin 105# 32" 1.2%
0951	Ran off	copies for log book & got more acid
	for OPS	office
1000	R+R in	with H2O To pit + 97
1010	Getting	sample of 112 for treatment
	+ securing	overshot to 112 & checking 107, 110, 105 for
	water to drop	
1020	Secured	H2O from 105 - too dirty
1030	105#	48" well over 50%
1035	AAA	in with w/oil to #99
	Put air	To #112 to mix tank before getting sample
	+ Dropping	H2O from 110 to pit + pumping pipe alley to pi
1045	Pipe	alley aready pumped + secured
	Securing	air to 112 + getting samples
1100	AiRo	in with w/H2O pit #97
1120	Doing	tests on #112 for treatment
1140	Dropping	96 for 2 quart samples
1200	Metro	O.K.
1210	Gasbed	97 @ 23'10 5/8
1230	Turbine	w/oil in with w/oil to 99

DATE 4-28-86 DAILY LOG BOOK

OPERATOR

TIME:

1245 Purging 105 → 110 for BS&W Check

1320 Secured 105 to 110 + started transfering 105 to 99 + set flow up on #98 to metro

1330 getting sample of #105 to #99 for BS+W

1345 BS+W on 105 to 99 at 1.48

Cleaning on ops office

1400 metro at max 6pm

1410 Getting samples of #165 oil

1420 Cleaning on front AREA

1445 Secured 98 to metro went dirty + clearing seperators to pit

1500 Merit in with w/oil to #99 BS+W 0.88

1520 UDO in with w/oil to 99

1530 AIRO in with w/oil to #99

1600 R+R spotted tanker trailer out back with sludge for decanter(?)

1605 U.D.O. in with w/oil to #99

started MDO yard pump

1640 Straightened out pit sep top + hoses. Cleaned roper filters. Secured pit to #97. SETTING UP TO TREAT #112

1710 (1) R+R in with oil, waste water to pit to #97

1730 Sampling 105 for water drop.

1745 (2) AIRO w/oil to #105 BS+W 70% .6% solids

1815 (3) GTS in with w/water to pit to 97 (4) Merit oil to #99 @ 8% BS+W

1840 (5) Merit w/oil to #114 @ 18% BS+W

1915 (6) G.O. Petroleum in with w/oil to #99 @ 1%

DATE 4-28 DAILY LOG BOOK

OPERATOR

TIME:

2030 Secured 6" on #110 water turned to oil still dropping out of water draw. Setting up to dro water out of #105 thru 6" Setting steam on rec tank and checking #165 for free water

2200 Secured dropping water of #105 thru 6". Set steam on #165. Only one diaphram pump works Had to set up fittings for circulation and suction. Borrowed a red 2" hose off of "star wars" to suse for caust into drums. Tom mixing 839. Had to scrounge around for open head drums. We need more

2235 GTS in with w/water to pit to #97 Gaged #110 from #107 at 8-11¼ Secured MDO yd pump

2340 #107 has been going to #105 for a while now. Added 839 to #112 Blowing with air and circulating there is two drums of caustic set out by centrifuge area the drums are labeled caustic 50% for #112 treatment.

0020 Plant secured.

4-29-86

0800 Gauges + Line-ups 96 Blue, 97 Red, 98 white, 99 ind

0905 Getting sample of #117 to test.

0920 Set up to sell oil from #99 to PNOCO

Pumping pit to #97 + dropping 117 to pit

0925 165# Took Sample Composite of 165# + Sampled Rec Tank

0930 Set up discharge hose over top of 112# for treatment

0945 Transfer of #117 on hold - oil sale ready to go

DATE 4-29-86

DAILY LOG BOOK

OPERATOR

TIME:

0945	UDO in with waste oil to #114
0950	checking metro sep for next drop put steam on #165 -
1000	purging metro sep for next discharge & checking SW Pump station for oil
1020	SW Pump station O.K. ready for metro drop
1020	put Bag of Cal Clouds into rec tank Blowing for 15 min
1030	RR in with coolant to #117 - emptied waste oil can
1035	Getting "star wars" sample
1040	GTS in with waste Coolent ~~00~~ 9 to 117# cap
1105	Setting up to get 20 gals of 7877 for 165 treatment cap
1115	Setting up to pump oil off top of star wars tanker to #110
1135	U.D.O in with w/H2O to pit & 97
1150	star wars tanker on hold until we get a pump & some hose free to use
1200	Airo in with w/H2O to Pit & 98
1215	Secured #97 red secured 98 white opened #98 red pumping pit to 98
1225	CTC in with ~~[illegible]~~ w/oil to #105
1235	added 32 gals [illegible] to 112# cap
1240	Gauged #99 at 19'3"
1250	STIPPING #115 to #105
1300	CROSBY & Overton in with w/coolant to #117

DATE 4-29-86

DAILY LOG BOOK

OPERATOR GR

TIME:

1320 Airo in with w/oil to #99 BS+W 7%

1320 Secured ~~105 to~~ 115 to 105 + started stripping #107 to #105

1340 V D O in with w/coolant to #117

1350 Frank's in with w/water to pit + 98

1425 Resource Recovery in with coolant to #117

1505 added 20 gals of 7778 to 165# Blowing air for 30 min

1525 D J's in with oil to #99 BS+W 2.6%

1545 MVS in with w/oil to #99 BS+W 8%

cleaning on front area

1550 Frank's in with w/oil to #99 BS+W 1.2%

1610 V D O in with w/oil to 99 BS+W 7%

Swing

1630 Going to page #96 for Metro drop

1635 Merit in with w/oil to #99 @ 3% BS&W

1700 6 bags alum + 2 bags calcium chloride added to #112 + circulating. Metro Started @ 25-4 3/8

1730 Profiling #165 ② R+R in with Boron to pit

1800 Sampling #112. No free water in #165 ③ C.C.S in with w/water to pit to #98

1830 Spinning bottom sample from #165 BS+W @ 95% - 5% Solids

1900 Metro OK Dropping water out of #110

#112

1900 ph for #112 @ 9.5. There isn't enuf alum to lower ph + CONTINUE TREATMENT.

DAILY LOG BOOK

DATE 4-29

OPERATOR HG-Jt

TIME:

1925	Going to see if we can drop water thru 6" on #110
	cleaning up around Rectank
2000	Dropping free water thru 6" & water draw on #110
	Metro flow max GPM and looks good - no odor.
2040	Tried water draw on #105. No free water. #110 still
	dropping thru 6" & water draw. #96 @ 23-0 3/8 #98 @ 12-1 1/4
2110	@CTC in with w/water to pit to #98
2150	@CLDO w/oil to #99 BS&W 5% Metro OK
2205	@GTS w/water to pit #98
2315	Topped off #105 from #107. Secured water from
	#110 turned only Now pumping #107 to #110 Secured
	circulation on #112 Secured air compressor cleaned
	roper filters Metro at max GPM looks good.
	Cleaned bleeder on West water pump so pump could
	be used to pump pit.
2350	Secured #107 to #110. The roper filter clogs up as
	fast as you turn it on. Blew condensate
	of #110 steam trap doesn't seem to work well.
0015	Securing plant and Metro.
	4-30-86 +
0800	Gauges & Line ups
0820	Working on Discharge SIDE of Y SEP LINE from
	Metro SEP
0825	pumping pit to 97 & pumping alleys to pit
0915	97 green, 98 Red, 96 white, 99 ind.
	Frank's in with w/oil to #99

DATE 4-20-86 DAILY LOG BOOK

OPERATOR JR CL CKP

TIME:

0920	working on star wars trailer
0930	Airo in with w/H2O to Pit #98
0935	cleaned pick-up Screen on pit pump + pumping pit to 98 - started #96 to metro
1000	UDO in with w/oil to 99
1005	added Six Bags of alum to 112# circulated & Blowing CKP for 1 hr
1015	Finish Repair on Metro & cleared steam trap on 110 (Keep an Eye on it Please)
1045	R&R in with w/H2O & Phenol to 116
1100	UDO in with w/H2O Pit # 98
1130	added 4 more ~~bags~~ Bags of alum into 112# CKP Circ + Blowing
1130	filled wash pump with gas + Oil CKP
1215	APA in with w/oil to #99
1230	star wars is lineup to decantor
1300	C+O in with coolant to #116
1315	ASF in with H2O to pit #98
	Merit in with w/oil to 99
	Airo in with
	Amalgamated in with
	Amalgamated in with
1400	Removed manway from #107
1430	added two more Bags of alum to 112# + added 20 gals of 339 to 112# on Circ + Blowing air
1500	J J William's in with w/oil to #99
1520	Resource Recovery in with skydroll to Pit #98