OhioEPA
State of Ohio Environmental Protection Agency
Central District Office

Street Address:
2305 Westbrooke Drive, Building C
Columbus, Ohio 43228
614-771-7505 **FAX** 614-771-7571

Mailing Address:
P.O. Box 2198
Columbus, Ohio 43266-2198

George V. Voinovich
Governor
Donald R. Schregardus
Director

EPA Region 5 Records Ctr.
330326

February 3, 1992

RE: COLUMBUS SCRAP CORP.
FRANKLIN COUNTY, OHIO
OHD131884348
PRELIMINARY ASSESSMENT

RECEIVED
FEB 7 . 1992
SITE ASSESSMENT SECTION

Ms. Jeanne Griffin
Pre-Remedial unit
U.S. EPA, Region V
HSM-5J
77 West Jackson Boulevard
Chicago, Illinois 60604

Dear Ms. Griffin:

Enclosed please find the Preliminary Assessment for Columbus Scrap Corp. in Columbus, Ohio. This report presents the site narrative and the PA score sheets.

Please feel free to contact me at (614) 771-7505 if you have any questions.

Sincerely,

Jeffrey W. Reynolds
Emergency & Remedial Response
Central District Office

what Qual? H
50.05

JWR/sc

Enclosures

cc: Laura Fay, DERR, CO
CDO File

DERR/9

Printed on recycled paper

Gold p.v
1/30/92

PRELIMINARY ASSESSMENT
COLUMBUS SCRAP CORPORATION
FRANKLIN COUNTY, OHIO
USEPA ID# OHD131884348

JANUARY 30, 1992

OHIO ENVIRONMENTAL PROTECTION AGENCY
DIVISION OF EMERGENCY AND REMEDIAL RESPONSE

Prepared By:
Jeffrey W. Reynolds
Site Coordinator

Reviewed By:
Deborah Strayton
Unit Supervisor

Date: January 30, 1992

Site: Columbus Scrap Corporation
580 Furnace Street
Franklin County, Ohio

EPA ID No.: OHD131884348

1. INTRODUCTION

Under authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA), the U.S. Environmental Protection Agency (EPA), Waste Management Division, Region V conducted a preliminary assessment at the Columbus Scrap Corporation site in Franklin County, Ohio. The purpose of this investigation was to collect information concerning conditions at Columbus Scrap sufficient to assess the threat posed to human health and the environment and to determine the need for additional CERCLA/SCIRRHI or other appropriate action. The scope of the investigation included review of available file information, a comprehensive target survey, and an onsite reconnaissance survey (December 6, 1991).

2. SITE DESCRIPTION, OPERATIONAL HISTORY, AND WASTE CHARACTERISTICS

2.1 Location

Columbus Scrap Corporation is located at 580 Furnace Street in the southwest area of downtown Columbus. The geographic coordinates are 39° 56' 51" N latitude and 83° 00' 17" W longitude (Refs. 1 & 2). To reach the site, travel south of downtown Columbus on High Street approximately 1.6 miles (2.6 km) and turn right on Whittier Street. Follow Whittier approximately 1.5 miles (2.4 km) and turn right on Furnace Street. Then follow the signs to the Columbus Scrap site (Refs. 1 & 3).

Columbus has a continental climate characterized by moderate extremes of temperature and precipitation. The annual temperature averages 51.6° F (11° C) and annual precipitation averages 36.97 inches (94 cm) (Ref. 4 - pg. 659).

The summers are warm and humid. July is the hottest month with an average daily maximum temperature of 84.4° F (29° C). The highest temperature ever recorded in Columbus was 102° F (39° C) during June 1944 (Ref. 4 - pg. 659).

The winters are cold with an average of five days with subzero

temperatures per year. January is the coldest month with an average daily minimum temperature of 19.4° (-7° C). The lowest temperature ever recorded in Columbus was -19° F (-28° C) during January 1985 (Ref. 4 - pg. 659).

The property is mostly surrounded by the Scioto River, which curves around in a semicircle to the west and then heads south (Ref. 1). The property is in a mixed commercial and industrial area. Residential neighborhoods are within a four mile radius in all directions but are closest to the northwest and the east (Refs. 1 & 3).

2.2 Site Description

Columbus Scrap leases 6.2 acres of an 11 plus acre property from CSX Transportation. Contamination (with PCBs) is mostly confined to the Columbus Scrap portion of the property and covers most of that portion (Refs. 3, 5, 6, & 7). The site is relatively flat and located in an urban area. The Columbus Scrap facility is triangular in shape with the two longest sides "pointing" to the southeast (Refs. 3, & 6).

The site is largely covered with piles of scrap metal of varying sizes and contents. Operations at the site include segregating metals, shearing into pieces, and baling them for sale and shipment off site to steel mills and smelters. The metals are separated into ferrous and non-ferrous (copper, brass, aluminum, stainless steel) categories. The shearer is in a building on the northwest corner of the facility near the entrance. The baler is located in a small building in the center of the site. There is a truck weighing scale at the north edge of the site next to the office (Refs. 3 & 6).

Columbus Scrap is surrounded by a variety of industrial/commercial properties. They include two warehouses located to the north and west of Columbus Scrap (the road to the facility passes between these buildings), a concrete company to the southwest, several sets of railroad tracks to the east/northeast, and the city of Columbus Impound Lot and Recreation Department Buildings to the south (Refs. 1, 3, & 8).

The site is approximately in the center of a piece of land located on an inside curve of the Scioto River. A strip of city park land (containing a bike path) follows the inside curve of the river and then continues south on the west side of the river. The river is approximately 1300 feet from the site at its closest point. The center of downtown Columbus is approximately one mile to the northeast (Refs. 1 & 9).

The site is currently not fenced in. There is some fencing to the north and west but there is access to the facility from the southwest, south, and east. Access is particularly open to the east

in the area of the railroad tracks. A representative of Columbus Scrap indicated, "there is also security on site at all hours when the facility is not operating (Refs. 3 & 10)".

Clear drainage patterns were not observed on the site visit or evident on topographic maps. Gary Reynolds, Columbus Scrap Vice-President, indicated that he thought the site was in a low area and storm water did not drain away from the site (Refs. 3 & 11). City storm sewers are located around the area of the site but do not appear to extend onto the site (Ref. 12). The site is located within the 500 year floodplain of the Scioto River which eventually drains to the Ohio River (Refs. 1 & 13).

2.3 Operational History and Waste Characteristics

Columbus Scrap Corporation operates a commercial scrap yard at 580 Furnace Street, southwest of downtown Columbus. They have leased the approximately six acre property from CSX Transportation since 1985 when they purchased the Summer Company. Previous to July 1985 Summer Company also operated this facility as a scrap yard. The Handler Compressed Steel Corporation used the site as a scrap yard from 1951 to 1981. Prior to that, CSX and its predecessors used the site for railroad operations (Refs. 5, 6, 11, 14, & 15).

Columbus Scrap is owned fifty percent by Cohen Brothers in Middletown, Ohio and fifty percent by Muskingum Iron and Metal in Zanesville, Ohio (Ref. 14).

On-site sampling was done May 25, 1989 and February 23, 1990 as part of federal PCB inspections performed by Ohio EPA Division of Emergency and Remedial Response personnel, who are authorized Toxic Substances Control Act (TSCA) representatives. The 1989 sampling found up to 1,000 ppm PCBs in soil surrounding eight leaking capacitors. The 1990 sampling found PCBs in soils at levels up to 8,700 ppm (Refs. 16 & 17).

These inspections were performed following an incident in which Columbus Scrap provided a roll-off box for an individual who put three PCB transformers in the box (Refs. 3, 16, & 17). The capacitors were removed, along with approximately 40 cubic yards of soil, from three different pits by Chem Waste Management under contract with Columbus Scrap (Refs. 3, 6, & 11).

PCB violations cited as a result of these TSCA inspections resulted in a Consent Agreement And Final Order with the USEPA dated January 8, 1991. Under this Consent Agreement Columbus Scrap was fined $8,000 (Refs. 16, 17, & 18).

Extensive additional sampling has been done under the terms of an Administrative Order by Consent (AOC) signed on April 10, 1991 with USEPA Region V, Emergency Response. This order requires Columbus Scrap Corporation and CSX Transportation to investigate the extent

of contamination and remediate the site. The cleanup level is expected to be 25 ppm of PCBs. This level was established with the assumption that the site will be fenced, totally limiting access (Refs. 7, 15, 19, & 20).

Phase I of the above investigation has been completed. Under this portion of the investigation the USEPA OSC, Steve Renninger (Westlake Office), first divided the site into fifty sectors. Kemron Environmental Services (Marietta, Ohio) then sampled the sectors for Columbus Scrap and CSX. Samples were composited within each sector, each sample containing five portions. Ecology and Environment personnel, as USEPA's Technical Assistance Team, split samples at some locations (Refs. 6 & 7).

Samples were all tested for PCBs and some were tested for total metals (no metals problems were found). Phase I of the investigation determined approximately five acres of the site are contaminated (with PCBs) at levels above 5 ppm. This level may convert to 25 ppm 'hot spots' when one aliquot (out of five) of a sample contributes 100% of a sample's PCB content (Refs. 6, 7, & 9).

Phase II work will include sampling of the five acres of the site (mostly on the Columbus Scrap portion of the property but some is on other CSX property, to the west and southwest of Columbus Scrap) potentially above cleanup levels- including sampling at depth. Original depth sampling will be at 12 inches and 24 inches. If "hits" at these depths are found then samples will be taken at 36 inches and 48 inches. Additional sampling completed in August 1991 did not find contamination outside CSX property (Refs. 7 & 19). The final report, including sample results, is not available yet.

3. GROUND WATER PATHWAY

3.1 Hydrogeologic Setting

Excluding the urban fill common in the area, the site is likely covered with alluvium overlying the Devonian bedrock. This alluvium could be expected to be poorly sorted, poorly bedded silt and sand, generally less than 25 feet thick. Individual layers are thin, lenticular, and nearly horizontal. This includes all detrital material deposited in valleys or undrained depressions since the last glacier (Refs. 21, 22, 23, & 24).

To the west of the site groundwater may be obtained from Devonian and Silurian limestone at yields up to 175 gpm. To the east and north of the site less groundwater is available via lenses of sand and gravel interbedded in clayey till overlying shale bedrock. To the south, extensive sand and gravel deposits may yield up to 500 or 1,000 gpm (Ref. 22).

3.2 Ground Water Targets

The majority of the population within a four mile radius of the site relies on municipal water supplies taken from a wellfield south of the city (outside the four mile radius), the Scioto River (upstream of the site), and the Hoover Reservoir on Big Walnut Creek (Ref. 25). Residents not connected to municipal water have been identified through the use of Ohio Department of Natural Resources (ODNR) well log maps (Ref. 26).

There are approximately 281 homes within four miles which are thought to use private wells for drinking water (Ref. 26). The average number of persons per household in Franklin County is 2.47 (Ref. 28). This equates to 696 residents (when rounded up by distance ring, according to HRS guidance). The nearest known residence relying on a private drinking well is approximately 9700 feet to the southwest (Refs. 1 & 26).

The nearest residences are located in a neighborhood southwest of the site. Depths of the five closest wells range from 27 to 64 feet deep with static water levels mostly less than 10 feet. These wells are set in a limestone layer that starts 11 to 20 feet below the ground surface (well logs attached w/ Ref. 26).

3.3 Ground Water Conclusions

Given Columbus Scrap's location, groundwater is probably very shallow under the site. The contaminated soil has made a release to groundwater likely. Although the suspected release of PCBs is not thought to endanger the local use of ground water. PCBs are not considered to be very mobile in soils and the nearest residential use of ground water is some distance from the site (Refs. 1, 26, & 27).

4. SURFACE WATER PATHWAY

4.1 Hydrologic Setting

The Scioto River surrounds the site to the north, the west and the south. Surface drainage from the site to the river is not known and was not determined during the site visit (Refs. 1 & 3). Gary Reynolds, Columbus Scrap Vice-President, indicated that storm water did not drain off of the site because it is in a low area (Ref. 11).

A map of Columbus storm sewers in the area shows two lines in the area leading west to the Scioto River and several lines heading south along the railroad tracks. However these lines do not appear to extend beneath the Columbus Scrap property (Ref. 12).

Because of the uncertainty about site drainage, the possible point

of entry to the Scioto River is also unknown. The river passes, at its closest point, within about 1300 feet of the site (at approximately river mile 130) to the south by southwest (Ref. 1). Scioto River flow rate for 1989 averaged 1,518 cubic feet per second (Ref. 29).

4.2 Surface Water Targets

There are no drinking water intakes located within 15 downstream miles of the site. Most local residents are served by the city of Columbus municipal water system as mentioned in section 3.2 above. Those not on municipal water are served by private wells (Refs. 25 & 26).

The Scioto River is used for recreational fishing all along its length including downtown (Ref. 30). Fish tissue sample results show levels of PCBs in fish just downstream (RM 129, at Greenlawn Avenue dam) of the site at levels up to 899 ppb (Ref. 31). Levels north of Columbus at RM 140 are considerably lower (10 ug/Kg). Other PCB sources along this stretch of the Scioto are unknown, but given the lack of PCB contamination in samples taken off CSX property and the lack of a known surface water drainage route, it is difficult to assume an observed release from this information (Refs. 1, 7, 12, 31, & 33). The site investigation should attempt to determine a surface water route (if there is one) between the site and the river and if there is sediment contamination attributable to the site in the river (which may have led to the PCB contaminated fish).

No wetlands have been identified within one half mile of the site or along the Scioto River within 15 miles downstream. The US Fish and Wildlife wetlands inventory maps have not been completed for this area of the state so there may be wetlands present but not identified. Soil maps of Franklin and Pickaway indicate areas along the Scioto (> 1/2 mile downstream) that could potentially have hydric soil components (Refs. 23 & 24).

Other uses of this section of the Scioto include agricultural, industrial, and recreational (Ref. 32).

4.3 Surface Water Conclusions

A Columbus Scrap employee has indicated stormwater does not drain away from the site. The site visit and a Columbus Storm sewers map also showed no obvious drainage pathway from the site to the river (Refs. 3, 11, & 12). Fish tissue analysis of Scioto River species has shown PCB contamination of individuals sampled one mile downstream at levels up to 899 ug/Kg. The nearest potential background sample is about 10 miles upstream (fish samples at that location contained 10 ug/Kg PCBs). Other potential sources of PCB contamination along this stretch of the Scioto are unknown (Refs. 32 & 33).

5. SOIL EXPOSURE AND AIR PATHWAYS

5.1 Physical Conditions

The site is currently covered by many large piles of scrap metal (Ref. 3). To make sampling possible in some quadrants, Columbus Scrap is moving piles of scrap so Kemron can get access to sample (Refs. 15 & 16). The perimeter of the site is currently unfenced except for a couple areas to the north and west (Ref. 3). As part of the ongoing investigation/ remediation they plan to fence the entire site. This will allow them to claim limited access to the site and use a 25 ppm cleanup level for the PCBs instead of 10 ppm (Refs. 3 & 16). Columbus Scrap personnel have indicated there is security on site at all hours when the facility is not operating (Ref. 10).

5.2 Soil and Air Targets

There are approximately 30 employees at Columbus Scrap. Fences separate the facility from the Lazarus warehouses to the north and west (Refs. 3 & 11). There are approximately 410 other people employed within one-fourth mile of the site (Ref. 35). The total population of residents within a four mile radius is estimated as 89,129 (Refs. 26 & 30). The nearest house is approximately one quarter mile to the east (Refs. 1 & 3). Estimates of workers (large numbers of targets downtown especially, about 95,000) and students (Ohio State University has over 50,000 students and is within four miles, Columbus State has about 16,000 and is within two miles) add approximately 300,000 more targets (Refs. 1 & 35).

5.3 Soil Exposure and Air Pathway Conclusions

Given current conditions of open site access and several acres of surface soil contamination, soil exposure may be of some threat to employees of Columbus Scrap or someone who may wander onto the site (Ref. 3 & 19). A release to air is possible (due to blowing dust over the basically unvegetated site) despite the relatively low volatility of PCBs (Ref. 27).

6. SUMMARY AND CONCLUSIONS

PCB contamination was discovered at Columbus Scrap Corporation during a 1989 TSCA inspection by Ohio EPA DERR personnel (Ref. 13). The sources of PCBs discovered during this inspection have since been removed but the subsequent investigation has documented remaining soil contamination (Refs. 6, 17, & 18). The soil is contaminated over virtually all six acres of the site and five acres of that has been determined to be potentially above 25 ppm and in need of remediation (Refs. 7 & 19). This investigation and forthcoming remediation are being done under an Administrative

Order on Consent between Columbus Scrap and the owner of the property, CSX Transportation, and USEPA Region V Emergency Response (Ref. 20).

The site is located near to the Scioto River and in a fairly low area so the soil contamination makes for a suspected release to groundwater. However due to the relative lack of mobility of PCBs and the distance to the nearest known residential well (almost two miles) groundwater contamination is unlikely to affect current drinking water sources (Refs. 1, 13, 26, & 27).

Surface water may have a potential for contamination due to the proximity of the Scioto River (within 1300 feet) and the presence of the site within the 500 year floodplain (Refs. 1 & 13). So far, however, a surface water connection between the contaminated area and the river has not been found (Refs. 1, 3 & 11). Also sampling under the AOC around the perimeter of the facility property has not shown contamination (Ref. 7). The site investigation should attempt to determine if this surface water route exists and if it has contributed to PCB contamination in the Scioto (by sampling sediments).

Soil contamination has potential for exposure due to the openness of the site. A release to the air is possible due to the nearly site wide surface soil contamination and the lack of vegetation to keep the dust down. This is despite the relatively non-volatile characteristics of PCBs (Refs. 3 & 27).

REFERENCES

1. U.S. Geological Survey, 7.5 minute topographic quadrangle maps of Ohio: Southwest Columbus, 1965, photorevised 1982; Southeast Columbus, 1964, photorevised 1985; Northwest Columbus, 1965, photorevised 1982; Northeast Columbus, 1964, photorevised 1982.

2. U.S. Environmental Protection Agency, "Standard Operating Procedure to Determine Site Latitude and Longitude Coordinates," 1991. Calculation worksheet for Columbus Scrap.

3. Jeffrey W. Reynolds, Ohio EPA, DERR/CDO, Field Report for Preliminary Assessment Site Visit, December 6, 1991 (with 23 photographs and site map).

4. Gale Research Company, The Weather Almanac. 1987. Gale Research Company, Book Tower, Detroit Michigan. 811 pp.

5. Gary Reynolds, Columbus Scrap Vice-President, telephone call with Jeff Reynolds, Ohio EPA, December 5, 1991. Re: Planning Site Visit 12/6/91 and PA Questions.

6. Kemron Environmental Services, Revised Workplan, Site Characterization, Columbus Scrap Facility, Columbus, Ohio, June 7, 1991.

7. Steve Renninger, USEPA, Emergency Response Branch, Response Section #1, Telephone Conversation with Jeff Reynolds, Ohio EPA. Re: Update on USEPA Work at Columbus Scrap.

8. Ohio Department of Transportation, 1989 Aerial Photo of Columbus Scrap Area.

9. John Circle, Franklin County Engineer, Franklin County Map, 1991.

10. Kirk Guy, Bricker & Eckler Law Firm, Letter to Louise Gross, USEPA, June 8, 1990.

11. Gary Reynolds, Columbus Scrap Vice-President, Telephone Call with Jeff Reynolds, Ohio EPA, November 22, 1991. Re: PA Questions.

12. City of Columbus Public Utilities and Aviation Department, Division of Sewerage and Drainage, Sewers Map for Columbus Scrap Area.

13. Federal Emergency Management Agency, Flood Insurance Rate Map for City of Columbus, Community Panel Number 390170 0015 B. July 5, 1983.

14. Gary Reynolds, Columbus Scrap Vice-President, Telephone Call with Jeff Reynolds, Ohio EPA, August 29, 1991. Re: PA Questions/Ownership.

15. Mark Murphy, CSX Transportation, Telephone Call with Jeff Reynolds, Ohio EPA, December 4, 1991. Re: Columbus Scrap PA Questions.

16. Kelly Sherman, Ohio EPA, DERR/PCB Compliance Group, PCB Compliance Inspection Report for May 25, 1989 Inspection of Columbus Scrap Corporation.

17. Kelly Sherman, Ohio EPA, DERR/PCB Compliance Group, PCB Compliance Inspection Report for February 23, 1990 Inspection of Columbus Scrap Corporation.

18. USEPA Region V Environmental Services Division, Consent Agreement with Columbus Scrap, January 8, 1991. Re: PCB Violations/ $8,000 Fine.

19. Steve Renninger, USEPA, Emergency Response Branch, Response Section #1, Pollution Report #6 for the Columbus Scrap Site, November 8, 1991.

20. USEPA, Region 5 Waste Management Division, Administrative Order by Consent with Columbus Scrap Corporation and CSX Transportation, April 10, 1991.

21. U.S. Geological Survey (by R.P. Goldthwait, G.W. White, and J.L. Forsyth), Prepared in Cooperation with Ohio Department of Natural Resources, Division of Water and Division of Geological Survey, Glacial Map of Ohio, 1961.

22. Ohio Department of Natural Resources (J. J. Schmidt), The Ground-Water Resources of Franklin County, Ohio and the Approximate Contours on the Bedrock Surface, 1958.

23. Soil Survey of Franklin County, Ohio, USDA, Soil Conservation Service in Cooperation with Ohio Department of Natural Resources, Division of Lands and Soil, and Ohio Agricultural Research and Development Center, Issued February 1980.

24. Soil Survey of Pickaway County, Ohio, USDA, Soil Conservation Service, in Cooperation with Ohio Department of Natural Resources, Division of Lands and Soil, and Ohio Agricultural Research and Development Center, Issued February 1980.

25. Jim Nottingham, Ohio EPA, Division of Public Drinking Water, Unit Supervisor, Meeting Notes/Personal Communication, December 18, 1991. Re: Source of Columbus' Drinking Water.

26. Ohio Department of Natural Resources, Division of Water, Well Log Files (Copied 1991).

27. Monsanto, Polychlorinated Biphenyls (PCBs) Material Safety Data Sheet, October 1988. Re: PCB Properties.

28. George Bridges, Ohio Data Users Center, Ohio Department of Development, Telephone Conversation with Jeff Reynolds, Ohio EPA, November 22, 1991. Re: Franklin County Population Density and Number of People Per House.

29. US Geological Survey, Water-Data Report OH-90-2, Prepared in Cooperation with the State of Ohio and with Other Agencies, Water Resources Data, Ohio, Water Year 1990, Volume 1. Ohio River Basin. Re: Scioto River Flow.

30. Steve Graham, Ohio Department of Natural Resources, Fish Management, Telephone Conversation with Jeff Reynolds, Ohio EPA, December 4, 1991. Re: Fishing in Scioto River near Columbus Scrap, Creel Survey.

31. Bernie Counts, Ohio EPA, Division of Water Quality Planning and Assessment, 1985 and 1990 Scioto River Fish Tissue Data, Sent to Jeff Reynolds, December 5, 1991.

32. Ohio EPA, Ohio Administrative Code 3745-1-09, Scioto River Basin Use Designations.

33. Rich Carter, Ohio EPA, DERR/PCB Compliance Section, Supervisor, Telephone Conversation with Jeff Reynolds, Ohio EPA, November 27, 1991. Re: Possible PCB Sources in the Scioto River.

34. Jeff Reynolds, Ohio EPA, Distance Ring Areas and Resident Population Calculations.

35. Jeff Reynolds, Ohio EPA, Worker and Student Air and Soil Target Estimations.

OMB Approval Number: 2050-0095
Approved for Use Through: 1/92

EPA Potential Hazardous Waste Site Preliminary Assessment Form

Identification

State: OH
CERCLIS Number: OHD131884348
CERCLIS Discovery Date: 7/21/89

1. General Site Information

Name: COLUMBUS SCRAP CORPORATION
Street Address: 580 FURNACE STREET
City: COLUMBUS
State: OHIO
Zip Code: 43215
County: FRANKLIN
Co. Code: 049
Cong. Dist: 12
Latitude: 39° 56' 51._"
Longitude: 83° 0' 17._"
Approximate Area of Site: 6 Acres; ____ Square Ft
Status of Site: ☒ Active ☐ Not Specified ☐ Inactive ☐ NA (GW plume, etc.)

2. Owner/Operator Information

Owner: CSX TRANSPORTATION
Street Address: 500 WATER STREET
City: JACKSONVILLE
State: FL
Zip Code: 32202
Telephone: (904) 359-1651

Operator: COLUMBUS SCRAP CORPORATION
Street Address: 500 FURNACE STREET
City: COLUMBUS
State: OH
Zip Code: 43215
Telephone: (614) 228-1603

Type of Ownership:
☒ Private
☐ Federal Agency
Name _____
☐ State
☐ Indian
☐ County
☐ Municipal
☐ Not Specified
☐ Other _____

How Initially Identified:
☐ Citizens Complaint
☐ PA Petition
☐ State/Local Program
☐ RCRA/CERCLA Notification
☒ Federal Program
☐ Incidental
☐ Not Specified
☐ Other _____

3. Site Evaluator Information

Name of Evaluator: JEFFREY W. REYNOLDS
Agency/Organization: Ohio EPA / DERR
Date Prepared: 1/30/92
Street Address: 2305-C WESTBROOKE DR., P.O. BOX 3198
City: COLUMBUS
State: OHIO
Name of EPA or State Agency Contact: LAURA FAY
Street Address: 1800 WATERMARK DRIVE
City: COLUMBUS
State: OHIO
Telephone: (614) 644-2294

4. Site Disposition (for EPA use only)

Emergency Response/Removal Assessment Recommendation:
☐ Yes
☐ No
Date: _____

CERCLIS Recommendation:
☐ Higher Priority SI
☐ Lower Priority SI
☐ NFRAP
☐ RCRA
☐ Other _____
Date: _____

Signature:
Name (typed):
Position:

EPA Potential Hazardous Waste Site
Preliminary Assessment Form - Page 2 of 4

CERCLIS Number: OHD 131884348

5. General Site Characteristics

Predominant Land Uses Within 1 Mile of Site (check all that apply):
- [x] Industrial
- [x] Commercial
- [x] Residential
- [ ] Forest/Fields
- [ ] Agriculture
- [ ] Mining
- [ ] DOD
- [ ] DOE
- [ ] DOI
- [ ] Other Federal Facility
- [ ] Other

Site Setting:
- [x] Urban
- [ ] Suburban
- [ ] Rural

Years of Operation:
Beginning Year 1951
Ending Year 1991
[ ] Unknown

Type of Site Operations (check all that apply):
- [ ] Manufacturing (must check subcategory)
  - [ ] Lumber and Wood Products
  - [ ] Inorganic Chemicals
  - [ ] Plastic and/or Rubber Products
  - [ ] Paints, Varnishes
  - [ ] Industrial Organic Chemicals
  - [ ] Agricultural Chemicals (e.g., pesticides, fertilizers)
  - [ ] Miscellaneous Chemical Products (e.g., adhesives, explosives, ink)
  - [ ] Primary Metals
  - [ ] Metal Coating, Plating, Engraving
  - [ ] Metal Forging, Stamping
  - [ ] Fabricated Structural Metal Products
  - [ ] Electronic Equipment
  - [ ] Other Manufacturing
- [ ] Mining
  - [ ] Metals
  - [ ] Coal
  - [ ] Oil and Gas
  - [ ] Non-metallic Minerals
- [ ] Retail
- [x] Recycling
- [x] Junk/Salvage Yard
- [ ] Municipal Landfill
- [ ] Other Landfill
- [ ] DOD
- [ ] DOE
- [ ] DOI
- [ ] Other Federal Facility
- [ ] RCRA
  - [ ] Treatment, Storage, or Disposal
  - [ ] Large Quantity Generator
  - [ ] Small Quantity Generator
  - [ ] Subtitle D
    - [ ] Municipal
    - [ ] Industrial
  - [ ] "Converter"
  - [ ] "Protective Filer"
  - [ ] "Non- or Late Filer"
- [ ] Not Specified
- [ ] Other

Waste Generated:
- [ ] Onsite
- [x] Offsite
- [ ] Onsite and Offsite

Waste Deposition Authorized By:
- [ ] Present Owner
- [ ] Former Owner
- [x] Present & Former Owner
- [ ] Unauthorized
- [ ] Unknown

Waste Accessible to the Public:
- [x] Yes
- [ ] No

Distance to Nearest Dwelling, School, or Workplace: 50 Feet

6. Waste Characteristics Information

Source Type (check all that apply)	Source Waste Quantity (include units)	Tier*:
[ ] Landfill		
[ ] Surface Impoundment		
[x] Drums	≈300 DRUMS	V
[ ] Tanks and Non-Drum Containers		
[ ] Chemical Waste Pile		
[ ] Scrap Metal or Junk Pile		
[ ] Tailings Pile		
[ ] Trash Pile (open dump)		
[ ] Land Treatment		
[ ] Contaminated Ground Water Plume (unidentified source)		
[ ] Contaminated Surface Water/Sediment (unidentified source)		
[x] Contaminated Soil	6 ACRES	A
[ ] Other		
[ ] No Sources		

* C = Constituent, W = Wastestream, V = Volume, A = Area

General Types of Waste (check all that apply)
- [ ] Metals
- [x] Organics
- [ ] Inorganics
- [ ] Solvents
- [ ] Paints/Pigments
- [ ] Laboratory/Hospital Waste
- [ ] Radioactive Waste
- [ ] Construction/Demolition Waste
- [ ] Pesticides/Herbicides
- [ ] Acids/Bases
- [x] Oily Waste
- [ ] Municipal Waste
- [ ] Mining Waste
- [ ] Explosives
- [ ] Other

Physical State of Waste as Deposited (check all that apply):
- [x] Solid
- [ ] Sludge
- [ ] Powder
- [ ] Liquid
- [ ] Gas

EPA **Potential Hazardous Waste Site**
Preliminary Assessment Form - Page 3 of 4

CERCLIS Number: OHD131884348

7. Ground Water Pathway

Is Ground Water Used for Drinking Water Within 4 Miles:
- [x] Yes
- [ ] No

Type of Drinking Water Wells Within 4 Miles (check all that apply):
- [ ] Municipal
- [x] Private
- [ ] None

Is There a Suspected Release to Ground Water:
- [ ] Yes
- [x] No

Have Primary Target Drinking Water Wells Been Identified:
- [ ] Yes
- [x] No

If Yes, Enter Primary Target Population: _____ People

Depth to Shallowest Aquifer: 37 Feet

Karst Terrain/Aquifer Present:
- [ ] Yes
- [x] No

Nearest Designated Wellhead Protection Area:
- [ ] Underlies Site
- [ ] >0 - 4 Miles
- [x] None Within 4 Miles

List Secondary Target Population Served by Ground Water Withdrawn From:

0 - ¼ Mile	—
>¼ - ½ Mile	—
>½ - 1 Mile	—
>1 - 2 Miles	33
>2 - 3 Miles	519
>3 - 4 Miles	144
Total Within 4 Miles	696

8. Surface Water Pathway

Type of Surface Water Draining Site and 15 Miles Downstream (check all that apply):
- [ ] Stream
- [x] River
- [ ] Pond
- [ ] Lake
- [ ] Bay
- [ ] Ocean
- [ ] Other _____

Shortest Overland Distance From Any Source to Surface Water:
1100 Feet
0.21 Miles

Is There a Suspected Release to Surface Water:
- [ ] Yes
- [x] No

Site is Located in:
- [ ] Annual - 10 yr Floodplain
- [ ] >10 yr - 100 yr Floodplain
- [x] >100 yr - 500 yr Floodplain
- [ ] >500 yr Floodplain

Drinking Water Intakes Located Along the Surface Water Migration Path:
- [ ] Yes
- [x] No

Have Primary Target Drinking Water Intakes Been Identified:
- [ ] Yes
- [x] No

If Yes, Enter Population Served by Primary Target Intakes: _____ People

List All Secondary Target Drinking Water Intakes:

Name	Water Body	Flow (cfs)	Population Served

Total within 15 Miles _____

Fisheries Located Along the Surface Water Migration Path:
- [x] Yes
- [ ] No

Have Primary Target Fisheries Been Identified:
- [ ] Yes
- [x] No

List All Secondary Target Fisheries:

Water Body/Fishery Name	Flow (cfs)
SCIOTO RIVER	1518 (1989)

CERCLIS Number
OHD 131884348

8. Surface Water Pathway (continued)

Wetlands Located Along the Surface Water Migration Path:
- ☐ Yes
- ☒ No

Have Primary Target Wetlands Been Identified:
- ☐ Yes
- ☒ No

List Secondary Target Wetlands:

Water Body	Flow (cfs)	Frontage Miles

Other Sensitive Environments Located Along the Surface Water Migration Path:
- ☐ Yes
- ☒ No

Have Primary Target Sensitive Environments Been Identified:
- ☐ Yes
- ☒ No

List Secondary Target Sensitive Environments:

Water Body	Flow (cfs)	Sensitive Environment Type

9. Soil Exposure Pathway

Are People Occupying Residences or Attending School or Daycare on or Within 200 Feet of Areas of Known or Suspected Contamination:
- ☐ Yes
- ☒ No

If Yes, Enter Total Resident Population:

_____ People

Number of Workers Onsite:
- ☐ None
- ☒ 1 - 100
- ☐ 101 - 1,000
- ☐ > 1,000

Have Terrestrial Sensitive Environments Been Identified on or Within 200 Feet of Areas of Known or Suspected Contamination:
- ☐ Yes
- ☒ No

If Yes, List Each Terrestrial Sensitive Environment:

_____

10. Air Pathway

Is There a Suspected Release to Air:
- ☒ Yes
- ☐ No

Enter Total Population on or Within:

Onsite	30
0 - ¼ Mile	410
> ¼ - ½ Mile	4,000
> ½ - 1 Mile	40,000
> 1 - 2 Miles	120,000
> 2 - 3 Miles	90,000
> 3 - 4 Miles	130,000
Total Within 4 Miles	384,410

Wetlands Located Within 4 Miles of the Site:
- ☐ Yes
- ☒ No

Other Sensitive Environments Located Within 4 Miles of the Site:
- ☐ Yes
- ☒ No

List All Sensitive Environments Within ½ Mile of the Site:

Distance	Sensitive Environment Type/Wetlands Area (acres)
Onsite	—
0 - ¼ Mile	—
> ¼ - ½ Mile	—

LATITUDE AND LONGITUDE CALCULATION WORKSHEET #1
LI USING CUSTOM RULER OR COORDINATOR™

SITE NAME: COLUMBUS SCRAP CORPORATION CERCLIS #: OHD131884348

AKA: _____ SSID: _____

ADDRESS: 580 FURNACE STREET

CITY: COLUMBUS STATE: OHIO ZIP CODE: 43215

SITE REFERENCE POINT: SPLIT OFF OF RR TRACK AT SE CORNER OF SITE

USGS QUAD MAP NAME: SW COLUMBUS TOWNSHIP: N/A N/S RANGE: N/A E/W

SCALE: 1:24,000 MAP DATE: 1984 SECTION: ____1/4 ____1/4 ____1/4

MAP DATUM: (1927) 1983 (CIRCLE ONE) MERIDIAN: _____

COORDINATES FROM LOWER RIGHT (SOUTHEAST) CORNER OF 7.5' MAP (attach photocopy):

LONGITUDE: 083° 00' 00" LATITUDE: 39° 52' 30"

COORDINATES FROM LOWER RIGHT (SOUTHEAST) CORNER OF 2.5' GRID CELL:

LONGITUDE: 083° 00' 00" LATITUDE: 39° 55' 00"

CALCULATIONS: LATITUDE (7.5' QUADRANGLE MAP)

A) ALIGN THE BOTTOM OF THE SCALE WITH BOTTOM OF GRID. ALIGN THE TOP OF THE SCALE WITH THE TOP OF GRID. POSITION EDGE OF RULER OVER SITE REFERENCE POINT WHILE KEEPING TOP AND BOTTOM ALIGNED.

B) READ TICS ON RULER AT 1- OR 0.5-SECOND INTERVALS (INTERPOLATE).

C) EXPRESS IN MINUTES AND SECONDS (1'= 60"): 1' 51.___"

D) ADD TO STARTING LATITUDE: 39° 55' 00.___" + 1' 51.___"

SITE LATITUDE: 39° 56' 51.___"

CALCULATIONS: LONGITUDE (7.5' QUADRANGLE MAP)

A) ALIGN THE BOTTOM OF THE SCALE WITH RIGHT SIDE OF GRID. ALIGN THE TOP OF THE SCALE WITH THE LEFT SIDE OF GRID. POSITION EDGE OF RULER OVER SITE REFERENCE POINT WHILE KEEPING TOP AND BOTTOM ALIGNED.

B) READ TICS ON RULER AT 1- or 0.5-SECOND INTERVALS. (INTERPOLATE)

C) EXPRESS IN MINUTES AND SECONDS (1'= 60"): 00' 17.___"

D) ADD TO STARTING LONGITUDE: 083° 00' 00.___" + 00' 17.___"

SITE LONGITUDE: 083° 00' 17.___"

INVESTIGATOR: JEFFREY W. REYNOLDS DATE: 12/16/91

2

SITE NAME: COLUMBUS SCRAP CORP. **NUMBER:** OHD131884348



TOPOGRAPHIC MAP QUADRANGLE NAME: SOUTHWEST COLUMBUS **SCALE:** 1:24,000

COORDINATES OF LOWER RIGHT-HAND CORNER OF 2.5-MINUTE GRID:

LATITUDE: 83° 00' 00" **LONGITUDE:** 39° 55' 00"

2



1 MILE

ROAD CLASSIFICATION

Heavy-duty — Light-duty

Medium-duty — Unimproved dirt

Interstate Route — U. S. Route — State Route

QUADRANGLE LOCATION

SOUTHWEST COLUMBUS, OHIO

N3952.5—W8300/7.5
PHOTOINSPECTED 1984
1965
PHOTOREVISED 1982
DMA 4363 I NE-SERIES V852

Revisions shown in purple and woodland compiled in cooperation with State of Ohio agencies from aerial photographs taken 1979 and other sources. This information not field checked. Map edited 1982

Purple tint indicates extension of urban areas

NOV 1991

133
NE

SDMS US EPA Region V

Imagery Insert Form

Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:

☐ Illegible due to bad source documents. Image(s) in SDMS is equivalent to hard copy.

Specify Type of Document(s) / Comment

☐ **Confidential Business Information (CBI).**
This document contains highly sensitive information. Due to confidentiality, materials with such information are not available in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document.

Specify Type of Document(s) / Comment

☒ **Unscannable Material: Oversized __x__ or ___ Format.**
Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center.

Specify Type of Document(s) / Comment

SITE MAPS

☐ **Other:**

FIELD ACTIVITY REPORT

DATE: 12/6/91 TIME: 9:30 **AM**/PM WEATHER: rain clear **cloudy** snow

COUNTY: Franklin TEMPERATURE: 30 °F

SITE: Columbus Scrap OHIO I.D.# 125-1289

LOCATION: 580 Furnace St.
Columbus

OHIO EPA PERSONNEL: Jeff Reynolds-DERR

OTHER PERSONNEL: Gary Reynolds-Columbus Scrap, vice-president

PROTECTION LEVEL: A B C **D**

FIELD INSTRUMENTS:

	CALIBRATION DATE	READINGS AT SITE
PID		
CGI/O_2		
RAD METER		
OTHER		

FINDINGS/RECOMMENDATIONS (Attach additional sheets if necessary):

Site visit for USEPA Preliminary Assessment.
I met with Gary Reynolds, vice-president of Columbus Scrap, in his office. He showed me a large map of the site he had made. The map indicated areas on the CSX property (eleven plus acres total) that the USEPA Emergency Response group (Steve Renninger-OSC) had required to be studied. Some of these areas were outside the 6.2 acres of the property Columbus Scrap was leasing. Some of the areas were marked as being slated for further investigation/remediation. Others were not contaminated proposed site cleanup levels (25 ppm PCBs).

Gary Reynolds said the scrap that previously covered parts of these areas outside the property Columbus Scrap is currently leasing belonged to a previous operator. He also said the capacitors found during the 1989 TSCA inspection had been left there. He said the original reason for the TSCA inspection was that a scrap supplier, Tracy Westfall of Machine Design company, had thrown transformer carcasses in a Columbus Scrap scrap box. These carcasses were never actually purchased by Columbus Scrap but led to the TSCA inspection. This inspection found eight capacitors, one of which was labelled as containing PCBs. The others were very rusty and no labels were found.

Mr. Reynolds indicated he had all eight capacitors removed as PCB containing along with 40 cubic yards of PCB contaminated soil- not all of which was contaminated.

Columbus Scrap handles both ferrous and non-ferrous (e.g.- copper, brass, aluminum, stainless steel) scrap. The non-ferrous materials are warehoused in the big building behind the office, where they are graded and then shipped to smelters. The ferrous materials are kept out in the yard. Heavy materials are sheared and/or cut/ torched. Light materials are baled. Then it is all shipped to steel mills.

Mr. Reynolds said the property Columbus Scrap is leasing ends roughly 18 feet inside the railroad tracks to the northeast. It is bordered on the southwest by railroad tracks (some scrap is still on CSX property outside this line) and on the northwest by the Lazarus warehouse property (fence line).

He said there are plans to fence in the property (allows a cleanup level of 25 ppm PCBs under TSCA regs.) but that is not his project. He said the railroad (CSX) is deciding how much to fence in and is working with the surveyor and the fence company. This work may begin this month or next.

I then went outside to take my photos and walk the site. I made a site map (attached) and took 24 photos as follows:

1 Southwest property line of Columbus Scrap. Columbus Scrap to left, more RR property to the right. Some scrap and lime(?) piles on right side. Looking southeast.

2 Northwest property line. Lazarus warehouse on left. Looking northeast.

3 Shear building. Looking north.

4 Office on left, scale in center, welding (cutting) area and crane on right. Looking southeast.

5 Cutting area. Looking south.

6 Locker building (for workers). Looking south.

7 Garage on right and warehouse on left. Looking north.

8 Drums in scrap pile. Looking west.

9 Drums extending northwest of scrap pile (feel empty, rusty-but most without visible holes and with bungs). Looking northwest.

10 More drums piled up (maybe 300 total in area?). Garage and warehouse in background. Looking west.

11 Southern part of Columbus Scrap. Taken from railroad yard, looking southwest.

12 Northern part of Columbus Scrap. Taken from railroad yard, looking west.

13 Central part of Columbus Scrap. Taken from railroad yard, looking west.

14 Baler building, looking north.

15 Puddled/Ice area on southern part of facility. Lime piles in background. Looking southwest.

16 Columbus scrap looking northwest.

17 Southwest edge of Columbus Scrap, looking northwest.

18 Northeast edge of Columbus Scrap, looking northwest.

19 Scrap piles, looking east.

20 Scrap piles, looking east.

21 Lime(?) pile, looking southwest. There may be drainage to the southeast in this area, some evidence of puddling that way.

22 Baled scrap, looking north.

23 Baled scrap, outside Columbus Scrap property, looking southwest.

24 Big scrap pile along southwest edge of facility, looking northwest.

I left the site at 10:50 a.m.

PREPARED BY: Jeffrey W. Boyle DATE: 12/9/91



8 e.g. - PHOTO LOCATION
S - SCRAP PILE
B - BALER
L - LOCKER
Sh - SHEARER
G - GARAGE
Of - OFFICE
WRHS - WAREHOUSE

COLUMBUS SCRAP CORP.
580 FURNACE ST.
COLUMBUS
SITE VISIT MAP - 12/6/91, JEFF REYNOLDS

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 1 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: 10:00 AM DATE: 12/9/91

LOCATION: Columbus Scrap

DIRECTION: SE

OBJECT: SW Property line, scrap

REMARKS: BALER / CS property on left, more RR property on right (lime pile in bkgd.)

EXHIBIT NO: 2

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/9/91

LOCATION: CS

DIRECTION: NE

OBJECT: NW property line, gate/entrance to CS.

REMARKS: Lazarus warehouse on left.

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 3 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/9/91

LOCATION: COLUMBUS SCRAP

DIRECTION: N

OBJECT: Shear Building

REMARKS: Metal is cut here.

EXHIBIT NO: 4

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/9/91

LOCATION: COLS. SCRAP

DIRECTION: ESE

OBJECT: OFFICE ON LEFT, SCALE IN CENTER

REMARKS: CRANE / CUTTING AREA ON RIGHT



OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 5 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: S

OBJECT: CUTTING AREA

REMARKS: FOR STEEL/FERROUS

EXHIBIT NO: 6

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION: S

OBJECT: LOCKER BLDG.

REMARKS: FOR EMPLOYEES' LOCKERS.

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 7 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: N

OBJECT: GARAGE (BLUE)

NON-FERROUS WAREHOUSE (TAN)

REMARKS:

EXHIBIT NO: 8

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION: W

OBJECT: DRUMS IN

SCRAP PILE

REMARKS:



OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 9 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: NW

OBJECT: MORE DRUMS

TO N OF SCRAP PILE

REMARKS: GARAGE BEHIND

EXHIBIT NO: 10

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION:

OBJECT: DRUMS - N

OF SCRAP PILE

REMARKS: GARAGE

BEHIND

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 11 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: SW

OBJECT: SOUTHERN PART COL. SCRAP

REMARKS: TAKEN FROM RAILYARD...

EXHIBIT NO: 12

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION: SW

OBJECT: NORTHERN PART COLS. SCRAP

REMARKS:

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 13 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: W

OBJECT: CENTRAL PART

COLUMBUS SCRAP

REMARKS:

EXHIBIT NO: 14

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION: N

OBJECT: BALER BLDG.

REMARKS:

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 15 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: SW

OBJECT: SCRAP AT SOUTH END OF SITE

REMARKS: LIME (?) PILES IN BACKGROUND

EXHIBIT NO: 16

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COLS. SCRAP

DIRECTION: NW

OBJECT: CENTER OF SITE.

REMARKS:

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 17 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLS. SCRAP

DIRECTION: NW

OBJECT: SW EDGE

COLS. SCRAP

REMARKS:

EXHIBIT NO: 18

PHOTOGRAPHER: JR TIME: DATE: 12/6/9

LOCATION: COLS. SCRAP

DIRECTION: NW

OBJECT: NE EDGE

COLS. SCRAP

REMARKS:

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 19 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLS. SCRAP

DIRECTION: E

OBJECT: SCRAP PILES

REMARKS:

EXHIBIT NO: 20

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COLS. SCRAP

DIRECTION: E

OBJECT: SCRAP PILES

REMARKS:

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 21 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLS. SCRAP

DIRECTION: SW

OBJECT: LIME PILES ?

REMARKS: DRAINAGE MAY RUN LEFT (SE) FROM HERE

EXHIBIT NO: 22

PHOTOGRAPHER: JR TIME: DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION: N

OBJECT: BALED SCRAP

REMARKS:

OHIO EPA PHOTOGRAPHY DATA

EXHIBIT NO: 23 3

PHOTOGRAPHER: JEFF REYNOLDS TIME: DATE: 12/6/91

LOCATION: COLUMBUS SCRAP

DIRECTION: SW

OBJECT: BALED SCRAP

REMARKS: OUTSIDE COLS. SCRAP PROPERTY

ATTACH PHOTOGRAPH HERE

PHOTO NOT AVAILABLE -

EXHIBIT NO: 24

PHOTOGRAPHER: JR TIME: 10:50 AM DATE: 12/6/91

LOCATION: COL. SCRAP

DIRECTION: NW

OBJECT: SCRAP PILE ALONG SW EDGE OF FACILITY

REMARKS:

4

ISSN 0731-5627

The Weather Almanac

A Reference Guide to Weather, Climate, and Air Quality in the United States and Its Key Cities, Comprising Statistics, Principles, and Terminology. Provides Weather/Health Information and Safety Rules for Environmental Hazards Associated with Storms, Weather Extremes, Earthquakes, and Volcanoes. Also Includes World Climatological Highlights and Special Features on Weather, Climate, and Society and on Ozone in the Upper Atmosphere.

FIFTH EDITION

James A. Ruffner
and
Frank E. Bair
Editors

GALE RESEARCH COMPANY
BOOK TOWER • DETROIT, MICHIGAN 48226

4

TABLE 1 NORMALS, MEANS AND EXTREMES

COLUMBUS, OHIO

LATITUDE: 40°00'N LONGITUDE: 82°53' W ELEVATION: FT. GRND 813 BARO 816 TIME ZONE: EASTERN WBAN: 14821

	(a)	JAN	FEB	MAR	APR	MAY	JUNE	JULY	AUG	SEP	OCT	NOV	DEC	YEAR
TEMPERATURE °F:														
Normals														
-Daily Maximum		34.7	38.1	49.3	62.3	72.6	81.3	84.4	83.0	76.9	65.0	50.7	39.4	61.5
-Daily Minimum		19.4	21.5	30.6	40.5	50.2	59.0	63.2	61.7	54.6	42.8	33.5	24.7	41.8
-Monthly		27.1	29.8	40.0	51.4	61.4	70.2	73.8	72.3	65.8	53.9	42.1	32.0	51.6
Extremes														
-Record Highest	46	74	73	85	89	94	102	100	101	100	90	80	76	102
-Year		1950	1957	1945	1948	1941	1944	1955	1983	1951	1951	1950	1982	JUN 1944
-Record Lowest	46	-19	-13	-6	14	25	35	43	39	31	20	5	-12	-19
-Year		1985	1977	1984	1982	1966	1972	1972	1965	1963	1962	1976	1983	JAN 1985
NORMAL DEGREE DAYS:														
Heating (base 65°F)		1175	986	775	408	178	19	0	5	78	355	687	1020	5686
Cooling (base 65°F)		0	0	0	0	66	175	273	235	102	11	0	0	862
% OF POSSIBLE SUNSHINE	34	36	42	44	51	56	60	60	60	61	55	37	30	49
MEAN SKY COVER (tenths)														
Sunrise - Sunset	36	7.8	7.5	7.4	7.0	6.6	6.2	6.0	5.9	5.6	5.7	7.4	7.8	6.7
MEAN NUMBER OF DAYS:														
Sunrise to Sunset														
-Clear	36	4.2	4.0	4.9	5.4	6.0	6.3	6.6	7.1	9.5	10.3	4.9	3.9	73.0
-Partly Cloudy	36	6.3	6.2	6.7	7.9	10.4	11.3	13.4	12.9	9.1	7.3	6.6	6.1	104.2
-Cloudy	36	20.5	18.0	19.5	16.7	14.6	12.5	11.0	11.1	11.5	13.3	18.4	20.9	188.1
Precipitation .01 inches or more	46	13.3	11.5	14.0	12.9	12.7	11.0	10.8	9.4	8.3	8.8	11.5	12.7	136.8
Snow, Ice pellets 1.0 inches or more	37	3.0	2.1	1.5	0.2	0.0	0.0	0.0	0.0	0.0	0.*	0.8	1.9	9.6
Thunderstorms	46	0.4	0.5	2.2	4.1	6.4	8.0	8.1	6.4	3.0	1.2	0.9	0.3	41.4
Heavy Fog Visibility 1/4 mile or less	36	2.0	1.6	1.1	0.6	0.9	1.1	1.2	1.8	1.8	1.5	1.3	1.5	16.5
Temperature °F														
-Maximum														
90° and above	26	0.0	0.0	0.0	0.0	0.5	3.2	5.3	3.0	1.4	0.0	0.0	0.0	13.4
32° and below	26	14.8	10.1	3.0	0.1	0.0	0.0	0.0	0.0	0.0	0.0	1.2	9.2	38.4
-Minimum														
32° and below	26	27.5	23.9	18.9	6.8	0.7	0.0	0.0	0.0	0.1	3.9	14.0	23.9	119.8
0° and below	26	3.3	1.7	0.2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.8	6.0
AVG. STATION PRESS. (mb)	13	988.5	988.5	985.8	985.9	985.0	986.0	987.1	988.3	988.9	989.4	988.8	988.7	987.6
RELATIVE HUMIDITY (%)														
Hour 01	26	74	73	69	69	76	80	82	84	82	78	77	76	77
Hour 07 (Local Time)	26	76	75	73	74	79	81	84	87	87	81	80	78	80
Hour 13	26	67	64	57	52	54	55	56	58	57	55	64	69	59
Hour 19	26	69	66	60	54	57	58	60	63	65	64	69	72	63
PRECIPITATION (inches):														
Water Equivalent														
-Normal		2.75	2.18	3.23	3.41	3.76	4.01	4.01	3.70	2.76	1.91	2.64	2.61	36.97
-Maximum Monthly	46	8.29	4.60	9.59	6.36	9.11	9.75	9.46	8.63	6.76	5.24	10.67	5.07	10.67
-Year		1950	1981	1964	1964	1968	1958	1958	1979	1979	1954	1985	1951	NOV 1985
-Minimum Monthly	46	0.53	0.29	0.61	0.67	0.95	0.71	0.48	0.58	0.51	0.11	0.60	0.46	0.11
-Year		1944	1978	1941	1971	1977	1984	1940	1951	1963	1963	1976	1955	OCT 1963
-Maximum in 24 hrs	38	4.81	2.15	3.40	2.37	2.72	2.93	3.82	3.79	4.86	1.87	2.47	1.74	4.86
-Year		1959	1975	1964	1957	1968	1958	1969	1972	1979	1965	1985	1978	SEP 1979
Snow, Ice pellets														
-Maximum Monthly	38	34.4	16.4	13.5	7.1	T				T	1.3	15.2	17.3	34.4
-Year		1978	1979	1962	1973	1966				1967	1962	1950	1960	JAN 1978
-Maximum in 24 hrs	38	7.5	8.9	8.6	6.3	T				T	1.3	8.2	8.7	8.9
-Year		1978	1971	1962	1973	1966				1967	1962	1950	1960	FEB 1971
WIND:														
Mean Speed (mph)	36	10.3	10.1	10.7	10.1	8.5	7.6	6.9	6.5	6.7	7.7	9.5	9.9	8.7
Prevailing Direction through 1963		SSW	NW	SSW	WNW	S	SSW	SSW	NNW	S	S	S	W	S
Fastest Mile														
-Direction	29	W	W	NW	W	NW	NW	W	SW	N	SW	N	SW	NW
-Speed (MPH)	29	56	57	63	56	54	47	51	43	38	43	61	47	63
-Year		1959	1956	1955	1970	1964	1966	1976	1979	1963	1979	1952	1971	MAR 1955
Peak Gust														
-Direction	2	W	E	W	S	W	SW	N	W	S	NW	W	W	W
-Speed (mph)	2	51	44	53	52	52	40	47	56	38	37	39	48	56
-Date		1985	1984	1985	1985	1985	1984	1985	1984	1985	1985	1985	1985	AUG 1984

See Reference Notes to this table on the following page.

TABLE 2 PRECIPITATION (inches)

COLUMBUS, OHIO

YEAR	JAN	FEB	MAR	APR	MAY	JUNE	JULY	AUG	SEP	OCT	NOV	DEC	ANNUAL
1956	2.13	4.11	3.44	4.76	4.85	4.2[illegible]	4.45	2.23	1.37	1.15	0.97	3.21	35.93
1957	1.94	1.82	1.61	5.70	5.41	5.20	2.99	0.81	2.99	1.27	3.23	4.68	37.77
1958	1.81	0.82	1.50	4.09	3.54	9.25	9.46	2.81	3.01	1.27	1.56	0.63	40.37
1959	2.44	3.08	1.45	3.69	4.15	1.55	3.23	1.55	1.55	3.33	3.71	2.27	36.91
1960	2.31	2.57	1.11	1.60	5.82	2.47	4.54	2.48	0.83	2.55	1.60	1.62	29.50
1961	0.65	2.90	4.83	4.58	2.90	3.49	4.61	2.73	1.05	1.18	3.49	2.42	34.83
1962	3.17	3.46	2.43	1.33	2.31	2.26	3.59	2.31	3.62	2.06	2.94	1.76	31.24
1963	1.39	1.01	7.14	3.27	1.61	1.25	2.90	3.67	0.51	0.11	0.80	0.85	24.51
1964	1.82	1.68	9.59	6.36	1.95	5.71	2.97	3.19	1.66	0.38	1.81	4.09	41.21
1965	2.70	3.76	2.90	5.90	4.00	2.42	3.76	4.62	6.18	3.98	1.19	1.24	42.65
1966	2.87	2.59	1.04	4.89	3.13	1.28	5.91	4.30	3.56	0.79	4.05	3.33	38.34
1967	0.78	2.46	4.40	3.29	4.59	2.92	4.22	1.51	2.63	1.39	3.22	2.55	33.96
1968	2.22	0.38	3.01	2.20	9.11	2.96	2.80	3.08	1.77	2.59	4.26	3.40	37.78
1969	3.40	1.17	1.32	3.10	3.04	8.19	7.65	3.25	1.40	1.52	3.87	2.30	40.21
1970	1.60	1.68	3.04	5.52	5.37	5.65	3.73	3.94	3.95	2.07	2.88	2.50	41.93
1971	1.57	3.16	2.70	0.67	3.66	4.16	4.22	2.81	3.08	1.32	1.73	4.61	33.69
1972	1.40	1.74	2.86	3.74	6.56	3.98	2.60	7.96	5.13	1.74	4.40	3.49	45.60
1973	2.46	1.29	3.43	3.72	3.36	8.77	4.07	4.97	2.82	3.29	5.37	2.70	46.25
1974	2.40	2.30	4.38	2.66	3.29	5.04	1.14	4.88	3.32	1.51	3.39	2.68	36.99
1975	3.21	3.47	4.10	2.71	3.17	3.53	2.04	4.51	5.46	2.29	1.54	3.01	39.04
1976	3.15	2.03	2.17	1.44	1.41	4.52	5.12	5.08	2.54	2.86	0.60	0.93	31.85
1977	1.57	1.02	3.88	4.04	0.95	4.02	2.52	4.76	3.48	2.57	3.77	3.54	36.12
1978	5.89	0.29	2.98	3.02	4.15	3.65	1.81	5.23	1.16	2.39	1.56	5.01	37.14
1979	3.32	2.88	1.01	4.01	3.27	4.23	8.06	8.63	6.76	1.26	3.91	1.83	49.17
1980	1.69	1.38	3.77	1.59	4.56	5.17	4.58	6.26	1.86	2.53	2.07	1.96	37.42
1981	0.70	4.60	1.11	5.38	6.50	5.73	4.14	1.41	2.28	1.40	1.65	2.88	37.78
1982	4.77	1.49	3.99	1.90	4.68	3.37	3.90	1.02	4.25	0.92	5.19	3.84	39.32
1983	1.20	0.74	1.69	5.58	5.06	4.59	2.80	2.23	1.91	4.45	5.00	3.16	38.41
1984	1.07	1.97	3.89	3.10	4.93	0.71	3.15	2.96	1.48	2.91	4.41	2.84	33.42
1985	1.31	1.67	3.78	0.73	4.96	1.41	6.88	2.34	1.18	1.93	10.67	1.81	38.67
Record Mean	2.89	2.44	3.97	3.16	3.72	3.70	3.73	3.26	2.60	2.22	2.80	2.59	37.09

TABLE 3 AVERAGE TEMPERATURE (deg F)

COLUMBUS, OHIO

YEAR	JAN	FEB	MAR	APR	MAY	JUNE	JULY	AUG	SEP	OCT	NOV	DEC	ANNUAL
1956	27.7	35.6	39.5	48.5	61.3	71.1	73.8	73.1	63.4	59.4	43.1	40.8	53.1
1957	25.8	36.5	40.7	54.1	62.7	72.3	75.1	73.3	66.3	51.5	43.4	36.8	53.2
1958	28.4	24.9	37.7	52.4	61.4	67.7	74.4	72.6	66.1	54.4	43.9	23.4	50.6
#1959	26.0	32.7	38.8	52.6	66.8	71.5	75.4	77.3	69.6	55.1	39.5	36.4	53.5
1960	34.1	28.8	28.4	55.3	59.4	69.7	71.8	74.9	68.3	55.1	44.4	25.1	51.3
1961	23.5	36.9	45.3	47.1	56.5	67.2	73.7	73.1	71.0	55.3	41.8	29.7	51.8
1962	24.6	28.8	36.9	48.7	67.2	72.3	71.3	71.6	61.5	54.4	40.8	24.9	50.2
1963	21.7	22.4	42.8	51.1	58.8	70.8	73.9	69.9	63.7	59.9	44.6	21.6	50.1
1964	30.1	27.7	41.1	53.6	63.4	70.3	74.4	71.2	65.0	51.1	45.1	33.9	52.3
1965	28.3	29.1	34.8	51.4	68.1	69.4	72.0	71.0	68.3	54.4	43.3	36.6	52.2
1966	22.2	29.4	41.8	49.4	56.1	71.4	75.6	71.3	63.2	50.7	42.4	32.6	50.5
1967	34.8	25.8	40.4	52.6	55.4	71.8	71.7	68.3	60.4	51.9	36.7	34.3	50.3
1968	23.6	25.7	43.3	53.1	58.5	71.5	74.1	73.0	65.5	54.1	44.0	31.1	51.5
1969	27.0	31.4	35.3	51.5	61.7	68.5	74.1	71.2	63.8	53.9	39.3	26.8	50.4
1970	20.6	28.5	36.9	53.4	64.9	69.8	73.5	72.4	68.9	55.6	42.4	34.3	51.8
1971	24.3	30.8	36.6	49.0	58.0	73.5	70.5	68.9	67.8	59.8	40.4	38.4	51.5
1972	28.2	27.7	37.0	48.8	60.8	63.6	71.9	70.1	64.6	49.6	40.5	36.1	49.9
1973	31.2	31.4	50.4	51.1	59.5	72.6	74.3	74.2	68.9	58.6	45.1	33.7	54.3
1974	33.2	31.2	44.6	54.3	60.8	67.7	74.4	74.0	62.2	52.8	44.5	34.0	52.8
1975	32.5	33.4	37.3	46.7	66.6	72.4	75.1	77.3	62.7	54.7	47.5	33.5	53.3
1976	24.0	37.4	46.5	50.9	58.1	70.5	72.0	68.3	61.7	47.5	33.9	24.8	49.6
1977	11.4	26.5	45.6	54.8	66.8	67.5	76.2	72.0	68.2	52.0	45.1	29.5	51.3
1978	19.0	16.6	34.5	50.6	59.6	70.4	73.5	73.2	69.8	51.5	44.4	34.4	49.8
1979	21.4	19.3	44.3	50.1	60.5	69.6	71.8	71.9	65.1	53.3	43.6	35.1	50.5
1980	29.3	25.2	37.2	49.5	62.4	67.4	75.9	75.9	68.3	50.8	40.8	32.5	51.3
1981	23.3	34.0	40.2	55.8	59.5	70.9	71.9	70.4	62.3	51.1	40.9	30.6	50.9
1982	21.2	29.2	40.4	46.4	66.8	65.8	74.4	69.2	63.5	56.2	45.4	40.4	51.6
1983	29.3	34.0	43.3	48.4	57.6	69.4	76.7	76.2	67.1	54.5	44.0	24.8	52.2
1984	23.3	37.4	32.3	50.0	57.6	73.1	71.2	72.9	63.1	59.4	40.6	39.5	51.7
1985	21.7	26.0	43.7	56.3	62.6	66.9	72.7	71.2	66.6	57.3	48.2	26.0	51.6
Record Mean	28.7	30.6	40.0	51.1	61.8	70.8	74.7	72.8	66.4	54.8	42.3	32.4	52.2
Max.	38.2	38.6	49.0	61.3	72.4	81.2	85.1	83.1	77.1	65.1	50.4	39.5	61.6
Min.	21.2	22.6	31.0	40.9	51.2	60.3	64.2	62.5	55.8	44.6	34.1	25.2	42.8

REFERENCE NOTES FOR TABLES 1, 2, 3 and 6 (COLUMBUS, OH)

GENERAL

T - TRACE AMOUNT
BLANK ENTRIES DENOTE MISSING/UNREPORTED DATA
# INDICATES A STATION OR INSTRUMENT RELOCATION

SPECIFIC

TABLE 1

(a) - LENGTH OF RECORD IN YEARS ALTHOUGH INDIVIDUAL MONTHS MAY BE MISSING.

* LESS THAN .05

NORMALS — BASED ON THE 1951-1980 RECORD PERIOD
EXTREMES — DATES ARE THE MOST RECENT OCCURRENCE.
WIND DIR. — NUMERALS SHOW TENS OF DEGREES CLOCKWISE FROM TRUE NORTH
"00" INDICATES CALM.
RESULTANT WIND DIRECTIONS ARE GIVEN TO WHOLE DEGREES.

EXCEPTIONS

TABLES 2, 3, and 6

RECORD MEANS ARE THROUGH THE CURRENT YEAR, BEGINNING IN
1879 FOR TEMPERATURE
1879 FOR PRECIPITATION
1948 FOR SNOWFALL

OHIO ENVIRONMENTAL PROTECTION AGENCY

TELEPHONE MEMORANDUM

WITH GARY REYNOLDS DATE 12/5/91

REPRESENTING COLUMBUS SCRAP V-P TIME 10:40 a.m.

PERMIT NO. PHONE 228-1603

OEPA STAFF JEFF REYNOLDS

SUBJECT COLUMBUS SCRAP - PA QUESTIONS AND TO LET HIM KNOW I'M COMING FOR SITE VISIT 12/6.

NOTES & SUMMARY: FOLLOW-UP DATE

GARY SAID THE SITE IS 6.2 ACRES (COLS. SCRAP FACILITY). PREVIOUSLY HAD 11 PLUS ACRES, TURNED SOME BACK OVER TO CSX. HE SAYS THE USEPA IS STUDYING 11 PLUS ACRES, NOT SIX LIKE THEY CLAIM. THEY ARE STUDYING SOME AREA OFF THE COLS. SCRAP FACILITY. HE DOESN'T WANT TO GIVE ME A COPY OF THE LEASE - DOESN'T UNDERSTAND WHY I NEED IT. HE SAID THEY HAVE TO UNREASOBLY MOVE DIRT. IT COULD POTENTIALLY COST THEM $2 MILLION TO HAUL THE DIRT AWAY, BUT THEY'RE A LONG WAY FROM AGREEING TO ANYTHING. I ASKED AGAIN IF I COULD GET A COPY OF THE LEASE IT DIDN'T SOUND LIKE I WOULD.

Signature Jeffrey W. Reynolds

OEPA-INDWW-3

KEMRON
ENVIRONMENTAL SERVICES

1815 Century Blvd. ▪ Suite 150 ▪ Atlanta, Georgia 30345 ▪ Telephone (404) 636-0928 ▪ FAX (404) 636-7162

Project 455

7 June 1991

REVISED WORK PLAN
SITE CHARACTERIZATION
COLUMBUS SCRAP FACILITY
COLUMBUS, OHIO

Submitted to:

U.S. Environmental Protection Agency
Region V
230 South Dearborn Street
Chicago, Illinois 60604

Submitted by:

KEMRON Environmental Services, Inc.
1815 Century Boulevard, Suite 150
Atlanta, Georgia 30345

gb:workplan.455

EXECUTIVE SUMMARY

The Columbus Scrap Facility is located at 580 Furnace Street, Columbus, Ohio. The property is owned by CSX Transportation and leased by Columbus Scrap Corporation, and has been operated by various companies as a scrap yard since 1951. In May 1989 the Ohio EPA inspected the facility and discovered eight capacitors on the property. The capacitors and surrounding soil were removed by Chemical Waste Management, leaving three shallow pits. Subsequent soil sampling by Chemical Waste Management and Maecorp indicated that complete remediation of PCB soil contamination had not been accomplished. PCB sampling of soils in and around the pits was repeated in July 1990 by KEMRON Environmental Services and the United States Environmental Protection Agency (USEPA). Assay results confirmed the presence of PCBs. A USEPA Administrative Order by Consent (AOC) was issued requiring Columbus Scrap and CSXT to conduct further contamination assessment and eventual remediation of the site. The AOC was signed on 10 April 1991.

This Work Plan was prepared by KEMRON under the direction of Mr. Mark Murphy, Project Coordinator for Columbus Scrap and CSXT, as required in paragraph 1 of the AOC. The sampling and analysis plan is designed to survey the site in appropriate detail for the presence of PCBs and leachable metals (the eight RCRA metals and zinc). A three phase approach is proposed, with sampling in each phase becoming increasingly detailed. The first phase involves delineation of potentially contaminated areas (PCAs). The second phase involves dividing the PCAs into sectors and characterizing surficial contaminant concentrations in each sector. The third phase involves depth profiling in contaminated sectors. Which areas are considered potentially contaminated and which sectors are considered contaminated will be base upon whether or not assay results exceed target contamination levels. Phase one samples will be contoured. Areas within the target contamination level contour (equal to one-fifth of the TCLP limit for each metal and 5 ppm for PCBs) will be considered potentially contaminated. Sector assays that exceed target levels will trigger depth profiling and eventual remediation of the affected sector. Remediation triggers will be the TCLP limits for metals and 25 ppm for PCBs.

Elements of this Work Plan include the Sampling and Analysis Plan, project organization, and project schedule. The health and safety of field personnel will be maintained through compliance with the project-specific Health and Safety Plan (Appendix A). Sampling and other work tasks will be done in accordance with procedures delineated in the Quality Assurance Project Plan (Appendix B).

1.0 INTRODUCTION

This Work Plan for characterization of soil contamination at the Columbus Scrap Facility, Columbus, Ohio was developed in compliance with an Administrative Order by Consent (AOC) for the site, signed on 10 April 1991.

Project background is outlined in this introductory section. Project organization and the proposed schedule for completion of Work Plan tasks are presented in Sections 2.0 and 3.0. Specific elements of the Work Plan are detailed in Section 4.0. A project-specific Health and Safety Plan and Quality Assurance Project Plan (QAPP) are included as Appendices A and B. The method for selecting sample locations is detailed in Appendix C.

1.1 PROJECT BACKGROUND

The subject site is located at 580 Furnace Street in Columbus, Ohio. The property is owned by CSX Transportation (CSXT) and has been leased to Columbus Scrap Corporation since July 1985. A site map is presented as Figure 1. In May 1989, polychlorinated biphenyl (PCB)-contaminated capacitors were discovered in a roll-off box owned by Columbus Scrap and used by a local equipment rebuilder. This discovery prompted the Ohio EPA (OEPA), acting as agent for the USEPA, to conduct an inspection of the subject property. The purpose of the inspection, performed on 25 May 1989, was to monitor Columbus Scrap's compliance with federal regulations governing the handling and disposal of PCBs. Eight electrical capacitors, at least one of which was identified as containing PCBs, were found during the course of the inspection. A soil sample collected by OEPA during the inspection and assayed for PCBs contained approximately 1,000 mg/kg (ppm) of the PCB Arochlor 1242.

Following the inspection, Chemical Waste Management, Inc. was retained by Columbus Scrap to remove the eight capacitors and excavate and dispose of surrounding soils. This was accomplished in June 1989. Three shallow pits remained where the capacitors had been located (Figure 1). Chemical Waste Management retrieved initial soil samples from the excavated pits on 23 February 1990 and confirmatory samples on 9 July 1990. Additional soil samples were collected from areas surrounding the pits by Maecorp, Inc. on 22 and 23 September 1990. Based



Figure 1. Site map.

upon the results of this sampling, USEPA determined that a more extensive soil sampling program should be conducted over the entire facility in anticipation of remediation of site soils.

Toward the end of this prior work, KEMRON was authorized by CSXT to conduct a general investigation and sampling program at the Columbus Scrap Facility. On 27 July 1990, ten representative soil samples were collected by KEMRON and split with a USEPA Technical Assistance Team. The samples were primarily from in and around the pits, as shown in Figure 2. These samples were assayed for PCBs. USEPA assay results indicated the presence of four PCB mixtures (see Section 1.3).

Representatives of Columbus Scrap, CSXT, KEMRON, and USEPA Region V met at the Columbus Scrap Facility on 17 December 1990. Various options for further action at the site were discussed. As a result, a USEPA Administrative Order by Consent (AOC) was issued, requiring Columbus Scrap and CSXT to conduct further contamination assessment and eventual remediation at the site. The AOC was signed on 10 April 1991. This Work Plan was prepared by KEMRON in response to the AOC.

1.2 FACILITY BACKGROUND

Columbus Scrap Corporation operates a commercial scrap yard on an approximately 6.5 acre site in Columbus, Ohio (Figure 3). The site is owned by CSXT, and Columbus Scrap operates under the terms of a lease dated July 1985. The site has an unbroken 40-year history as an operating scrap yard. Between November 1981 and July 1985, the site was operated as a scrap yard by Summer Company. In July 1985, Columbus Scrap purchased Summer Company. Prior to November 1981, the site was used as a scrap yard by Handler Compressed Steel Corporation. Handler had leased the property since May 1951. Prior to May 1951 the site was used in conjunction with railroad operations.

The site is utilized for the storage, shredding, and recycling of scrap metal. The triangular parcel is bounded on the northeast and southwest by railroad track and rail spurs and on the northwest by a warehouse operation. Aside from the inventory, four structures occupy

OHIO ENVIRONMENTAL PROTECTION AGENCY

TELEPHONE MEMORANDUM

WITH STEVE RENNINGER DATE 11/25/91

REPRESENTING USEPA - ER (WESTLAKE) OSC TIME 2:30 p.m.

PERMIT NO. PHONE (216) 835-5200

OEPA STAFF JEFF REYNOLDS

SUBJECT COLUMBUS SCRAP / I CALLED FOR AN UPDATE ON THEIR WORK.

NOTES & SUMMARY: FOLLOW-UP DATE

STEVE SAID THEY SAMPLED SOME SOIL FOR TOTAL METALS. NO PROBLEMS FOUND. ABOUT 5 OF 6 ACRES "HOT" FOR PCBs. COMPUTER GENERATED CONTOUR LINES - WILL MAP AND THEN SAMPLE TO DEPTH OF 2 FEET. WILL USE 25 ppm FOR "HOT" AREA SINCE RESTRICTING ACCESS TO SITE - WHOLE SITE. THEY'RE CURRENTLY TAKING ADDITIONAL SAMPLES. WAITING FOR COLS. SCRAP TO MOVE SCRAP PILES. THEN THEY SAMPLE THAT AREA. HE'D LIKE A COPY OF THE FINAL PA.

Signature

OEPA-INDWW-3

REF. 8
↑N
COLUMBUS
SCRAP

FRANKLIN COUNTY
OHIO
JOHN CIRCLE COUNTY ENGINEER

JACK FOULK • DOROTHY S. TEATER • HUGH DeMOSS
BOARD OF COMMISSIONERS



The Discovery Bridge



Columbus 92

The Santa Maria



AmeriFlora 92

Franklin Park Conservatory

INCLUDING: Columbus &
Bexley • Brice • Canal Winchester • Downtown Columbus • Dublin • Franklin Park • Gahanna • Grandview Heights • Grove City • Groveport • Harrisburg • Hilliard • Lithopolis • Lockbourne • Marble Cliff • Minerva Park • New Albany • New Rome • Obetz • The Ohio State University • Pickerington • Reynoldsburg • Riverlea • Upper Arlington • Urbancrest • Valleyview • Westerville • Whitehall • Worthington.

PLAN AHEAD • SAVE TIME

FOR FREE DISTRIBUTION ONLY

GOODALE BLVD.
Dublin Rd Water Treatment Plant
TWIN RIVERS DR
U.S. Post Office
Franklin Co. Veterans Memorial
State Capitol
Franklin University
Cultural Arts Center
Dodge Park
Lazarus Dist Center
1 Franklin Co Government Center
2 Franklin Co Administration Bldg
Cooper Stadium
Mt Calvary Cemetery
Jewish Cemetery
Greenlawn Park
Greenlawn Cemetery
Columbus Police Impounding Lot
Lower Scioto Park
Scioto River
Fire Training Academy
Schiller Park
Lincoln Park
Berliner Park
St. Anthony Mercy Hospital
Franklin Co. Pre-Release Center & Ohio Correctional Medical Center
Franklin Co. Correctional Center II
Solid Waste Reduction Facility
Manor-Franklin Park
Capital Area Humane Society
C & O RR Yards
Stockbridge Park
GREENLAWN AVE. C146
STIMMEL RD. C249
HART RD. C254
C125
C142
C378
HARMON AVE.
FRANK RD.
GROVEPORT RD.
CORR RD.
WHITTIER ST.
LIVINGSTON AVE.
MOOBERRY
BRYDEN
FRANKLIN
OAK
BROAD ST.
MAIN ST.
FULTON ST.
KENNEDY DR
THURMAN
HANFORD
HOSACK
BARTHMAN AVE
MARION RD.
LOCKBOURNE
CHAMPION
PARSONS
OHIO AVE.
FAIRWOOD
BUCKEYE PARK RD
KINGSTON AVE.
BELLEVUE AVE
COCHRANE AVE
DERING AVE.
NEFF AVE.
SOUTHGATE DR
STOCKBRIDGE RD
RUMSEY RD
COULTER AVE
CAROLANN AVE.
HILOCK
BASSWOOD
BRUCKNER RD
SILVERBROOK DR
EVERGREEN DR
FABER
KOEBEL
GLENDOWER
LLEWELLYN AVE.
FORNOFF RD
CASTLE RD
FORNOFF RD.
PHELPS RD
DELAMEY
CURRIER
MARKHAM RD
LEE ELLEN
HILLGATE
CARNATION ST.
SHELLY
GIBSON
DOLBY
SCIOTO
ROYAL CREEK CT
TOKEN DR
WILLOW VIEW CT.
WILLOW VIEW DR
BROWN RD.
260
104
3000
2000
1000
105
103
102
101
100A
100B
99A
99B
99C
108A
108B
109
107
106
95
96
92
76
78
84
89
21
65
62
40
23
33
82
3
20
2C
3a
4A
5
7
9
10
12
14
16
18
22
24
26
28
30
32
34
36
38
40
42
44
46
48
50
52
54
56
58
60
62
64
66
68
70
72
74
76
78
80
82
84
86
88
90
92
94
96
98
100
102
104
106
108
110
112
114
116
118
120
122
124
126
128
130
132
134
136
138
140
142
144
146
148
150
152
154
156
158
160
162
164
166
168
170
172
174
176
178
180
182
184
186
188
190
192
194
196
198
200
202
204
206
208
210
212
214
216
218
220
222
224
226
228
230
232
234
236
238
240
242
244
246
248
250
252
254
256
258
260
262
264
266
268
270
272
274
276
278
280
282
284
286
288
290
292
294
296
298
300
302
304
306
308
310
312
314
316
318
320
322
324
326
328
330
332
334
336
338
340
342
344
346
348
350
352
354
356
358
360
362
364
366
368
370
372
374
376
378
380
382
384
386
388
390
392
394
396
398
400
402
404
406
408
410
412
414
416
418
420
422
424
426
428
430
432
434
436
438
440
442
444
446
448
450
452
454
456
458
460
462
464
466
468
470
472
474
476
478
480
482
484
486
488
490
492
494
496
498
500
502
504
506
508
510
512
514
516
518
520
522
524
526
528
530
532
534
536
538
540
542
544
546
548
550
552
554
556
558
560
562
564
566
568
570
572
574
576
578
580
582
584
586
588
590
592
594
596
598
600
602
604
606
608
610
612
614
616
618
620
622
624
626
628
630
632
634
636
638
640
642
644
646
648
650
652
654
656
658
660
662
664
666
668
670
672
674
676
678
680
682
684
686
688
690
692
694
696
698
700
702
704
706
708
710
712
714
716
718
720
722
724
726
728
730
732
734
736
738
740
742
744
746
748
750
752
754
756
758
760
762
764
766
768
770
772
774
776
778
780
782
784
786
788
790
792
794
796
798
800
802
804
806
808
810
812
814
816
818
820
822
824
826
828
830
832
834
836
838
840
842
844
846
848
850
852
854
856
858
860
862
864
866
868
870
872
874
876
878
880
882
884
886
888
890
892
894
896
898
900
902
904
906
908
910
912
914
916
918
920
922
924
926
928
930
932
934
936
938
940
942
944
946
948
950
952
954
956
958
960
962
964
966
968
970
972
974
976
978
980
982
984
986
988
990
992
994
996
998
1000
1002
1004
1006
1008
1010
1012
1014
1016
1018
1020
1022
1024
1026
1028
1030
1032
1034
1036
1038
1040
1042
1044
1046
1048
1050
1052
1054
1056
1058
1060
1062
1064
1066
1068
1070
1072
1074
1076
1078
1080
1082
1084
1086
1088
1090
1092
1094
1096
1098
1100
1102
1104
1106
1108
1110
1112
1114
1116
1118
1120
1122
1124
1126
1128
1130
1132
1134
1136
1138
1140
1142
1144
1146
1148
1150
1152
1154
1156
1158
1160
1162
1164
1166
1168
1170
1172
1174
1176
1178
1180
1182
1184
1186
1188
1190
1192
1194
1196
1198
1200
1202
1204
1206
1208
1210
1212
1214
1216
1218
1220
1222
1224
1226
1228
1230
1232
1234
1236
1238
1240
1242
1244
1246
1248
1250
1252
1254
1256
1258
1260
1262
1264
1266
1268
1270
1272
1274
1276
1278
1280
1282
1284
1286
1288
1290
1292
1294
1296
1298
1300
1302
1304
1306
1308
1310
1312
1314
1316
1318
1320
1322
1324
1326
1328
1330
1332
1334
1336
1338
1340
1342
1344
1346
1348
1350
1352
1354
1356
1358
1360
1362
1364
1366
1368
1370
1372
1374
1376
1378
1380
1382
1384
1386
1388
1390
1392
1394
1396
1398
1400
1402
1404
1406
1408
1410
1412
1414
1416
1418
1420
1422
1424
1426
1428
1430
1432
1434
1436
1438
1440
1442
1444
1446
1448
1450
1452
1454
1456
1458
1460
1462
1464
1466
1468
1470
1472
1474
1476
1478
1480
1482
1484
1486
1488
1490
1492
1494
1496
1498
1500
1502
1504
1506
1508
1510
1512
1514
1516
1518
1520
1522
1524
1526
1528
1530
1532
1534
1536
1538
1540
1542
1544
1546
1548
1550
1552
1554
1556
1558
1560
1562
1564
1566
1568
1570
1572
1574
1576
1578
1580
1582
1584
1586
1588
1590
1592
1594
1596
1598
1600
1602
1604
1606
1608
1610
1612
1614
1616
1618
1620
1622
1624
1626
1628
1630
1632
1634
1636
1638
1640
1642
1644
1646
1648
1650
1652
1654
1656
1658
1660
1662
1664
1666
1668
1670
1672
1674
1676
1678
1680
1682
1684
1686
1688
1690
1692
1694
1696
1698
1700
1702
1704
1706
1708
1710
1712
1714
1716
1718
1720
1722
1724
1726
1728
1730
1732
1734
1736
1738
1740
1742
1744
1746
1748
1750
1752
1754
1756
1758
1760
1762
1764
1766
1768
1770
1772
1774
1776
1778
1780
1782
1784
1786
1788
1790
1792
1794
1796
1798
1800
1802
1804
1806
1808
1810
1812
1814
1816
1818
1820
1822
1824
1826
1828
1830
1832
1834
1836
1838
1840
1842
1844
1846
1848
1850
1852
1854
1856
1858
1860
1862
1864
1866
1868
1870
1872
1874
1876
1878
1880
1882
1884
1886
1888
1890
1892
1894
1896
1898
1900
1902
1904
1906
1908
1910
1912
1914
1916
1918
1920
1922
1924
1926
1928
1930
1932
1934
1936
1938
1940
1942
1944
1946
1948
1950
1952
1954
1956
1958
1960
1962
1964
1966
1968
1970
1972
1974
1976
1978
1980
1982
1984
1986
1988
1990
1992
1994
1996
1998
2000
2002
2004
2006
2008
2010
2012
2014
2016
2018
2020
2022
2024
2026
2028
2030
2032
2034
2036
2038
2040
2042
2044
2046
2048
2050
2052
2054
2056
2058
2060
2062
2064
2066
2068
2070
2072
2074
2076
2078
2080
2082
2084
2086
2088
2090
2092
2094
2096
2098
2100
2102
2104
2106
2108
2110
2112
2114
2116
2118
2120
2122
2124
2126
2128
2130
2132
2134
2136
2138
2140
2142
2144
2146
2148
2150
2152
2154
2156
2158
2160
2162
2164
2166
2168
2170
2172
2174
2176
2178
2180
2182
2184
2186
2188
2190
2192
2194
2196
2198
2200
2202
2204
2206
2208
2210
2212
2214
2216
2218
2220
2222
2224
2226
2228
2230
2232
2234
2236
2238
2240
2242
2244
2246
2248
2250
2252
2254
2256
2258
2260
2262
2264
2266
2268
2270
2272
2274
2276
2278
2280
2282
2284
2286
2288
2290
2292
2294
2296
2298
2300
2302
2304
2306
2308
2310
2312
2314
2316
2318
2320
2322
2324
2326
2328
2330
2332
2334
2336
2338
2340
2342
2344
2346
2348
2350
2352
2354
2356
2358
2360
2362
2364
2366
2368
2370
2372
2374
2376
2378
2380
2382
2384
2386
2388
2390
2392
2394
2396
2398
2400
2402
2404
2406
2408
2410
2412
2414
2416
2418
2420
2422
2424
2426
2428
2430
2432
2434
2436
2438
2440
2442
2444
2446
2448
2450
2452
2454
2456
2458
2460
2462
2464
2466
2468
2470
2472
2474
2476
2478
2480
2482
2484
2486
2488
2490
2492
2494
2496
2498
2500
2502
2504
2506
2508
2510
2512
2514
2516
2518
2520
2522
2524
2526
2528
2530
2532
2534
2536
2538
2540
2542
2544
2546
2548
2550
2552
2554
2556
2558
2560
2562
2564
2566
2568
2570
2572
2574
2576
2578
2580
2582
2584
2586
2588
2590
2592
2594
2596
2598
2600
2602
2604
2606
2608
2610
2612
2614
2616
2618
2620
2622
2624
2626
2628
2630
2632
2634
2636
2638
2640
2642
2644
2646
2648
2650
2652
2654
2656
2658
2660
2662
2664
2666
2668
2670
2672
2674
2676
2678
2680
2682
2684
2686
2688
2690
2692
2694
2696
2698
2700
2702
2704
2706
2708
2710
2712
2714
2716
2718
2720
2722
2724
2726
2728
2730
2732
2734
2736
2738
2740
2742
2744
2746
2748
2750
2752
2754
2756
2758
2760
2762
2764
2766
2768
2770
2772
2774
2776
2778
2780
2782
2784
2786
2788
2790
2792
2794
2796
2798
2800
2802
2804
2806
2808
2810
2812
2814
2816
2818
2820
2822
2824
2826
2828
2830
2832
2834
2836
2838
2840
2842
2844
2846
2848
2850
2852
2854
2856
2858
2860
2862
2864
2866
2868
2870
2872
2874
2876
2878
2880
2882
2884
2886
2888
2890
2892
2894
2896
2898
2900
2902
2904
2906
2908
2910
2912
2914
2916
2918
2920
2922
2924
2926
2928
2930
2932
2934
2936
2938
2940
2942
2944
2946
2948
2950
2952
2954
2956
2958
2960
2962
2964
2966
2968
2970
2972
2974
2976
2978
2980
2982
2984
2986
2988
2990
2992
2994
2996
2998
3000
3002
3004
3006
3008
3010
3012
3014
3016
3018
3020
3022
3024
3026
3028
3030
3032
3034
3036
3038
3040
3042
3044
3046
3048
3050
3052
3054
3056
3058
3060
3062
3064
3066
3068
3070
3072
3074
3076
3078
3080
3082
3084
3086
3088
3090
3092
3094
3096
3098
3100
3102
3104
3106
3108
3110
3112
3114
3116
3118
3120
3122
3124
3126
3128
3130
3132
3134
3136
3138
3140
3142
3144
3146
3148
3150
3152
3154
3156
3158
3160
3162
3164
3166
3168
3170
3172
3174
3176
3178
3180
3182
3184
3186
3188
3190
3192
3194
3196
3198
3200
3202
3204
3206
3208
3210
3212
3214
3216
3218
3220
3222
3224
3226
3228
3230
3232
3234
3236
3238
3240
3242
3244
3246
3248
3250
3252
3254
3256
3258
3260
3262
3264
3266
3268
3270
3272
3274
3276
3278
3280
3282
3284
3286
3288
3290
3292
3294
3296
3298
3300
3302
3304
3306
3308
3310
3312
3314
3316
3318
3320
3322
3324
3326
3328
3330
3332
3334
3336
3338
3340
3342
3344
3346
3348
3350
3352
3354
3356
3358
3360
3362
3364
3366
3368
3370
3372
3374
3376
3378
3380
3382
3384
3386
3388
3390
3392
3394
3396
3398
3400
3402
3404
3406
3408
3410
3412
3414
3416
3418
3420
3422
3424
3426
3428
3430
3432
3434
3436
3438
3440
3442
3444
3446
3448
3450
3452
3454
3456
3458
3460
3462
3464
3466
3468
3470
3472
3474
3476
3478
3480
3482
3484
3486
3488
3490
3492
3494
3496
3498
3500
3502
3504
3506
3508
3510
3512
3514
3516
3518
3520
3522
3524
3526
3528
3530
3532
3534
3536
3538
3540
3542
3544
3546
3548
3550
3552
3554
3556
3558
3560
3562
3564
3566
3568
3570
3572
3574
3576
3578
3580
3582
3584
3586
3588
3590
3592
3594
3596
3598
3600
3602
3604
3606
3608
3610
3612
3614
3616
3618
3620
3622
3624
3626
3628
3630
3632
3634
3636
3638
3640
3642
3644
3646
3648
3650
3652
3654
3656
3658
3660
3662
3664
3666
3668
3670
3672
3674
3676
3678
3680
3682
3684
3686
3688
3690
3692
3694
3696
3698
3700
3702
3704
3706
3708
3710
3712
3714
3716
3718
3720
3722
3724
3726
3728
3730
3732
3734
3736
3738
3740
3742
3744
3746
3748
3750
3752
3754
3756
3758
3760
3762
3764
3766
3768
3770
3772
3774
3776
3778
3780
3782
3784
3786
3788
3790
3792
3794
3796
3798
3800
3802
3804
3806
3808
3810
3812
3814
3816
3818
3820
3822
3824
3826
3828
3830
3832
3834
3836
3838
3840
3842
3844
3846
3848
3850
3852
3854
3856
3858
3860
3862
3864
3866
3868
3870
3872
3874
3876
3878
3880
3882
3884
3886
3888
3890
3892
3894
3896
3898
3900
3902
3904
3906
3908
3910
3912
3914
3916
3918
3920
3922
3924
3926
3928
3930
3932
3934
3936
3938
3940
3942
3944
3946
3948
3950
3952
3954
3956
3958
3960
3962
3964
3966
3968
3970
3972
3974
3976
3978
3980
3982
3984
3986
3988
3990
3992
3994
3996
3998
4000
4002
4004
4006
4008
4010
4012
4014
4016
4018
4020
4022
4024
4026
4028
4030
4032
4034
4036
4038
4040
4042
4044
4046
4048
4050
4052
4054
4056
4058
4060
4062
4064
4066
4068
4070
4072
4074
4076
4078
4080
4082
4084
4086
4088
4090
4092
4094
4096
4098
4100
4102
4104
4106
4108
4110
4112
4114
4116
4118
4120
4122
4124
4126
4128
4130
4132
4134
4136
4138
4140
4142
4144
4146
4148
4150
4152
4154
4156
4158
4160
4162
4164
4166
4168
4170
4172
4174
4176
4178
4180
4182
4184
4186
4188
4190
4192
4194
4196
4198
4200
4202
4204
4206
4208
4210
4212
4214
4216
4218
4220
4222
4224
4226
4228
4230
4232
4234
4236
4238
4240
4242
4244
4246
4248
4250
4252
4254
4256
4258
4260
4262
4264
4266
4268
4270
4272
4274
4276
4278
4280
4282
4284
4286
4288
4290
4292
4294
4296
4298
4300
4302
4304
4306
4308
4310
4312
4314
4316
4318
4320
4322
4324
4326
4328
4330
4332
4334
4336
4338
4340
4342
4344
4346
4348
4350
4352
4354
4356
4358
4360
4362
4364
4366
4368
4370
4372
4374
4376
4378
4380
4382
4384
4386
4388
4390
4392
4394
4396
4398
4400
4402
4404
4406
4408
4410
4412
4414
4416
4418
4420
4422
4424
4426
4428
4430
4432
4434
4436
4438
4440
4442
4444
4446
4448
4450
4452
4454
4456
4458
4460
4462
4464
4466
4468
4470
4472
4474
4476
4478
4480
4482
4484
4486
4488
4490
4492
4494
4496
4498
4500
4502
4504
4506
4508
4510
4512
4514
4516
4518
4520
4522
4524
4526
4528
4530
4532
4534
4536
4538
4540
4542
4544
4546
4548
4550
4552
4554
4556
4558
4560
4562
4564
4566
4568
4570
4572
4574
4576
4578
4580
4582
4584
4586
4588
4590
4592
4594
4596
4598
4600
4602
4604
4606
4608
4610
4612
4614
4616
4618
4620
4622
4624
4626
4628
4630
4632
4634
4636
4638
4640
4642
4644
4646
4648
4650
4652
4654
4656
4658
4660
4662
4664
4666
4668
4670
4672
4674
4676
4678
4680
4682
4684
4686
4688
4690
4692
4694
4696
4698
4700
4702
4704
4706
4708
4710
4712
4714
4716
4718
4720
4722
4724
4726
4728
4730
4732
4734
4736
4738
4740
4742
4744
4746
4748
4750
4752
4754
4756
4758
4760
4762
4764
4766
4768
4770
4772
4774
4776
4778
4780
4782
4784
4786
4788
4790
4792
4794
4796
4798
4800
4802
4804
4806
4808
4810
4812
4814
4816
4818
4820
4822
4824
4826
4828
4830
4832
4834
4836
4838
4840
4842
4844
4846
4848
4850
4852
4854
4856
4858
4860
4862
4864
4866
4868
4870
4872
4874
4876
4878
4880
4882
4884
4886
4888
4890
4892
4894
4896
4898
4900
4902
4904
4906
4908
4910
4912
4914
4916
4918
4920
4922
4924
4926
4928
4930
4932
4934
4936
4938
4940
4942
4944
4946
4948
4950
4952
4954
4956
4958
4960
4962
4964
4966
4968
4970
4972
4974
4976
4978
4980
4982
4984
4986
4988
4990
4992
4994
4996
4998
5000
5002
5004
5006
5008
5010
5012
5014
5016
5018
5020
5022
5024
5026
5028
5030
5032
5034
5036
5038
5040
5042
5044
5046
5048
5050
5052
5054
5056
5058
5060
5062
5064
5066
5068
5070
5072
5074
5076
5078
5080
5082
5084
5086
5088
5090
5092
5094
5096
5098
5100
5102
5104
5106
5108
5110
5112
5114
5116
5118
5120
5122
5124
5126
5128
5130
5132
5134
5136
5138
5140
5142
5144
5146
5148
5150
5152
5154
5156
5158
5160
5162
5164
5166
5168
5170
5172
5174
5176
5178
5180
5182
5184
5186
5188
5190
5192
5194
5196
5198
5200
5202
5204
5206
5208
5210
5212
5214
5216
5218
5220
5222
5224
5226
5228
5230
5232
5234
5236
5238
5240
5242
5244
5246
5248
5250
5252
5254
5256
5258
5260
5262
5264
5266
5268
5270
5272
5274
5276
5278
5280
5282
5284
5286
5288
5290
5292
5294
5296
5298
5300
5302
5304
5306
5308
5310
5312
5314
5316
5318
5320
5322
5324
5326
5328
5330
5332
5334
5336
5338
5340
5342
5344
5346
5348
5350
5352
5354
5356
5358
5360
5362
5364
5366
5368
5370
5372
5374
5376
5378
5380
5382
5384
5386
5388
5390
5392
5394
5396
5398
5400
5402
5404
5406
5408
5410
5412
5414
5416
5418
5420
5422
5424
5426
5428
5430
5432
5434
5436
5438
5440
5442
5444
5446
5448
5450
5452
5454
5456
5458
5460
5462
5464
5466
5468
5470
5472
5474
5476
5478
5480
5482
5484
5486
5488
5490
5492
5494
5496
5498
5500
5502
5504
5506
5508
5510
5512
5514
5516
5518
5520
5522
5524
5526
5528
5530
5532
5534
5536
5538
5540
5542
5544
5546
5548
5550
5552
5554
5556
5558
5560
5562
5564
5566
5568
5570
5572
5574
5576
5578
5580
5582
5584
5586
5588
5590
5592
5594
5596
5598
5600
5602
5604
5606
5608
5610
5612
5614
5616
5618
5620
5622
5624
5626
5628
5630
5632
5634
5636
5638
5640
5642
5644
5646
5648
5650
5652
5654
5656
5658
5660
5662
5664
5666
5668
5670
5672
5674
5676
5678
5680
5682
5684
5686
5688
5690
5692
5694
5696
5698
5700
5702
5704
5706
5708
5710
5712
5714
5716
5718
5720
5722
5724
5726
5728
5730
5732
5734
5736
5738
5740
5742
5744
5746
5748
5750
5752
5754
5756
5758
5760
5762
5764
5766
5768
5770
5772
5774
5776
5778
5780
5782
5784
5786
5788
5790
5792
5794
5796
5798
5800
5802
5804
5806
5808
5810
5812
5814
5816
5818
5820
5822
5824
5826
5828
5830
5832
5834
5836
5838
5840
5842
5844
5846
5848
5850
5852
5854
5856
5858
5860
5862
5864
5866
5868
5870
5872
5874
5876
5878
5880
5882
5884
5886
5888
5890
5892
5894
5896
5898
5900
5902
5904
5906
5908
5910
5912
5914
5916
5918
5920
5922
5924
5926
5928
5930
5932
5934
5936
5938
5940
5942
5944
5946
5948
5950
5952
5954
5956
5958
5960
5962
5964
5966
5968
5970
5972
5974
5976
5978
5980
5982
5984
5986
5988
5990
5992
5994
5996
5998
6000
6002
6004
6006
6008
6010
6012
6014
6016
6018
6020
6022
6024
6026
6028
6030
6032
6034
6036
6038
6040
6042
6044
6046
6048
6050
6052
6054
6056
6058
6060
6062
6064
6066
6068
6070
6072
6074
6076
6078
6080
6082
6084
6086
6088
6090
6092
6094
6096
6098
6100
6102
6104
6106
6108
6110
6112
6114
6116
6118
6120
6122
6124
6126
6128
6130
6132
6134
6136
6138
6140
6142
6144
6146
6148
6150
6152
6154
6156
6158
6160
6162
6164
6166
6168
6170
6172
6174
6176
6178
6180
6182
6184
6186
6188
6190
6192
6194
6196
6198
6200
6202
6204
6206
6208
6210
6212
6214
6216
6218
6220
6222
6224
6226
6228
6230
6232
6234
6236
6238
6240
6242
6244
6246
6248
6250
6252
6254
6256
6258
6260
6262
6264
6266
6268
6270
6272
6274
6276
6278
6280
6282
6284
6286
6288
6290
6292
6294
6296
6298
6300
6302
6304
6306
6308
6310
6312
6314
6316
6318
6320
6322
6324
6326
6328
6330
6332
6334
6336
6338
6340
6342
6344
6346
6348
6350
6352
6354
6356
6358
6360
6362
6364
6366
6368
6370
6372
6374
6376
6378
6380
6382
6384
6386
6388
6390
6392
6394
6396
6398
6400
6402
6404
6406
6408
6410
6412
6414
6416
6418
6420
6422
6424
6426
6428
6430
6432
6434
6436
6438
6440
6442
6444
6446
6448
6450
6452
6454
6456
6458
6460
6462
6464
6466
6468
6470
6472
6474
6476
6478
6480
6482
6484
6486
6488
6490
6492
6494
6496
6498
6500
6502
6504
6506
6508
6510
6512
6514
6516
6518
6520
6522
6524
6526
6528
6530
6532
6534
6536
6538
6540
6542
6544
6546
6548
6550
6552
6554
6556
6558
6560
6562
6564
6566
6568
6570
6572
6574
6576
6578
6580
6582
6584
6586
6588
6590
6592
6594
6596
6598
6600
6602
6604
6606
6608
6610
6612
6614
6616
6618
6620
6622
6624
6626
6628
6630
6632
6634
6636
6638
6640
6642
6644
6646
6648
6650
6652
6654
6656
6658
6660
6662
6664
6666
6668
6670
6672
6674
6676
6678
6680
6682
6684
6686
6688
6690
6692
6694
6696
6698
6700
6702
6704
6706
6708
6710
6712
6714
6716
6718
6720
6722
6724
6726
6728
6730
6732
6734
6736
6738
6740
6742
6744
6746
6748
6750
6752
6754
6756
6758
6760
6762
6764
6766
6768
6770
6772
6774
6776
6778
6780
6782
6784
6786
6788
6790
6792
6794
6796
6798
6800
6802
6804
6806
6808
6810
6812
6814
6816
6818
6820
6822
6824
6826
6828
6830
6832
6834
6836
6838
6840
6842
6844
6846
6848
6850
6852
6854
6856
6858
6860
6862
6864
6866
6868
6870
6872
6874
6876
6878
6880
6882
6884
6886
6888
6890
6892
6894
6896
6898
6900
6902
6904
6906
6908
6910
6912
6914
6916
6918
6920
6922
6924
6926
6928
6930
6932
6934
6936
6938
6940
6942
6944
6946
6948
6950
6952
6954
6956
6958
6960
6962
6964
6966
6968
6970
6972
6974
6976
6978
6980
6982
6984
6986
6988
6990
6992
6994
6996
6998
7000
7002
7004
7006
7008
7010
7012
7014
7016
7018
7020
7022
7024
7026
7028
7030
7032
7034
7036
7038
7040
7042
7044
7046
7048
7050
7052
7054
7056
7058
7060
7062
7064
7066
7068
7070
7072
7074
7076
7078
7080
7082
7084
7086
7088
7090
7092
7094
7096
7098
7100
7102
7104
7106
7108
7110
7112
7114
7116
7118
7120
7122
7124
7126
7128
7130
7132
7134
7136
7138
7140
7142
7144
7146
7148
7150
7152
7154
7156
7158
7160
7162
7164
7166
7168
7170
7172
7174
7176
7178
7180
7182
7184
7186
7188
7190
7192
7194
7196
7198
7200
7202
7204
7206
7208
7210
7212
7214
7216
7218
7220
7222
7224
7226
7228
7230
7232
7234
7236
7238
7240
7242
7244
7246
7248
7250
7252
7254
7256
7258
7260
7262
7264
7266
7268
7270
7272
7274
7276
7278
7280
7282
7284
7286
7288
7290
7292
7294
7296
7298
7300
7302
7304
7306
7308
7310
7312
7314
7316
7318
7320
7322
7324
7326
7328
7330
7332
7334
7336
7338
7340
7342
7344
7346
7348
7350
7352
7354
7356
7358
7360
7362
7364
7366
7368
7370
7372
7374
7376
7378
7380
7382
7384
7386
7388
7390
7392
7394
7396
7398
7400
7402
7404
7406
7408
7410
7412
7414
7416
7418
7420
7422
7424
7426
7428
7430
7432
7434
7436
7438
7440
7442
7444
7446
7448
7450
7452
7454
7456
7458
7460
7462
7464
7466
7468
7470
7472
7474
7476
7478
7480
7482
7484
7486
7488
7490
7492
7494
7496
7498
7500
7502
7504
7506
7508
7510
7512
7514
7516
7518
7520
7522
7524
7526
7528
7530
7532
7534
7536
7538
7540
7542
7544
7546
7548
7550
7552
7554
7556
7558
7560
7562
7564
7566
7568
7570
7572
7574
7576
7578
7580
7582
7584
7586
7588
7590
7592
7594
7596
7598
7600
7602
7604
7606
7608
7610
7612
7614
7616
7618
7620
7622
7624
7626
7628
7630
7632
7634
7636
7638
7640
7642
7644
7646
7648
7650
7652
7654
7656
7658
7660
7662
7664
7666
7668
7670
7672
7674
7676
7678
7680
7682
7684
7686
7688
7690
7692
7694
7696
7698
7700
7702
7704
7706
7708
7710
7712
7714
7716
7718
7720
7722
7724
7726
7728
7730
7732
7734
7736
7738
7740
7742
7744
7746
7748
7750
7752
7754
7756
7758
7760
7762
7764
7766
7768
7770
7772
7774
7776
7778
7780
7782
7784
7786
7788
7790
7792
7794
7796
7798
7800
7802
7804
7806
7808
7810
7812
7814
7816
7818
7820
7822
7824
7826
7828
7830
7832
7834
7836
7838
7840
7842
7844
7846
7848
7850
7852
7854
7856
7858
7860
7862
7864
7866
7868
7870
7872
7874
7876
7878
7880
7882
7884
7886
7888
7890
7892
7894
7896
7898
7900
7902
7904
7906
7908
7910
7912
7914
7916
7918
7920
7922
7924
7926
7928
7930
7932
7934
7936
7938
7940
7942
7944
7946
7948
7950
7952
7954
7956
7958
7960
7962
7964
7966
7968
7970
7972
7974
7976
7978
7980
7982
7984
7986
7988
7990
7992
7994
7996
7998
8000
8002
8004
8006
8008
8010
8012
8014
8016
8018
8020
8022
8024
8026
8028
8030
8032
8034
8036
8038
8040
8042
8044
8046
8048
8050
8052
8054
8056
8058
8060
8062
8064
8066
8068
8070
8072
8074
8076
8078
8080
8082
8084
8086
8088
8090
8092
8094
8096
8098
8100
8102
8104
8106
8108
8110
8112
8114
8116
8118
8120
8122
8124
8126
8128
8130
8132
8134
8136
8138
8140
8142
8144
8146
8148
8150
8152
8154
8156
8158
8160
8162
8164
8166
8168
8170
8172
8174
8176
8178
8180
8182
8184
8186
8188
8190
8192
8194
8196
8198
8200
8202
8204
8206
8208
8210
8212
8214
8216
8218
8220
8222
8224
8226
8228
8230
8232
8234
8236
8238
8240
8242
8244
8246
8248
8250
8252
8254
8256
8258
8260
8262
8264
8266
8268
8270
8272
8274
8276
8278
8280
8282
8284
8286
8288
8290
8292
8294
8296
8298
8300
8302
8304
8306
8308
8310
8312
8314
8316
8318
8320
8322
8324
8326
8328
8330
8332
8334
8336
8338
8340
8342
8344
8346
8348
8350
8352
8354
8356
8358
8360
8362
8364
8366
8368
8370
8372
8374
8376
8378
8380
8382
8384
8386
8388
8390
8392
8394
8396
8398
8400
8402
8404
8406
8408
8410
8412
8414
8416
8418
8420
8422
8424
8426
8428
8430
8432
8434
8436
8438
8440
8442
8444
8446
8448
8450
8452
8454
8456
8458
8460
8462
8464
8466
8468
8470
8472
8474
8476
8478
8480
8482
8484
8486
8488
8490
8492
8494
8496
8498
8500
8502
8504
8506
8508
8510
8512
8514
8516
8518
8520
8522
8524
8526
8528
8530
8532
8534
8536
8538
8540
8542
8544
8546
8548
8550
8552
8554
8556
8558
8560
8562
8564
8566
8568
8570
8572
8574
8576
8578
8580
8582
8584
8586
8588
8590
8592
8594
8596
8598
8600
8602
8604
8606
8608
8610
8612
8614
8616
8618
8620
8622
8624
8626
8628
8630
8632
8634
8636
8638
8640
8642
8644
8646
8648
8650
8652
8654
8656
8658
8660
8662
8664
8666
8668
8670
8672
8674
8676
8678
8680
8682
8684
8686
8688
8690
8692
8694
8696
8698
8700
8702
8704
8706
8708
8710
8712
8714
8716
8718
8720
8722
8724
8726
8728
8730
8732
8734
8736
8738
8740
8742
8744
8746
8748
8750
8752
8754
8756
8758
8760
8762
8764
8766
8768
8770
8772
8774
8776
8778
8780
8782
8784
8786
8788
8790
8792
8794
8796
8798
8800
8802
8804
8806
8808
8810
8812
8814
8816
8818
8820
8822
8824
8826
8828
8830
8832
8834
8836
8838
8840
8842
8844
8846
8848
8850
8852
8854
8856
8858
8860
8862
8864
8866
8868
8870
8872
8874
8876
8878
8880
8882
8884
8886
8888
8890
8892
8894
8896
8898
8900
8902
8904
8906
8908
8910
8912
8914
8916
8918
8920
8922
8924
8926
8928
8930
8932
8934
8936
8938
8940
8942
8944
8946
8948
8950
8952
8954
8956
8958
8960
8962
8964
8966
8968
8970
8972
8974
8976
8978
8980
8982
8984
8986
8988
8990
8992
8994
8996
8998
9000
9002
9004
9006
9008
9010
9012
9014
9016
9018
9020
9022
9024
9026
9028
9030
9032
9034
9036
9038
9040
9042
9044
9046
9048
9050
9052
9054
9056
9058
9060
9062
9064
9066
9068
9070
9072
9074
9076
9078
9080
9082
9084
9086
9088
9090
9092
9094
9096
9098
9100
9102
9104
9106
9108
9110
9112
9114
9116
9118
9120
9122
9124
9126
9128
9130
9132
9134
9136
9138
9140
9142
9144
9146
9148
9150
9152
9154
9156
9158
9160
9162
9164
9166
9168
9170
9172
9174
9176
9178
9180
9182
9184
9186
9188
9190
9192
9194
9196
9198
9200
9202
9204
9206
9208
9210
9212
9214
9216
9218
9220
9222
9224
9226
9228
9230
9232
9234
9236
9238
9240
9242
9244
9246
9248
9250
9252
9254
9256
9258
9260
9262
9264
9266
9268
9270
9272
9274
9276
9278
9280
9282
9284
9286
9288
9290
9292
9294
9296
9298
9300
9302
9304
9306
9308
9310
9312
9314
9316
9318
9320
9322
9324
9326
9328
9330
9332
9334
9336
9338
9340
9342
9344
9346
9348
9350
9352
9354
9356
9358
9360
9362
9364
9366
9368
9370
9372
9374
9376
9378
9380
9382
9384
9386
9388
9390
9392
9394
9396
9398
9400
9402
9404
9406
9408
9410
9412
9414
9416
9418
9420
9422
9424
9426
9428
9430
9432
9434
9436
9438
9440
9442
9444
9446
9448
9450
9452
9454
9456
9458
9460
9462
9464
9466
9468
9470
9472
9474
9476
9478
9480
9482
9484
9486
9488
9490
9492
9494
9496
9498
9500
9502
9504
9506
9508
9510
9512
9514
9516
9518
9520
9522
9524
9526
9528
9530
9532
9534
9536
9538
9540
9542
9544
9546
9548
9550
9552
9554
9556
9558
9560
9562
9564
9566
9568
9570
9572
9574
9576
9578
9580
9582
9584
9586
9588
9590
9592
9594
9596
9598
9600
9602
9604
9606
9608
9610
9612
9614
9616
9618
9620
9622
9624
9626
9628
9630
9632
9634
9636
9638
9640
9642
9644
9646
9648
9650
9652
9654
9656
9658
9660
9662
9664
9666
9668
9670
9672
9674
9676
9678
9680
9682
9684
9686
9688
9690
9692
9694
9696
9698
9700
9702
9704
9706
9708
9710
9712
9714
9716
9718
9720
9722
9724
9726
9728
9730
9732
9734
9736
9738
9740
9742
9744
9746
9748
9750
9752
9754
9756
9758
9760
9762
9764
9766
9768
9770
9772
9774
9776
9778
9780
9782
9784
9786
9788
9790
9792
9794
9796
9798
9800
9802
9804
9806
9808
9810
9812
9814
9816
9818
9820
9822
9824
9826
9828
9830
9832
9834
9836
9838
9840
9842
9844
9846
9848
9850
9852
9854
9856
9858
9860
9862
9864
9866
9868
9870
9872
9874
9876
9878
9880
9882
9884
9886
9888
9890
9892
9894
9896
9898
9900
9902
9904
9906
9908
9910
9912
9914
9916
9918
9920
9922
9924
9926
9928
9930
9932
9934
9936
9938
9940
9942
9944
9946
9948
9950
9952
9954
9956
9958
9960
9962
9964
9966
9968
9970
9972
9974
9976
9978
9980
9982
9984
9986
9988
9990
9992
9994
9996
9998
10000

BRICKER & ECKLER
100 SOUTH THIRD STREET
COLUMBUS, OHIO 43215-4291

TELEPHONE (614) 227-2300
FAX (614) 227-2390

WRITER'S DIRECT DIAL NUMBER

227-2378

June 8, 1990

TELECOPIED

Louise Gross, Esq.
Assistant Regional Counsel
Region V
U. S. Environmental
Protection Agency
230 South Dearborn Street
Chicago, Illinois 60604

Re: Docket No. TSCA-V-C-05-90
Settlement Proposal

Dear Louise:

Over the past two months we have had an extensive sampling program performed at the Columbus Scrap Corporation facility to identify the extent of PCB's in the area that the capacitors were discovered. Based upon the testing that was done at the site to date, we would make the following proposal for cleanup.

At the outset, it is our opinion that this area is inaccessible to the general public; therefore a twenty-five part per million cleanup level should be established for the site. The area of the site where the capacitors were discovered is not near any access roads that would be utilized by the general public, and is in a very desolate rail area which is only traversed by workers on locomotive-driven magnetic cranes. It is improbable that anyone from the general public would ever be in this area or have access to it. There are fences and walls around the majority of the site that is adjacent to any types of public access. The back portion of the facility is bounded by many acres of railroad tracks and is a approximately one quarter

mile away from the nearest public thoroughfare. There is also security on site at all hours when the facility is not operating. We believe that the site would qualify under the definition of "other restricted access locations". (40 C.F.R. Section 761.123) Therefore, we believe that the twenty-five parts per million cleanup level is appropriate.

It is our intention to cleanup the areas that have tested greater than twenty-five parts per million to a depth and circumference around the test point to provide cleanup below the twenty-five parts per million level. Appropriate post-cleanup testing will be utilized to insure that the area has been cleaned to the twenty-five parts per million level. Prior to disposal the material will be tested and deposited in an appropriate facility. The cleanup and disposal will be provided by Chemical Waste Management, Inc. Post testing results will be submitted to U. S. EPA for your scrutiny.

The attached exhibits, although not to scale, represent the grid testing that was done at the alleged spill site. We propose the following cleanup program.

? 1. In area one we will remove a 2-foot diameter to a 12 foot depth around test point 1B.

2. In area two and three we will remove test points 2A through 2G and 3A, 3G, 3E, and 3F at the perimeter of the grid points to a depth of 18". We will further remove test points 3B, 3C and 3D and an area 2 feet in diameter of each of these test points to a depth of 36".

3. In area four we will remove test point 4A at a 2 foot diameter to a depth of 18". We will further remove test points 4B and 4G to a 2 foot diameter at a depth of 12".

4. In area five we will remove test points 5A, 5B, 5G, 5E, and 5F plus 2 foot outside of the perimeter to a depth of 24".

During excavation we will inspect for oily or discolored soils which would evidence the possibility of contaminated materials. Any evidence of contamination will be removed to insure that the cleanup is thorough.

Thank you for your prompt attention to this proposal. I will look forward to hearing from you in the near future on this matter.

Sincerely,

Kirk

Kirk N. Guy

KNG/vac
encl.

OHIO ENVIRONMENTAL PROTECTION AGENCY

TELEPHONE MEMORANDUM

11

WITH GARY REYNOLDS DATE 11/22/91

REPRESENTING COLUMBUS SCRAP TIME 11:30 a.m.

PERMIT NO. PHONE 228-1603

OEPA STAFF JEFF REYNOLDS

SUBJECT COLUMBUS SCRAP, I CALLED HIM TO ASK SOME QUESTIONS FOR THE PA.

NOTES & SUMMARY: FOLLOW-UP DATE

GARY SAID COLS. SCRAP TOOK OVER THE SITE IN 1985. HE SAID THEIR LEASE IS DAY TO DAY, WITH A 30 DAY NOTICE BY EITHER PARTY, WITH CSX. HE SAID THEY DON'T REALLY HAVE A CONTACT JUST SEND BILLS TO RAILROAD. FOR ENVIRONMENTAL THEY TALK TO MARK MURPHY OF CSX. TRY (904) 281-4006 - HE MIGHT HAVE THE REAL ESTATE INFO I WANT. KEN COHEN IS THE PRESIDENT OF COLS. SCRAP CORP. COLS SCRAP BOUGHT INVENTORY & ASSETS FROM SUMMER & CO. - ALL OUT OF BUSINESS. JOE SUMMER WAS CHAIRMAN, MAY BE IN PHONE BOOK, ON DAWSON AVE. IN BEXLEY. BOUGHT FROM HANDLERS IN 1981 - LEON HANDLER FROM BOCA RATON? HE SAID LIME(?) PILE BELONGS TO RR - ON CSX PROPERTY - BUT NOT ON LEASE PROPERTY - SOURCE UNKNOWN. RUSTY DRUMS ARE VERY OLD (HANDLER DAYS). SAYS DRUMS BROUGHT TO SITE EMPTY - REJECTS FROM COLS. STEEL DRUM. ALSO OFF THEIR PROPERTY. GARY HAS BEEN THERE SINCE 1981 - DRUMS WERE OLD THEN. ABOUT 30 EMPLOYEES. RAIN STAYS IN YARD, NO SEWERS ON SITE. PCB MATERIAL - TOOK OUT 3-15 yd^3 (≈40 yd^3) BOXES. TOOK THAT AMOUNT SOIL OUT TO REDUCE TESTING. WHEN TESTED FOR AT DUMP (DISPOSAL FACILITY) FOUND NO PCB IN TEST BOX. GR

Signature

OEPA-INDWW-3

— LEGEND —

Sanitary Sewers

Storm Sewers

Combined Sewers

Private Sanitary Sewers
Private San. Sewers Assigned to City

Private Storm Sewers
Private Storm Sewer Assigned to City

Private Combined Sewers
Private Combined Sewers Assigned to City

Abandoned Sewers - Sanitary

Storm — x — x Combined — x — x

Relief Sewers

Bulkhead in Sewers

Cone Top Inlets

All M.H.s Shown As Open Circle ○

All Catch Basin M.H.s Shown As Solid Circle ●

All Catch Basins Shown As Small Solid Circle •

County Record Plan Nos. Shown Thus - 278 c

Show Clean Out As A Small Open Circle & Mark C.O.

DATA INTERPRETATION

$\frac{8 \leftarrow .31}{746}$ = SIZE - DIRECTION OF FLOW - GRADE RECORD PLAN NO.

SHOW STREET GRADES AT AN ANGLE TO STREETS & INTERSECTIONS THUS



APPROVED
Nov. 18, 1946
May 9, 1949
July 23, 1969

LEGEND FOR 200' SCALE SEWER ATLAS

CITY OF COLUMBUS, OHIO
DEPARTMENT OF PUBLIC SERVICE
DIVISION OF ENGINEERING AND CONSTRUCTION

SCALE
1 INCH = 200'

DR. TR. | SHEET | FILE NO. AA-D.0



THIS MAP IS 64% REDUCTION OF ORIGINAL


RIVER ST.
FURNACE
ST.
CC-346
C. & O. R.R.
WHITTIER
ST.
SCIOTO
CC-300
FRA 70-12.3

Refer to the FLOOD INSURANCE RATE MAP EFFECTIVE date shown on this map to determine when actuarial rates apply to structures in the zones where elevations or depths have been established.

To determine if flood insurance is available in this community, contact your insurance agent, or call the National Flood Insurance Program, at (800) 638-6620.

APPROXIMATE SCALE

1000 0 1000 FEET

NATIONAL FLOOD INSURANCE PROGRAM

FIRM
FLOOD INSURANCE RATE MAP

CITY OF
COLUMBUS,
OHIO
FRANKLIN AND FAIRFIELD
COUNTIES

PANEL 15 OF 105
(SEE MAP INDEX FOR PANELS NOT PRINTED)

RECEIVED
NOV 07 1991
Ohio Environmental Protection Agency
CENTRAL DISTRICT OFFICE

COMMUNITY-PANEL NUMBER
390170 0015 B

EFFECTIVE DATE:
JULY 5, 1983

KEY TO MAP

13

500-Year Flood Boundary
100-Year Flood Boundary
Zone Designations*
100-Year Flood Boundary
500-Year Flood Boundary



Base Flood Elevation Line With Elevation In Feet** — 513

Base Flood Elevation in Feet Where Uniform Within Zone** — (EL 987)

Elevation Reference Mark — RM7×

Zone D Boundary

River Mile — •M1.5

**Referenced to the National Geodetic Vertical Datum of 1929

*EXPLANATION OF ZONE DESIGNATIONS

ZONE	EXPLANATION
A	Areas of 100-year flood; base flood elevations and flood hazard factors not determined.
A0	Areas of 100-year shallow flooding where depths are between one (1) and three (3) feet; average depths of inundation are shown, but no flood hazard factors are determined.
AH	Areas of 100-year shallow flooding where depths are between one (1) and three (3) feet; base flood elevations are shown, but no flood hazard factors are determined.
A1-A30	Areas of 100-year flood; base flood elevations and flood hazard factors determined.
A99	Areas of 100-year flood to be protected by flood protection system under construction; base flood elevations and flood hazard factors not determined.
B	Areas between limits of the 100-year flood and 500-year flood; or certain areas subject to 100-year flooding with average depths less than one (1) foot or where the contributing drainage area is less than one square mile; or areas protected by levees from the base flood. (Medium shading)
C	Areas of minimal flooding. (No shading)
D	Areas of undetermined, but possible, flood hazards.
V	Areas of 100-year coastal flood with velocity (wave action); base flood elevations and flood hazard factors not determined.
V1-V30	Areas of 100-year coastal flood with velocity (wave action); base flood elevations and flood hazard factors determined.

NOTES TO USER

Certain areas not in the special flood hazard areas (zones A and V) may be protected by flood control structures.

This map is for flood insurance purposes only; it does not necessarily show all areas subject to flooding in the community or all planimetric features outside special flood hazard areas.

For adjoining map panels, see separately printed Index To Map Panels.

INITIAL IDENTIFICATION:
AUGUST 9, 1974

FLOOD HAZARD BOUNDARY MAP REVISIONS:
FEBRUARY 3, 1978


ZONE B
ZONE B
Main Street Weir
2nd
ZONE C
FULTON
STREET
ZONE C
SHORT
STREET
MAIER PLACE
LIBERTY STREET
FURNACE STREET
ZONE B
CHESSIE
SYSTEM
SYCAMORE STREET
COLUMBUS
SCRAP
FRANKFORT
N
ZONE C
Whittier
St.
ZONE B
ZONE C
Greenlawn
Avenue
/Dam
SCIOTO
BOULEVARD

OHIO VIRONMENTAL PROTECTION AGENCY

TELEPHONE MEMORANDUM

WITH GARY REYNOLDS (VICE-PRES.) DATE 8-29-91

REPRESENTING COLUMBUS SCRAP TIME 3:50 p.m.

PERMIT NO. PHONE (614) 228 1603

OEPA STAFF JEFF REYNOLDS

SUBJECT COLS. SCRAP - 580 FURNACE ST., COLS.

PA QUESTIONS/OWNERSHIP

NOTES & SUMMARY: FOLLOW-UP DATE

GARY REYNOLDS SAID THEY'VE BEEN WORKING WITH THE USEPA. THREE WEEKS AGO STEVE RENNINGER HAD BEEN THERE SAMPLING AND THEY WERE BACK AGAIN YESTERDAY. HE CONFIRMED THE FOLLOWING SCRAP COMPANY OWNERSHIP (I GOT EARLIER FROM SHERYL GARRETT OF COLS. SCRAP):

50% COHEN BROS.
CONTACT: KEN COHEN
P.O. BOX 957
MIDDLETOWN, OH 45044
(513) 422-3696,

50% JOSEPHS (MUSKINGUM IRON & METAL)
CONTACT: JACK JOSEPH
P.O. BOX 2726
ZANESVILLE, OH 43702
(614) 452-9351

COLUMBUS SCRAP PURCHASED OPERATION (PROPERTY OWNED BY CSX) IN 1985.
FROM SUMMER AND COMPANY 1981-1985.
HANDLER'S AND COMPANY - STARTED IN 1940's?

Signature [signature]

OEPA-INDWW-3

OHIO ENVIRONMENTAL PROTECTION AGENCY

TELEPHONE MEMORANDUM

WITH MARK MURPHY DATE 12/4/91

REPRESENTING CSX TIME 9:30 a.m.

PERMIT NO. PHONE (904) 359-1651

OEPA STAFF JEFF REYNOLDS

SUBJECT COLUMBUS SCRAP / PA QUESTIONS (I CALLED HIM)

NOTES & SUMMARY: FOLLOW-UP DATE

LIME PILES - PARTLY ON THIS PROPERTY. PERHAPS ASSOCIATED WITH CONCRETE OR MAYBE SCALE FROM TRAIN STEAM BOILERS - BUT QUANTITY PROBABLY TOO HUGE FOR SCALE. HE'S NOT SURE ABOUT THE DRUMS - MAYBE ASSOCIATED W/ SCRAP OPERATIONS. HE THINKS HANDLER STARTED AROUND 1941 - MAYBE BEFORE. HE SAID I'LL HAVE TO PUT REQUEST FOR DEED / LEASE IN WRITING. HE SAID CLEANUP IS BASICALLY A 50/50 SPLIT OF COSTS BUT CSX HASN'T RECEIVED PAYMENT FROM COLS. SCRAP YET. COLS. SCRAP DID INITIAL REMOVAL OF PCB WASTES AND PAID FOR IT. HIS ADDRESS IS
CSX ENVIRONMENTAL
500 WATER ST.
JACKSONVILLE, FL 32202

Signature Jeff W. Reynolds

OEPA-INDWW-3


JACKSON
LAWRENCE
GALLIA
SCIOTO
MEIGS
Jackson
Gallipolis
Portsmouth
West Portsmouth
New Boston
Ironton
Middleport
Pomeroy
Chillicothe
Lake Jackson
Scioto River
Ohio River
Raccoon Creek
Salt Creek
Pine Creek
Symmes Creek
Guyan Creek
Leading Creek
Campaign Creek
Highland
Adams
Pike
Ross
Vinton
Gallia
Meigs
Lawrence
Scioto
Jefferson
Harrison
Belmont
Monroe
Washington
Morgan
Perry
Athens
Hocking
Fairfield
Franklin
Pickaway
Ross
Pike
Scioto
Lawrence
Gallia
Meigs
Vinton
Jackson


MARION
MORROW
DELAWARE
FRANKLIN
COLUMBUS
PICKAWAY
FAIRFIELD
HOCKING
Delaware
Mt Vernon
Westerville
Marion
Galloway
Lockbourne
Circleville
Lancaster
Logan
Washington C.H.
Bloomingburg
Williamsport
Ashville
Pickerington
Groveport
Grove City
Urbancrest
Hilliard
Dublin
Worthington
Gahanna
Reynoldsburg
Baltimore
Thurston
Basil
Pleasantville
Stoutsville
Ashville
Ringgold
Amanda
Five Points
Darbyville
Derby
Commercial Pt
South Bloomfield
Mt Sterling
Georgesville
Lilly Chapel
Plain City
Marysville
London
Mechanicsburg
Urbana
Bellefontaine
Kenton
Ada
Lima
Findlay
Fremont
Sandusky
Tiffin
Mansfield
Ashland
Wooster
Millersburg
Coshocton
Zanesville
Chillicothe
Circleville
Lancaster
Newark
Granville
Johnstown
Mt Liberty
Centerburg
Sparta
Galena
Sunbury
Delaware
Ashley
Radnor
Norton
Marion
Caledonia
Bellville
Loudonville
Mt Gilead
Cardington
Chesterville
Frederickstown
Fredonia
Utica
Martinsburg
Fallsburg
Chatham
Nexandria
Alexandria
Blacklick
Etna
Pickerington
Lockbourne
Ashville
Amanda
Ringgold
Stoutsville
Oakland
Rockbridge
Enterprise
Logan
Maxville
Sugar Grove
Tarlton

EXPLANATION

Features smaller than half a mile in maximum dimension shown in only a few places

Recent

Alluvium

Poorly sorted, poorly bedded silt and sand, generally less than 25 feet thick; individual layers are thin, lenticular, and nearly horizontal. Includes all detrital material deposited in valleys or undrained depressions since retreat of last glacier. In small undrained depressions such as kettle holes, consists of muck or peat. Commonly rests on sand and gravel outwash in larger valleys and on till in smaller valleys. May contain buried vegetation not more than 6,000 years old

Wisconsin

WATER-LAID DEPOSITS

Outwash

Composed of well-sorted sand and gravel, horizontally layered, commonly crossbedded. Smooth surfaces slope 5 to 50 feet per mile away from the glacier. Occurs as broadly spread "outwash plains" or restricted "valley trains," commonly preserved as terraces owing to postglacial erosion. Locally near the former ice margin includes kettle holes. Not shown more than a short distance south of the glacial boundary. Deposited by aggrading streams of melt water pouring from glacier. May have silt capping 0 to 2 feet thick and locally, on higher terraces, 5 feet thick

Kames and eskers

High, steep hummocks (kames) and long, sinuous ridges (eskers) composed almost entirely of bedded sand and gravel 10 to 200 feet or more thick. Materials range from coarse cobbles to fine sand. Formed in channels, tubes, or pits in the wasting glacier. Crossbedding and channel structures are common. Beds may dip 20° in any direction; dips steeper than this are usually associated with large boulders or embedded masses of till. Belts of kames (kame moraine) occur locally, chiefly in the Akron-Canton area. Locally a thin till cover indicates a subsequent readvance of the ice



Lacustrine (lake) deposits

Silt and clay, commonly laminated, in places covered by marl and peat. Range from 5 to 50 feet in thickness and commonly are underlain by till. Deposited in temporary lakes (including those in the Lake Erie basin) dammed to the north by retreating ice and to the south by bedrock "highs" or end moraines

ICE-LAID DEPOSITS



Ground moraine

Smooth-surfaced deposit of till ("hardpan") forming relatively flat land, except where it thinly caps broad, rolling hills near the glacial margin. Bedrock commonly is exposed in these marginal hills and in isolated localities elsewhere. Composed of an unsorted, unstratified mixture of clay, silt, sand, and coarser fragments deposited discontinuously by ice advancing over smoothed bedrock and older glacial deposits. Richer in clay in northern Ohio and in sand in southern Ohio. Till averages 50 feet in thickness in western Ohio and less than 25 feet in eastern Ohio; locally thickness may exceed 400 feet. May include several layers of till indicating successive ice advances; youngest till ranges in age from more than 24,000 years in northern Ohio to less than 18,000 years in southern Ohio. Leached of carbonates to depths of 1½ to 4 feet (locally 6 feet); in southern Ohio may be capped by 1 to 3 feet of silt (loess)

End moraine

Belts of sharply rolling or hummocky land, generally higher than adjoining land surface. Composed of till, an unsorted, unstratified mixture of clay, silt, sand, and coarser fragments, generally more than 100 feet thick, which may contain lenses or masses of stratified sand and gravel. Boulders and undrained depressions are common. End moraine was deposited along the roughly continuous edge of the glacier, mostly by sloughing off of till, and marks the position of the ice sheet during a halt or minor readvance

QUATERNARY

WATER-LAID DEPOSITS

the ice sheet during a halt or minor readvance

QUATE

41°

Pleistocene

Illinoian

WATER-LAID DEPOSITS

Outwash

Smooth-surfaced deposit of horizontally bedded sand and gravel, locally cemented, with a silt (loess) cap 2 to 10 feet thick. Soil developed on these deposits is yellow to red, clay rich, and leached of carbonates to depths of 8 to 15 feet. Outwash filled valleys and, where undissected by present streams, forms high, smooth, nearly flat surfaces; where dissected, outwash forms terrace remnants and rolling hills. Outwash was deposited by aggrading streams of melt water; a few filled kettle holes are faintly discernible. May include outwash of more than one period of deposition

Kames

High hummocks of bedded, moderately well to poorly sorted deposits ranging from fine sand to coarse cobbles; commonly crossbedded, with dips in all directions. Thick zones of gravel cemented by calcium carbonate are common. Soils developed in these deposits are red to yellow and leached of carbonates to depths of 5 to 15 feet. Kames were deposited in depressions in the wasting glacier

ICE-LAID DEPOSITS

Ground moraine

Rolling, smooth-surfaced deposit of till, changing to discontinuous till or only occasional erratics on bedrock hills. Till is generally less than 30 feet thick and is capped by silt (loess) 0 to 6 feet thick. A heavy glei soil (gumbotil) has been developed on the till, which is leached of its carbonates to depths of 6 to 14 feet in central and eastern Ohio and 5 to 8 feet in southwestern Ohio. Surface is characterized by well-integrated drainage, lacking closed depressions. Deposited by early ice sheet advancing over smoothed bedrock and older glacial deposits

End moraine

Hummocks composed mostly of silty till but including large masses of deeply weathered gravel. Closed depressions are lacking and boulders are rare. Recognized only in the terminal position of the glacier; removed by erosion in some areas

Illinoian and (or) older

WATER-LAID DEPOSITS

Lacustrine (lake) deposits

Gray laminated silt and clay, generally calcareous, 35 to 65 feet thick. Locally overlie red noncalcareous laminated clay that rests on red clay-rich noncalcareous sand. Overlain by fine sand, silt (loess), and (or) colluvial material. In many places dissected by deep gullies. Deposited in lakes formed in valleys of north-flowing streams dammed by the advance of an early glacier. Extensive deposits in the Teays valley and tributaries are known as the Minford silt

Kansan(?)

ICE-LAID DEPOSITS

Ground moraine

Till, 5 to 20 feet thick, entirely leached of carbonates at almost every exposure. Deposited by an early glacier, identified as Kansan(?) because of extreme depth of leaching and degree of weathering of deposits

GLACIAL FEATURES

Contact

Line marking boundary of a mapped deposit within a stage boundary

40°

Substage boundary

Limit of a significant advance or readvance of the ice edge, dashed where approximately located; may lie in either end moraine or ground moraine. Substage boundaries are based on (1) minor changes in the surface soil profile, (2) persistent differences in texture and (or) color of till consistent with regional stratigraphy as revealed in nearby exposures, (3) persistent differences in average thickness of loess cover, and (4) differences in extent of postglacial modification of glacial topography. Each substage boundary is believed to represent the position of the ice edge at the culmination of a substage



Fine-grained sand and silt at various depths in deeply buried valleys. Material generally contains water but it cannot be recovered except with difficulty. Wells are usually developed in scattered sand and gravel lenses above or below this material, or in the underlying bedrock.

LOCATION OF BEDROCK DATA

o
Wells from which bedrock data were obtained

Δ ⚒
Exposure or quarry in consolidated rock

——500——
Contour on the bedrock surface

MAP ILLUSTRATING

THE GROUND-WATER RESOURCES OF FRANKLIN COUNTY, OHIO

AND THE APPROXIMATE CONTOURS ON THE BEDROCK SURFACE

BY JAMES J. SCHMIDT

ALTITUDE IN FEET ABOVE SEA LEVEL

BEDROCK CONTOUR INTERVAL 50 FEET

TOPOGRAPHY FROM THE U.S. GEOLOGICAL SURVEY TOPOGRAPHIC MAPS OF THE DUBLIN, EAST COLUMBUS, LONDON, MILFORD CENTER, WEST COLUMBUS, AND WESTERVILLE QUADRANGLES. CONTOUR INTERVAL 10 FEET.

SCALE IN MILES

0 1 2 3 4

PUBLISHED BY
STATE OF OHIO
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF WATER
1958

BULLETIN 30 PLATE I

39° 50'

82°45'

82°40'

JK


COLUMBUS
Seagrave
Upper Arlington
CLINTON
US MILITARY LAND
REFUGEE TRACT
WATERWORKS
STATE HOSPITAL
INSTITUTE
FEEBLE MINDED
AVENUE
McCALVARY CEMETERY
GREENLAWN CEMETERY
NORTH BASE
Briggsdale
SEWAGE DISPOSAL PLANT
Marsh Run
MARION
Steelton
Bannon
Valley Crossing
Edward
Obetz
Bexley
SCIOTO RIVER
MILITARY
CANAL
HOCKING
NORFOLK
WESTERN
CREEK

82°45' 82°40'



EXPLANATION

AREAS IN WHICH THE PRINCIPAL SOURCES OF GROUND WATER ARE THE GLACIAL DEPOSITS

Best ground-water areas in Franklin County. Wells yield 1,000 gallons a minute or more from permeable sand and gravel deposits adjacent to the major perennial streams. Large sustained yields recharged by stream infiltration.

Regionally extensive permeable sand and gravel deposits not traversed by major streams. Yields of as much as 500 gallons a minute or more may be developed, although a test drilling program should be conducted to locate the coarser materials.

Shallow sand and gravel deposits traversed by a major stream. Yields of as much as 300 gallons a minute should be available from induced stream infiltration.

Interbedded sand and gravel deposits underlying thick till. Yields of as much as 200 gallons a minute may be obtained after extensive test drilling. Greater yields may be available during short periods of intermittent pumping. Yields of 350 gallons a minute have been reported.

40° 05'

Lenses of sand and gravel deposits interbedded in clayey till which overlies the shale bedrock. Yields of as much as 25 gallons a minute, sufficient for small industries, farm, and domestic supplies.

Irregular lenses of sand and gravel thinly scattered in thin to thick layers of glacial till which overlies impermeable Mississippian or Devonian shale. Yields of 5 to 10 gallons a minute, sufficient for farm and domestic use are available.

Thin glacial drift overlying impervious shale. Yields of as much as 5 gallons a minute from lenses of sand and gravel scattered irregularly throughout glacial drift. Yields of less than 2 gallons a minute may be expected where permeable materials are not encountered. Home owners commonly rely on dug wells and cisterns to supplement their supplies.

AREAS IN WHICH THE PRINCIPAL SOURCES OF GROUND WATER ARE THE DEVONIAN AND SILURIAN LIMESTONE AND DOLOMITE

Ground water obtained from Devonian and Silurian limestone and dolomite. Yields of as much as 175 gallons a minute may be expected from Devonian limestone. Cumulative yields up to 400 gallons a minute, may be obtained at greater depth, however, the degree of hardness, dissolved solids and sulphates increases. Hydrogen sulphide may or may not be present at depth.

Ground water obtained from permeable sand and gravel traversed by major streams. Depending upon the exact location, yields of as much as 250 gallons a minute or more may be expected. Cumulative yields of as much as 400 gallons a minute may be expected from wells developed in both sand and gravel deposits and the underlying limestone.

40° 00'

DGW
23

OIL SURVEY
OF
FRANKLIN COUNTY, OHIO

OHIO EPA
DWQMA



United States Department of Agriculture, Soil Conservation Service
in cooperation with
Ohio Department of Natural Resources, Division of Lands and Soil,
and Ohio Agricultural Research and Development Center

23

(Joins sheet 34)



(Joins sheet 47)

Mh - Soils potentially containing wetlands, none positively identified

23

(Joins sheet 31)



(Joins sheet 45)

23

R. 22 W.

(Joins sheet 3

(Joins sheet 52

23


R. 18 W.
Mh
ElB
ElD2
water
WdA
EmB
OcB
MlB
Up
Ut
HeE2
CeB
Ur
water
A
CrB
KeB
Ko
Kp
MlD2
MkB
KeC2
Rs
WeB
OcC2
Cc
Mh
H A M I L

23

Mh, EIB, MkB, Ee - Soils Potentially Containing Wetlands - No Wetlands Definite

23

R. 22 W.
Shadeville
water
water
PICKAWAY
MkB
CrA
KeB
CrB
CeB2
MlC2
HeE2
OcB
OcC2
WdA
WdB
Gn
ThA
SlA
ElD2
ElB
ElC2
EmB
CeA
Ee

24

DG-6

SOIL SURVEY OF

PICKAWAY COUNTY, OHIO



United States Department of Agriculture,
Soil Conservation Service, in cooperation with
Ohio Department of Natural Resources,
Division of Lands and Soil, and
Ohio Agricultural Research and Development C

COUNTY, OHIO — SHEET NUMBER 4 PICKAWAY COUNTY

Fe - soils potentially containing wetlands, none definite

MEETING NOTES

With: Jim Nottingham, Supvr From: Div. Public Drinking Water

OEPA Staff: Jeff Reynolds Division: DERR

Date: 12/18/91 Time: 2:00 p.m.

Subject: Source of City of Columbus' Water

Jim said Columbus draws their water from three sources:

-Scioto River (Dublin Road Water Treatment Plant)

-Hoover Reservoir, on Big Walnut Creek (Hap Cremean - formerly Morse Road - Water Treatment Plant)

-Groundwater Wells (Parsons Avenue Water Treatment Plant)

These wells and their distribution areas are shown on the attached map.

Jim also said there are no public drinking water intakes from the Scioto River in the Central District (includes Franklin and Pickaway counties) south of Columbus.

Columbus Water System
1989



Storage Tanks ●

1. Smoky Row Rd.
2. Busch Blvd.
3. Ulry Rd.
4. Morse Rd.
5. Henderson Rd.
6. Karl Rd.
7. Arlington
8. Hilliard-Rome Rd.
9. Westgate Park
10. Joyce Ave.
11. East Broad St.
12. Fairwood Ave.
13. Urbancrest
14. Grove City
15. Hilliard (3)

RECEIVED
JUL 31 1989

FRANKLIN
FRANKLIN
Lindberg Sch
Hilltonia Jr High Sch
St Agnes Sch
West Mound St Sch
Police Sta
Fire Sta
S Franklin Sch
Briggsdale
Childrens Home
County Home
Drive-in Theater
Trailer Park
East Franklin Sch
Finland Jr High Sch
Finland Sch
Wilson Sch
Central Point Shopping Center
Haunts Park
Baseball Park
Mt Calvary Cem
GREENLAWN CEMETERY
Mausoleum
Trailer Park
Columbus Workhouse
Sewage Disposal
SOUTHVIEW PARK
INTERCHANGE 105
INTERCHANGE 108
BALTIMORE
COLUMBUS
CORP BDY
BROWN ROAD
COLUMBUS ROAD
FRANKLIN ROAD
HOPKINS AVE
LINNET AVE
JACKSON RD
STIMMEL
SPRINGMONT AVE
WHEATLAND AVE
HIGHLAND AVE
SULLIVANT AVE
WHITEHORNE AVE
COLUMBIAN AVE
SAFFORD AVE
S WAYNE AVE
S EUREKA ROAD
Scioto
26


2 MILES
KINS AVE
BROWN
ast Franklin
ch
750
Section E
(298 to 425)
743
701
Finland
Jr High Sch
760
Finland
Sch
425
FRANK



St Leo Sch
MOLER
FREBIS
ST
AVE
JENKINS
MARKISON
Mercy Hosp
Southwood Sch
Lincoln Park Sch
Recreation Center
Park
WOODROW
Reeb Ave Sch
St Ladislaus Sch
Park
BM 739
BM 741
BM 738
Lockourne Rd Ch
Trailer Park
SMITH
ROAD
Smith Rd Sch
INNIS
REEB
Sub Sta
Trailer Park
Moler Sch
County Hospital
DRIVE
WESTERN
AVENUE
ALUM
Bannon
SOUTH
REFUGEE
BOUNDARY
T 5 N
T 4 N
CONRAIL
Mount Carmel Ch
ELWOOD
Agudas Achim Cem
Tifcreth Cem
Beth Jacob Cem
Koebel Sch
JONATHAN
OMAR
Marion-Franklin High Sch
Jr High Sch
Park
BM 746
BM 780
Watkins Sch
WATKINS
GROVEWOOD
DERING
DELRAY
Kian Run
CHESAPEAKE
GROVEPORT
CORR
ROAD
LOCKBOURNE
CULLMAN
SCHRYVER
ZIEGLER
Buckeye Jr High Sch
Fire Sta
Scioto Trail Sch
Drive-in Theater
AVENUE
SOUTHFIELD
Clarfield Sch
ORSON
NORFOLK
AND
PIPELINE
BM 771
BM 764
BM 766
Stockbridge Sch
Park
COLTON
Valley Crossing
Edward Station

OHIO ENVIRONMENTAL PROTECTION AGENCY

28

TELEPHONE MEMORANDUM

WITH GEORGE BRIDGES DATE 11/22/91

REPRESENTING OH. DATA USERS CENTER (OH. DEPT. OF DVLPMT.) TIME 11:05 a.m.

PERMIT NO. PHONE (614) 466-2115

OEPA STAFF JEFF REYNOLDS

SUBJECT FRANKLIN CO. CENSUS INFO.

NOTES & SUMMARY: FOLLOW-UP DATE

I ASKED HIM FOR THE AVERAGE NUMBER OF PEOPLE PER HOUSE IN FRANKLIN COUNTY (= 2.47) AND THE POPULATION DENSITY IN FRANKLIN COUNTY (= 1,780.4 PEOPLE/MILE^2).

Signature [illegible]

OEPA-INDWW-3

Water Resources Data
Ohio
Water Year 1990

Volume 1. Ohio River Basin
Excluding Project Data



U.S. GEOLOGICAL SURVEY WATER-DATA REPORT OH-90-2
Prepared in cooperation with the State of Ohio
and with other agencies

29

SCIOTO RIVER BASIN

03227500 SCIOTO RIVER AT COLUMBUS, OH

LOCATION.--Lat 39°54'34", long 83°00'33", Franklin County, Hydrologic Unit 05060001, on right bank at sewage-treatment plant of city of Columbus, 0.4 mi downstream from bridge on Frank Road, 2.8 mi upstream from Scioto Big Run, and 5 mi downstream from Olentangy River.

DRAINAGE AREA.--1,629 mi².

PERIOD OF RECORD.--October 1920 to current year. Monthly discharge only for some periods, published in WSP 1305.

REVISED RECORDS.--WSP 743: 1927(M). WSP 803: 1922-24, 1926-30, 1932-33. WSP 1908: Drainage area.

GAGE.--Water-stage recorder. Datum of gage is 680.00 ft above National Geodetic Vertical Datum of 1929. Prior to Oct. 1, 1924, nonrecording gage at site 200 ft upstream at same datum.

REMARKS.--Estimated daily discharges: Dec. 15-28 and Jan. 4-9, 13, 14. Records good except for estimated daily discharges, which are fair. Flow regulated by Griggs Reservoir 10.4 mi upstream (see station 03221500), O'Shaughnessy Reservoir 20.4 mi upstream (see station 03220500), and Delaware Lake 35 mi upstream from station. Records include sewage return flow from Frank Road Treatment Plant. Shadeville Treatment Plant flow enters downstream. Water supply for city of Columbus is obtained from Scioto River downstream from Griggs Dam and Big Walnut Creek downstream from Central College. For statement on diversions from Big Walnut Creek, see REMARKS for station 03229500. Water-quality data collected at this site 1965 to 1977. U.S. Army Corps of Engineers satellite telemeter at station.

AVERAGE DISCHARGE.--70 years, 1,405 ft³/s.

EXTREMES FOR PERIOD OF RECORD.--Maximum discharge, 68,200 ft³/s Jan. 22, 1959, gage height, 27.22 ft, from high-water mark in well, from rating curve extended above 46,000 ft³/s; minimum daily, 47 ft³/s Sept. 6, 1930.

EXTREMES OUTSIDE PERIOD OF RECORD.--Flood of Mar. 25, 1913 reached a stage of 25.9 ft, discharge, 138,000 ft³/s, estimated by Franklin County Conservancy District.

EXTREMES FOR CURRENT YEAR.--Maximum discharge, 25,500 ft³/s June 9, gage height, 21.67 ft; minimum daily, 120 ft³/s Oct. 15.

DISCHARGE, CUBIC FEET PER SECOND, WATER YEAR OCTOBER 1989 TO SEPTEMBER 1990
MEAN VALUES

DAY	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
1	145	243	349	2430	1360	1650	946	693	1790	354	1200	413
2	154	170	260	1910	3410	2150	3260	543	1780	345	1070	427
3	134	162	229	2130	7120	2090	3210	547	1740	448	807	345
4	127	158	216	1950	11300	1100	3060	1360	1360	426	956	311
5	122	144	221	2100	9760	1010	2160	3720	872	230	923	284
6	123	159	228	2400	7690	917	2080	4190	1240	325	508	176
7	123	170	277	2000	6730	1580	1160	3630	2040	246	870	313
8	123	298	243	1800	6130	1000	947	2280	4650	198	2060	295
9	123	294	229	1800	4570	1050	935	1790	17500	183	1430	1010
10	186	205	216	1810	3030	478	1730	1490	9540	214	891	682
11	199	179	218	1520	2360	983	3800	706	5360	1060	606	596
12	143	170	217	1390	2160	1030	5880	956	4120	6460	336	841
13	128	175	202	1200	2310	1330	5780	3530	4850	6880	334	761
14	126	187	189	1100	2460	1270	4750	6220	4950	10700	754	672
15	120	527	180	952	8500	1090	3710	7270	6440	8890	1080	729
16	124	2230	170	889	13300	1490	2350	9620	4630	5490	1390	290
17	269	2660	160	758	12200	985	1740	9840	2780	6790	1320	538
18	132	2080	160	462	10400	440	1500	7690	1210	7110	745	274
19	620	1600	150	428	9100	1110	821	4760	920	6330	656	863
20	358	1210	150	2110	7270	1250	1000	3880	1210	4830	821	551
21	219	881	140	3480	4790	937	1390	5330	473	3250	681	513
22	193	698	140	4090	3290	701	2710	3600	352	7660	1030	416
23	180	929	140	3750	2160	469	3710	3320	626	7000	867	876
24	173	693	130	3260	1890	575	2570	2870	576	5200	1620	1260
25	172	405	130	2430	1780	902	1760	1310	357	5610	2320	718
26	173	239	130	1700	1630	888	1550	2360	390	4860	1940	515
27	169	247	130	1540	1690	507	1010	2280	487	4660	874	499
28	171	286	130	1490	1690	319	876	4930	548	2120	398	268
29	163	288	239	1770	---	403	878	10100	395	1290	503	337
30	161	623	566	1630	---	631	958	3460	392	641	450	432
31	218	---	2080	1160	---	500	---	1630	---	767	329	---
TOTAL	5571	18310	8219	57439	150080	30835	68231	115905	83578	110567	29769	16205
MEAN	180	610	265	1853	5360	995	2274	3739	2786	3567	960	540
MAX	620	2660	2080	4090	13300	2150	5880	10100	17500	10700	2320	1260
MIN	120	144	130	428	1360	319	821	543	352	183	329	176

CAL YR 1989 TOTAL 554113 MEAN 1518 MAX 12600 MIN 120
WTR YR 1990 TOTAL 694709 MEAN 1903 MAX 17500 MIN 120

OHIO ENVIRONMENTAL PROTECTION AGENCY

30

TELEPHONE MEMORANDUM

WITH STEVE GRAHAM / FISH MGMT. DATE 12/4/91

REPRESENTING OH DEPT. NATURAL RESOURCES TIME 2:55 p.m.

PERMIT NO. PHONE 481-6300

OEPA STAFF JEFF REYNOLDS

SUBJECT FISHING ON THE SCIOTO - NEAR DOWNTOWN

NOTES & SUMMARY: FOLLOW-UP DATE PICKED UP CREEL 12/5

STEVE SAID THERE IS FISHING EVERY WHERE DOWNTOWN. THERE ARE LOTS OF BASS IN THAT AREA. THEY DID A CREEL SURVEY ON THAT PORTION OF THE SCIOTO IN 1987 (INFO. ON # ANGLERS, USAGE, TYPES FISH).

Signature [illegible]

OEPA-INDWW-3

Dec. 03, 1991

Scioto River (02-001)

- Search for Fish Tissue Sites

AT Rm 129.1

1) F074-85 (Rm 129.1): 3/ white Bass; collected Sept. 19, 1985

collected by: Yoder

- PCB DATA entered

2) F075-85 (Rm 129.1): 2/ Lm Bass; collected Sept. 19, 1985

collected by: Yoder

- PCB DATA entered

3) F076-90 (Rm 129.1): Dst. Greenlawn Dam

5/ channel catfish; collected Sept. 25, 1990

~~pc~~ collected by: Yoder

- PCB DATA entered

4) F079-90 (Rm 129.1): Dst. Greenlawn Dam

comp.: 5/ sauger, 1/ saugeye

collected Sept. 25, 1990 collected by: Yoder

- PCB DATA entered

RECEIVED
DEC 06 1991
Ohio Environmental Protection Agency
CENTRAL DISTRICT OFFICE

RECEIVED FROM:
BERNIE COUNTS
OEPA - DWQPA

Oct. 02, 1991

Scioto River (02-001)

Search for Fish Tissue sites

between Rm 129.1 to 140.0

** 1) F019-90 (RM. 140.0): upst. Fishinger Rd.; at Griggs Res.
collected By: Boucher 5/LM Bass, collected 08/20/90
- PCB DATA entered.

2) F020-90 (RM. 140.0): upst. Fishinger Rd; at Griggs Res.
collected By: Smith 4/Carp, collected 08/08/90
- No PCB DATA entered

** 3) F030-90 (RM. 130.4): Greenlawn Dam pool
collected By: Boucher 5/LM Bass, collected 08/22/40
- PCB DATA entered

4) F040-80 (RM. unknown): N.W. Columbus
collected By: US EPA comp. of SM Bass and Hog sucker
- No PCB DATA entered

31

Rivcode 02001 RM 129.1 Sample ID F074-85

	Concentration (ug/kg)	Remark:
a-BHC	1.000	U
b-BHC	1.000	U
y-BHC	1.000	U
d-BHC	1.000	U
Heptachlor	1.000	U
Aldrin	1.000	U
Heptachlor Epoxide	1.000	U
Endosulfan I	1.000	U
4,4-DDE	2.000	U
Dieldrin	2.000	U
Endrin	2.000	U
Endosulfan II	2.000	U
4,4'-DDD	2.000	U
Endrin Aldehyde	2.000	U
Endosulfan Sulfate	2.000	U

	Concentration (ug/kg)	Remark:
4,4'-DDT	2.000	U
Methoxychlor	2.000	U
Mirex	5.0000	U
Hexachlorobenzene	.000	
Chlordane	340.000	
Toxaphene	10.000	U
PCB1016	30.00	U
PCB1221	30.00	U
PCB1232	30.00	U
PCB1242	30.00	U
PCB1248	210.00	
PCB1254	50.00	U
PCB1260	280.00	

Seek

Back

Forward

Save

New

Comments

QUIT

%LIPID: .00

☐ PROOFED?

Rivcode 02001 RM 129.1 Sample ID: F075-85

	Concentration (ug/kg)	Remark:
a-BHC	1.000	U
b-BHC	1.000	U
y-BHC	1.000	U
d-BHC	1.000	U
Heptachlor	1.000	U
Aldrin	1.000	U
Heptachlor Epoxide	1.000	U
Endosulfan I	1.000	U
4,4-DDE	98.000	
Dieldrin	2.000	U
Endrin	2.000	U
Endosulfan II	2.000	U
4,4'-DDD	2.000	U
Endrin Aldehyde	2.000	U
Endosulfan Sulfate	2.000	U

	Concentration (ug/kg)	Remark:
4,4'-DDT	2.000	U
Methoxychlor	2.000	U
Mirex	5.0000	U
Hexachlorobenzene	.000	
Chlordane	870.000	
Toxaphene	10.000	U
PCB1016	30.00	U
PCB1221	30.00	U
PCB1232	30.00	U
PCB1242	30.00	U
PCB1248	740.00	
PCB1254	50.00	U
PCB1260	.00	U

%LIPID: .00

☐ PROOFED?

Seek

Back

Forward

Save

New

Comments

QUIT

31

31

Rivcode 02001 RM 129.1 Sample ID F076-90

	Concentration (ug/kg)	Remark:
a-BHC	2.000	U
b-BHC	2.000	U
y-BHC	2.000	U
d-BHC	2.000	U
Heptachlor	2.000	U
Aldrin	7.410	
Heptachlor Epoxide	37.260	
Endosulfan I	2.000	U
4,4-DDE	2.000	U
Dieldrin	72.700	
Endrin	2.000	U
Endosulfan II	2.000	U
4,4'-DDD	2.000	U
Endrin Aldehyde	2.000	U
Endosulfan Sulfate	10.090	

	Concentration (ug/kg)	Remark:
4,4'-DDT	8.900	
Methoxychlor	20.000	U
Mirex	2.0000	U
Hexachlorobenzene	2.000	U
Chlordane	1806.500	
Toxaphene	20.000	U
PCB1016	10.00	U
PCB1221	10.00	U
PCB1232	10.00	U
PCB1242	10.00	U
PCB1248	10.00	U
PCB1254	10.00	U
PCB1260	899.00	

Seek

Back

Forward

Save

New

Comments

QUIT

%LIPID: 11.55

☒ PROOFED?

Rivcode 02001 RM 129.1 Sample ID F079-90

	Concentration (ug/kg)	Remark:
a-BHC	1.000	U
b-BHC	1.000	U
y-BHC	1.000	U
d-BHC	1.000	U
Heptachlor	1.960	U
Aldrin	1.000	U
Heptachlor Epoxide	4.690	
Endosulfan I	1.000	U
4,4-DDE	10.000	U
Dieldrin	10.000	U
Endrin	1.000	U
Endosulfan II	1.000	U
4,4'-DDD	1.900	
Endrin Aldehyde	1.000	U
Endosulfan Sulfate	1.280	

	Concentration (ug/kg)	Remark:
4,4'-DDT	2.940	
Methoxychlor	10.000	U
Mirex	1.0000	U
Hexachlorobenzene	1.000	U
Chlordane	173.100	
Toxaphene	10.000	U
PCB1016	5.00	U
PCB1221	5.00	U
PCB1232	5.00	U
PCB1242	5.00	U
PCB1248	146.90	
PCB1254	5.00	U
PCB1260	104.70	

Seek
Back
Forward
Save
New
Comments
QUIT

%LIPID: .35

☒ PROOFED?

31

Rivcode 02001 RM 130.4 Sample Id F030-90

	Concentration (ug/kg)	Remark:
a-BHC	2.000	U
b-BHC	2.000	U
y-BHC	2.000	U
d-BHC	2.000	U
Heptachlor	2.000	U
Aldrin	2.000	U
Heptachlor Epoxide	2.000	U
Endosulfan I	2.000	U
4,4-DDE	6.710	
Dieldrin	4.060	
Endrin	2.000	U
Endosulfan II	2.000	U
4,4'-DDD	2.000	U
Endrin Aldehyde	2.000	U
Endosulfan Sulfate	2.000	U

	Concentration (ug/kg)	Remark:
4,4'-DDT	2.000	U
Methoxychlor	2.000	U
Mirex	2.0000	U
Hexachlorobenzene	2.000	U
Chlordane	60.080	
Toxaphene	19.960	U
PCB1016	9.98	U
PCB1221	9.98	U
PCB1232	9.98	U
PCB1242	9.98	U
PCB1248	9.98	U
PCB1254	9.98	U
PCB1260	69.53	

Seek

Back

Forward

Save

New

Comments

QUIT

%LIPID: .10

☒ PROOFED?

31

Rivcode 02001 RM 140.0 Sample ID F019-90

	Concentration (ug/kg)	Remark:
a-BHC	1.980	U
b-BHC	1.980	U
y-BHC	1.980	U
d-BHC	1.980	U
Heptachlor	1.980	U
Aldrin	1.980	U
Heptachlor Epoxide	1.980	U
Endosulfan I	1.980	U
4,4-DDE	4.300	
Dieldrin	11.190	
Endrin	1.980	U
Endosulfan II	1.980	U
4,4'-DDD	1.980	U
Endrin Aldehyde	1.980	U
Endosulfan Sulfate	1.980	U

	Concentration (ug/kg)	Remark:
4,4'-DDT	1.980	U
Methoxychlor	1.980	U
Mirex	2.0000	U
Hexachlorobenzene	1.980	U
Chlordane	27.750	
Toxaphene	19.770	U
PCB1016	9.89	U
PCB1221	9.89	U
PCB1232	9.89	U
PCB1242	9.89	U
PCB1248	9.89	U
PCB1254	9.89	U
PCB1260	10.91	

%LIPID: .44

☒ PROOFED?

Seek

Back

Forward

Save

New

Comments

QUIT

Stream Segment	Use Designations: Aquatic Life Habitat						Water Supply			Recreation		Comments
	State Resource Water	Warmwater	Exceptional Warmwater	Seasonal Salmonid	Coldwater	Nuisance Prevention	Public	Agricultural	Industrial	Bathing Waters	Primary Contact	Secondary Contact
. . . . .												
Scioto River - Frank Rd. to downstream from Bridge Street in Chillicothe (RM 127.7-70.7)		+						+	+		+	
- Dublin Rd. WTP dam to Frank Rd. (RM 133.4-127.7)	+	+						+	+		+	
- O'Shaughnessy dam to the Dublin Rd. WTP dam (RM 148.8-133.4)	+	+					+	+	+		+	
- all other segments		+						+	+		+	
Pond Creek		+						+	+		+	
Dry Run		+						+	+		+	
Wolf Run		+						+	+		+	
Carroll Run		+						+	+		+	
Sheep Pen Run		+						+	+		+	
Scioto Brush Creek			+					+	+		+	
Duck Run			+					+	+		+	
Sweeney Run			+					+	+		+	
McCullough Creek			+					+	+		+	
East Branch			+					+	+		+	
Bear Creek			+					+	+		+	
Saw Pit Run			+					+	+		+	
. . . . .												

Stream Segment	Aquatic Life Habitat: State Resource Water	Aquatic Life Habitat: Warmwater	Aquatic Life Habitat: Exceptional Warmwater	Aquatic Life Habitat: Seasonal Salmonid	Aquatic Life Habitat: Coldwater	Water Supply: Nuisance Prevention	Water Supply: Public	Water Supply: Agricultural	Water Supply: Industrial	Recreation: Bathing Waters	Recreation: Primary Contact	Recreation: Secondary Contact	Comments
. . . . .													
Scioto River - frank Rd. to downstream from Bridge Street in Chillicothe (RM 127.7-70.7)		•						•	•		•		
- Dublin Rd. WTP dam to Frank Rd. (RM 133.4-127.7)	•	•						•	•		•		
- O'Shaughnessy dam to the Dublin Rd. WTP dam (RM 148.8-133.4)	•	•					•	•	•		•		
- all other segments		•						•	•		•		
Pond Creek		•						•	•		•		
Dry Run		•						•	•		•		
Wolf Run		•						•	•		•		
Carroll Run		•						•	•		•		
Sheep Pen Run		•						•	•		•		
Scioto Brush Creek			•					•	•		•		
Duck Run			•					•	•		•		
Sweeney Run			•					•	•		•		
McCullough Creek			•					•	•		•		
East Branch			•					•	•		•		
Bear Creek			•					•	•		•		
Saw Pit Run			•					•	•		•		
. . . . .													

OHIO VIRONMENTAL PROTECTION AGENCY

TELEPHONE MEMORANDUM

WITH RICH CARTER DATE 11/27/91

REPRESENTING OEPA - DERR/PCB COMPLIANCE GROUP TIME 10:25 a.m.

PERMIT NO. PHONE 644-3065

OEPA STAFF JEFF REYNOLDS

SUBJECT PCBs IN SCIOTO RIVER / FISH TISSUE (I CALLED HIM)

NOTES & SUMMARY: FOLLOW-UP DATE

I EXPLAINED TO RICH THAT FISH TISSUE SAMPLES IN THE AREA OF FRANK ROAD SHOWED MUCH HIGHER PCB LEVELS THAN SAMPLES TEN MILES UPSTREAM AND ASKED IF HE KNEW ANY OTHER LIKELY SOURCES OF PCBs ALONG THAT STRETCH. HE SAID TRANSFORMERS IN VAULTS IN THE DOWNTOWN AREA MAY BE POSSIBLE - DRAINAGE MAY GO TO STORM SEWERS. OFFHAND HE DOESN'T KNOW OF ANY OTHERS AND DOESN'T KNOW HOW LIKELY THESE DOWNTOWN SOURCES ARE.

Signature

OEPA-INDWW-3

Distance Ring Area Calculations and Distance Ring Populations

Radius	πr^2
4 miles	50.26 mi.^{2}
3 miles	28.27 mi.^{2}
2 miles	12.57 mi.^{2}
1 miles	3.14 mi.^{2}
1/2 mile	0.79 mi.^{2}
1/4 mile	0.20 mi.^{2}

Distance Ring	Area	x Population Density (1780.4/mi^2)	= Estimated Number Of People
3 mi. to 4 mi.	21.99 mi.^{2}		39,151
2 mi. to 3 mi.	15.70 mi.^{2}		27,953
1 mi. to 2 mi.	9.43 mi.^{2}		16,790
1/2 mi. to 1 mi.	2.35 mi.^{2}		4,184
1/4 mi. to 1/2 mi.	0.59 mi.^{2}		1,051
0 mi. to 1/4 mi.	0.20 mi.^{2}		0*

* - Estimate would be 356 people, but site visit, maps, etc. show no residents within 1/4 mile of the site.

Numbers of Workers Within One-Fourth Mile of Columbus Scrap

		# Employees
1.	Universal Concrete, 500 W. Whittier. Talked to Tom Wagenhauser @ (614) 841-1955. Facility is closed.	0
2.	City of Columbus Fleet Management Division, 423 Short St. Talked to Brenda Patterson @ 645-8281.	75-80
3.	City of Columbus Traffic Engineering Division, 515 Short St. Talked to Pat Williams @ (614) 645-7393.	72
4.	Lang Stone Co. Inc., 178 W. Sycamore St. Talked to Tom Gill @ (614) 228-5489.	32
5.	Contract Sweepers, 561 Short St. Wouldn't disclose number of workers over the phone. Estimated @ 10.	10
6.	City of Columbus Recreation Department. Talked to Alan McKnight @ 645-3300. Workers in three different buildings: 420 W. Whittier (51), 440 W. Whittier (30), and 460 W. Whittier (8).	89
7.	Lazarus Warehouse, 562 W. Whittier. Talked to Dee Plant @ (614) 463-3486.	80
8.	Spartan Warehousing and Distributing, 371 Maier Pl. Wouldn't disclose number of workers over the phone. Estimated @ 50.	50

Total number of surrounding area workers within one-fourth mile is about 410, plus 30 at Columbus Scrap, equals about 440.

Numbers of Workers and Students Estimated

1.	Mid-Ohio Regional Planning Commission. Talked to Nancy Roeger @ (614) 228-2663. Their estimate for number of workers downtown (within the inner belt).	95,000
2.	Columbus State Admissions Office (1-2 mile distance ring). Called (614) 227- 2453, about 16,000 students, mostly daytime.	16,000
3.	Ohio State University (3-4 mile distance ring). Admissions greater than 50,000 students, mostly daytime.	50,000

Compiled by Jeff Reynolds, Ohio EPA on phone calls made 12/20/91, 1/10/92 and 1/16/92.