Revised Manifest Summary Report

PACIFIC FINANCIAL CENTER
CAPITAL & COUNTIES USA, INC.

Manifest Date	Bates#	Manifest#	Quantity	Units	Gallons	Code	# Trips	Assessed (gl) Volume	
04/16/1986		84345328		1700	LBS		CMP		

Total Records: 1 Default Volume: 0 Total Waste Volume: .85

Pick up for recycling back to customer.

RBS Auth.

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Pick up hours: 8:00 a.m. - 2:00 p.m. April 14, 1986

Please print or type (Form designed for use on elite (12 pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1 Generator's US EPA ID No: CAD076200047

Manifest Document No

2 Page 1 of

Information in the shaded areas is not required by Federal law.

3 Generator's Name and Mailing Address: Al Leverante
Pacific Financial Center
800 W. 6th St., Los Angeles, CA

4 Generator's Phone (213)

A. State Manifest Document Number: 84345328

B. State Generator's ID: CAD076200047

5 Transporter 1 Company Name: Omega Recovery Services

6 US EPA ID Number: CAD042245001

C. State Transporter's ID:

D. Transporter's Phone: ~~213/698-0991~~

7 Transporter 2 Company Name:

8 US EPA ID Number:

E. State Transporter's ID: 701734

F. Transporter's Phone:

9 Designated Facility Name and Site Address: Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602

10 US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11 US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12 Containers No.	Type	13 Total Quantity	14 Unit Wt/Vol	I. Waste No.
a. Hazardous waste, Liquid N.O.S. ORM-E NA 9189 (R-11)	011	DM	1100 LB	P	211
b. Hazardous waste, Liquid N.O.S. ORM-E NA9189 (R-11)	003	DM	600 LB	P	211
c.					
d.					

J. Additional Descriptions for Materials Listed Above
a) 10 - 100 # Drums
b) 3 - 200 # Drums

K. Handling Codes for Wastes Listed Above
a) R01
b) R01

15. Special Handling Instructions and Additional Information
Drums are down at loading dock. Labels are needed.
Bill to: B & D Air Conditioning
5642 Middlecoff
Huntington Beach, CA 92649
Don Kincaid
714/846-1007

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: AL LAVERANTE
Signature: Al Laverante
Date: Month 4 Day 16 Year 86

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Isaac Woods Jr.
Signature: Isaac Woods Jr
Date: Month 04 Day 16 Year 86

18. Transporter 2 Acknowledgement or Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: STEVEN SIMPSON
Signature: Steve Simpson
Date: Month 04 Day 16 Year 86

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 89541

05/31/2001 "ORIGINAL MANIFEST COPY"

Pick up for recycling back to customer.

RBS Auth.

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Pick up hours: 8:00 - 2:00 April 14, 1986
a.m. p.m.

Please print or type (Form designed for use on elite (12 pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No: CAD076200047
Manifest Document No:
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Pacific Financial Center
800 W. 6th St., Los Angeles, CA
Al Leverante
4. Generator's Phone (213)

A. State Manifest Document Number: 84345328
B. State Generator's ID: CAD076200047

5. Transporter 1 Company Name: Omega Recovery Services
6. US EPA ID Number: CAD042245001
C. State Transporter's ID:
D. Transporter's Phone: ~~213/698-0991~~

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID: 701734
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Omega Recovery Services
12504 E. Whittier Blvd.
Whittier, CA 90602
10. US EPA ID Number: CAD042245001
G. State Facility's ID: CAD042245001
H. Facility's Phone: 213/698-0991

	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
GENERATOR a	Hazardous waste, Liquid N.O.S. ORM-E NA 9189 (R-11)	010	DM	110 LB	P	211
b	Hazardous waste, Liquid N.O.S. ORM-E NA9189 (R-11)	003	DM	60 LB	P	211
c						
d						

J. Additional Descriptions for Materials Listed Above
a) 10 - 100 # Drums
b) 3 - 200 # Drums

K. Handling Codes for Wastes Listed Above
a) R01
b) R01

15. Special Handling Instructions and Additional Information
Drums are down at loading dock. Labels are needed.
Bill to: S & D Air Conditioning
5642 Middlecoff
Huntington Beach, CA 92649
Don Kincaid
714/846-1007

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name	Signature	Date (Month Day Year)
AL LAVERANTE	Al Leverante	4/16/86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date (Month Day Year)
Isaac Woods Jr.	Isaac Woods Jr	04/16/86

18. Transporter 2 Acknowledgement or Receipt of Materials

Printed/Typed Name	Signature	Date (Month Day Year)

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date (Month Day Year)
STEVEN SIMPSON	Steve Simpson	04/16/86

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 69541

Pick up for recycling back to customer.

RBS Auth.

State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Pick up hours: 8:00 - 2:00 April 14, 1986

Please print or type (Form designed for use on elite (12 pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1 Generator's US EPA ID No: CAD076200047 | Manifest Document No | 2 Page 1 of | Information in the shaded areas is not required by Federal law.

3 Generator's Name and Mailing Address: Pacific Financial Center, 800 W. 6th St., Los Angeles, CA — Al Leverante

4 Generator's Phone: 213

A. State Manifest Document Number: 84345328

B. State Generator's ID: CAD076200047

5 Transporter 1 Company Name: Omega Recovery Services | 6 US EPA ID Number: CAD042245001

C. State Transporter's ID:

D. Transporter's Phone: ~~213/698-0991~~

7 Transporter 2 Company Name | 8 US EPA ID Number

E. State Transporter's ID: 701734

F. Transporter's Phone:

9 Designated Facility Name and Site Address: Omega Recovery Services, 12504 E. Whittier Blvd., Whittier, CA 90602 | 10 US EPA ID Number: CAD042245001

G. State Facility's ID: CAD042245001

H. Facility's Phone: 213/698-0991

11 US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12 Containers No.	Type	13 Total Quantity	14 Unit Wt/Vol	I. Waste No.
a. Hazardous waste, Liquid N.O.S. ORM-E NA 9189 (R-11)	010	DM	1100 LB	P	211
b. Hazardous waste, Liquid N.O.S. ORM-E NA9189 (R-11)	003	DM	600 LB	P	211
c.					
d.					

J. Additional Descriptions for Materials Listed Above
a) 10 - 100 # Drums
b) 3 - 200 # Drums

K. Handling Codes for Wastes Listed Above
a) R01
b) R01

15. Special Handling Instructions and Additional Information
Drums are down at loading dock. Labels are needed.
Bill to: S & D Air Conditioning, 5642 Middlecoff, Huntington Beach, CA 92649 — Don Kincaid 714/846-1007

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: AL LAVERANTE | Signature: Al Leverante | Date (Month Day Year): 4/16/86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Isaac Woods Jr. | Signature: Isaac Woods Jr | Date (Month Day Year): 04/16/86

18. Transporter 2 Acknowledgement or Receipt of Materials

Printed/Typed Name | Signature | Date (Month Day Year)

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: STEVEN SIMPSON | Signature: Steve Simpson | Date (Month Day Year): 04/16/86

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
TO: P.O. Box 3000, Sacramento, CA 95812

DHS 8022 A (7/84)
(EPA 8700-22)

84 69541