MADISON COUNTY (07/11) Logged into [RLS] as: DRELLERMAN

SUMMARY PROPERTY INFO ASSESSMENT REMEDIATION EVENTS IMAGES MAPS CALLS

Property ID	Property Address	Property City	Property County	Owner Name
17001	1505 MADISON 531	FREDERICKTOWN	MADISON	[redacted]

Owner Information

Owner Name
[redacted]

Owner Phone
[redacted]

Owner Alt. Phone

Occupant Name
,

Occupant Phone

Occupied By

Property

Property PIN

Property Type
RESIDENTIAL

May Contain an EBL Has a Child Care

Children Are Present

Description

Comments

Summary

High Lead
361

Property Status
INELIGIBLE FOR REMEDIATION

Soil Assessment Status
RESULTS LETTER SENT

Soil Remediation Status

Remediation Contractor

Owner Report

Residential Lead PRODUCTION [Version 2.0]

MADISON COUNTY (R/LT) Logged into [RLS] as: DHELLERMAN

SUMMARY PROPERTY INFO ASSESSMENT REMEDIATION EVENTS IMAGES MAPS CALLS

Property ID	Property Address	Property City	Property County	Owner Name
17001	1505 MADISON 531	FREDERICKTOWN	MADISON	[redacted]

Lead XRF Soil Data (9) | Lab Soil (8) | Lab Water (0) | Lab Dust (0) | Lab Solid (0) | Lab Wipe (0) | Add Sampling

Date	Sample ID	Quadrant	Analyte	Matrix	Result	MDL	Result Qualifier
04/21/2011	GSCPLA-17001	GARDEN AREA	Arsenic	SOIL	8.7 mg/kg		
04/21/2011	GSCPLA-17001	GARDEN AREA	Barium	SOIL	127 mg/kg		
04/21/2011	GSCPLA-17001	GARDEN AREA	Cadmium	SOIL	1 mg/kg		U
04/21/2011	GSCPLA-17001	GARDEN AREA	Chromium	SOIL	13.8 mg/kg		
04/21/2011	GSCPLA-17001	GARDEN AREA	Lead	SOIL	334 mg/kg		
04/21/2011	GSCPLA-17001	GARDEN AREA	Selenium	SOIL	10.2 mg/kg		U
04/21/2011	GSCPLA-17001	GARDEN AREA	Silver	SOIL	2 mg/kg		U
04/21/2011	GSCPLA-17001	GARDEN AREA	Solids, percent	SOIL	96.7 %		

Residential Lead PRODUCTION [Version 2.0]