US EPA RECORDS CENTER REGION 5
461719

18
2

Inspection by OEPA Air confirmed 2-15-84

Notes from building inspection:

- Doors open and visible emissions observed all over.
- 4 driers observed 6' × 20' possible asbestos waste on floor. Observed fan on top of drier and observed possible asbestos waste.
- Saw drum of sodium nitrite
- pipe insulation appears to be asbestos and raggedy in places
- Someone came in w/ fire hoses and sprayed the whole place down – they think it's clean now. I don't think they did any good.
- Observed a blob of fibrous material laying on the ground under a cyclone and also a clump of fluffy material inside. (Took sample of blob on ground.)
- Ducts inside had gray dust in them.
- Building open, public can get in. Public exposed to any landfill problems.
- Saw couple boxes of acoustical ceiling tile could be asbestos material