US EPA RECORDS CENTER REGION 5
490287

ecology and environment, inc.

International Specialists in the Environment

Job Number FL0 302SA

B.F. GOODRICH / HENRY

E & E Job Number _____

Telephone Code Number _____

Site Name B. F. Goodrich

State/City ILLINOIS / HENRY

TDD F05-8808-039

PAN FIL0302 SA

SSID _____

Start/Finish Date 9-27-88 / 9-27-88

Book 1 of 1

E & E Emergency Response Center — (716) 631-9530

9-27-88 9:45 AM

Kurt SIMS TEAM LEADER
DAN SULLIVAN TEAM

D. F. Goodrich
309/364-9405

KEN WILLINGS
SR. ENVIR. ENG.

GREG VANDERLAAN
G&M Consulting
ASSOC. ENG.

no present disposal on site

ponds are closed (N. of site) & capped
have sludge
mostly PVC wastes
Orig. closed in 1970's - final cap in 1987

LAGOONS
~~Ponds~~ noted as a hole in are clean now.
- one empty
near SE corner
- the other is clean water

Wastes are drummed and taken off-site

drum storage area N. secondary contain.
concrete pad w/curbing

drums are mostly solid waste - non-haz.
(not listed RCRA)

Sludge shipped off-site

Peoria Disp. Co.
State Land Improvement - Ottawa Il.

big. hog. most incin. some reclaimed

- Rollins - Deer Pk. Tepal
- LWD - Calvert City, Kent
- chem clear - chr.

wells 2 & 3 have shown contamination

recent samples w 3 detects some benzene at low levels

Benzene from spill when mistake in pumping from truck.

no underground tanks now. benzene

Drilling well logs will be sent later. 3 sampled wells & Stadels wells possible

---

SW storm water drains w/ ~~[illegible]~~

NPDES waste water permit

air - possible release of
PVC residue

Fire/Explosion in 60's in process
bldgs.

Direct contact
fences surround & 24 hr
guard.

No access to any ponds

No effect or damage to Fauna
Flora

weed control & mowed berms

No offsite damage

Storm drains - NPDES

Bio treatment & then discharged

No unauthorized dumping

Permits

RCRA - ILT180010324

SSPC - YES no #

air permit-state # 123803 AAD

NPDES ILO001392

state waste # 1238030010

5 ponds

3 (N.) capped & closed

1 in SE unused
1 in SE clean

landfilling of PVC waste near N. ponds (old)

No recovery or treatment on site except Bio of waste

Process wastewater

Sheet piling along river for erosion control

N. ponds are clay lined

Soil/Sedi

2 along River on-site

1 N. of site at gun club

1 S. & N. of W.R. Grace plant

wells

BF well #3 ~ 105' 8" dia.
10 "
2 "
BLDG 731

10 RW-1 MSD
2 RW-2
3 RW-3 DUP
3 RW-4 DUP

MR. STOJEL'S well RW5

Henry Muni #3 = RW6 1936/12"ø/62'
also Henry's #5 /1968/16"ø/150'
#4 /1944/12"ø/74.5'
near #3

well B /1889/artesian/1376'
in Park near City Hall

Backwater Lakes
(~2' deep)

Senacthwine Lake
Swan Lake
Sawmill Lake

Downstream 5-6 miles
Marshall Co. Natl. Wildlife
Refuge

Nearby Residences

- Stadelt - adj.
- Duck club caretaker
- ~1 mi W.
- trailer Pk SW ~1 mile

Ownership

Parent Co.
B.F. Goodrich

1600 Oaktree Blvd.
Cleve. OHIO 44131

216/447-6000

Responses

spill cleanup w/ IEPA (not ordered)
soil removed w/ spill

in situ phys treatment
sulphuric acid neutralized

spills contained with diking