Ashland, Wis.
5-18-72 CDT

VRMZ
WFC
VREB

Frank Marquette 11:15AM
Gridon Const Co
Minneapolis, Minn.

Wanted to know about borings made at site.
Told him boring information available to contractor at Ashland
Said looked like material at site not too good. Told him treatment Plant built on site of an old sawmill as indicated in specific provisions
decayed wood, sawdust, bark etc must be removed and replaced with base fill
Excavated material couldn't be used for backfill, berms, etc would have to be hauled away.
Oh that answers his question

GH0147