US EPA Region 7 Analytical Services Request (ASR) Form

Project ID: _____ ASR Number: _____ Projected Delivery Date: 12/14/2016

Project Desc: Recycletronics

City: Sioux City State: Iowa Program: RCRA

Site Name: Recycletronics

Site ID: _____ Site OU: _____ EPA (CERCLIS) ID: [redacted]

Exemption 2

GPRA PRC: _____

Project Manager: Rebecca Wenner
Organization: WEMM/AWMD Phone Number: (913) 551-7644

Contact: _____ Contact Phone: _____
Organization: _____

ASR Purpose: Waste characterization
Comments:

Is this activity currently or potentially a criminal investigation?: No
Has a QAPP for the requested services been approved?: Yes
QAPP Log Number and/or QA Document Number: _____

For health, safety and environmental compliance are any samples expected to contain:

Dioxin >1pbb: Unlikely
RCRA Listed Wastes: Unlikely
Toxic/Hazardous Chemicals >1000ppm: Possible

Number of Samples	Analysis (Include separated matrix, specific analytes & analytical method[s])	Concentration of Interest	Expected Concentration
15	Solid (soil) and waste (crushed glass). Total Metals (including Hg) and TCLP Metals, Analytical Method SW-846 - 6010, 7471, and 1311.	Low	Low

For assistance, call the Region VII Laboratory Technology & Analysis Branch (LTAB) Manager (or designee) at 913-551-5154.

Special Analytical Requirements or Comments:

Date Submitted: 12/2/2016 By: [signature]

The Sampling Supplies Request (SSR) form will be completed in LIMS by LTAB staff based on the laboratory assignment(s). The SSR will be electronically sent to the EPA Project Manager, sampling contact and R7 warehouse@epa.gov contact (if needed) with the LTAB accepted ASR.

571505