US EPA RECORDS CENTER REGION 5
484251

R1F13

R1F14

R1F15

R1F16

R1F18

R1F19

R1F23

R1F24

R1F25

Riverview Radiator ER

R1F25	R1F18	R1F14
R1F24	R1F16	R1F13
R1F23	R1F17	
R1F19	R1F15	

Site Name: Riverview Radiator
Photo No: 1 (R1F25)
Direction: East
Photographer: N. Smith
Date: March 26, 1999
Subject: A view of the dam built by ~~the~~ LE Wayne County to decrease migration of products in ditch.

Site Name: Riverview Radiator
Photo No: 2 (R1F24)
Direction: West
Photographer: N. Smith
Date: March 26, 1999
Subject: A view of the ditch showing discoloration.

Site Name: Riverview Radiator
Photo No: 3 (R1F23)
Direction: South
Photographer: N. Smith
Date: March 26, 1999
Subject: A view of the discoloration in the ditch.

Site Name: Riverview Radiator
Photo No: 4 (RIF19)
Direction: Southeast
Photographer: N. Smith
Date: March 26, 1999
Subject: A view of the sheen on the water in the ditch.

Site Name: Riverview Radiator
Photo No: 5 (RIF18)
Direction: Southeast
Photographer: N. Smith
Date: March 26, 1999
Subject: START air monitoring around ditch.

Site Name: Riverview Radiator
Photo No: 6 (RIF16)
Direction: Northwest
Photographer: C. Elliott
Date: March 26, 1999
Subject: The drum on the left contains oily material that was sampled.

Site Name: Riverview Radiator
Photo No: 7(RIF17)
Direction: East
Photographer: C. Elliott
Date: March 26, 1999
Subject: START sampling oily material from drum.

Site Name: Riverview Radiator
Photo No: 8 (RIF15)
Direction: West
Photographer: C. Elliott
Date: March 26, 1999
Subject: START sampling the liquid from the sewer drain.

Site Name: Riverview Radiator
Photo No: 9 (RIF14)
Direction: South
Photographer: C. Elliott
Date: March 26, 1999
Subject: START sampling the liquid from the ditch.

Site Name: Riverview Radiator
Photo No: 10 (RIF13)
Direction: South
Photographer: C. Elliott
Date: March 26, 1999
Subject: START sampling the solid material in the ditch.

Site: Riverview Radiator
Photo No: 1 (R1F25)
Direction: East
Photographer: N. Smith

Date: March 26, 1999
Subject: A view of the dam built by Wayne County to decrease migration of products in ditch.

Site: Riverview Radiator
Photo No: 2 (R1F24)
Direction: West
Photographer: N. Smith

Date: March 26, 1999
Subject: A view of the ditch showing discoloration.

Site: Riverview Radiator
Photo No: 3 (R1F23)
Direction: South
Photographer: N. Smith

Date: March 26, 1999
Subject: A view of the discoloration in the ditch.

Site: Riverview Radiator
Photo No: 4 (R1F19)
Direction: Southeast
Photographer: N. Smith

Date: March 26, 1999
Subject: A view of the sheen on the water in the ditch.

Site: Riverview Radiator
Photo No: 5 (R1F18)
Direction: Southeast
Photographer: N. Smith

Date: March 26, 1999
Subject: START air monitoring around ditch.

Site: Riverview Radiator
Photo No: 6 (R1F16)
Direction: Northwest
Photographer: C. Elliott

Date: March 26, 1999
Subject: The drum on the left contains oily material that was sampled.

Site: Riverview Radiator
Photo No: 7 (R1F17)
Direction: East
Photographer: C. Elliott

Date: March 26, 1999
Subject: START sampling oily material from drum.

Site: Riverview Radiator
Photo No: 8 (R1F15)
Direction: West
Photographer: C. Elliott

Date: March 26, 1999
Subject: START sampling the liquid from the sewer drain.

Site: Riverview Radiator
Photo No: 9 (R1F14)
Direction: South
Photographer: C. Elliott

Date: March 26, 1999
Subject: START sampling the liquid from the ditch.

Site: Riverview Radiator
Photo No: 10 (R1F13)
Direction: South
Photographer: C. Elliott

Date: March 26, 1999
Subject: START sampling the solid material in the ditch.