non responsive

[redacted]

949429

non responsive

PRELIMINARY ASSESSMENT

DRAFT

NOV 06 1990

CERCLIS IDENTIFICATION NUMBER	
STATE	SITE NUMBER
OHIO	OHT 400013997

SITE LOCATION

SITE NAME: Legal, common or descriptive name of site
WESTINGHOUSE ELECTRIC COMPANY

STREET ADDRESS, ROUTE or SPECIFIC LOCATION IDENTIFIER
1501 S. Dixie Hwy.

CITY	STATE	ZIP CODE	TELEPHONE
Lima,	Ohio	45804	(419) 221-6000

COORDINATES: LATITUDE and LONGITUDE	TOWNSHIP, RANGE, and SECTION
40° 42' 30"; 84° 07' 30"	T4S R6E Sec 12

OWNER/OPERATOR IDENTIFICATION

OWNER	OPERATOR
Westinghouse Electric Company	Same
OWNER ADDRESS	OPERATOR ADDRESS
1501 S. Dixie Hwy.	Same
CITY	CITY
Lima	Same

STATE	ZIP CODE	TELEPHONE	STATE	ZIP CODE	TELEPHONE
Ohio	45804	(419) 221-6000	Same	Same	( ) Same

TYPE OF OWNERSHIP	OWNER/OPERATOR NOTIFICATION ON FILE
☒ PRIVATE	☒ Unknown
☐ FEDERAL: Agency name _____	☐ CERCLA 103 C. UNCONTROLLED WASTE SITE DATE: _____
☐ STATE	☐ RCRA 3001 DATE: _____
☐ COUNTY	
☐ MUNICIPAL	
☐ OTHER: _____	
☐ NOT SPECIFIED	

SITE STATUS	YEARS OF OPERATION	APPROXIMATE SIZE OF SITE
☒ ACTIVE	BEGINNING YEAR: Unknown	40 acres
☐ INACTIVE	ENDING YEAR: Still operating	
☐ UNKNOWN	☐ UNKNOWN	

SITE EVALUATION

AGENCY / ORGANIZATION
Ohio EPA, NWDO

INVESTIGATOR
James M. Ottarson

CONTACT
Same

ADDRESS
Box 466, Bowling Green, Ohio 43402

TELEPHONE
(419) 352-8461

DATE
8/8/91

SHAWNEE TWP. FIRE DEPARTMENT INCIDENT REPORT INCIDENT # [illegible]
EMS #
FS #

DATE 3/12/86 DAY OF WEEK Wednesday

NATURE OF INCIDENT Investigation

REPORTED LOCATION Westinghouse

REPORTED BY Larry Talley (226-3121 EXT. 419) 4416

ALARM RECEIVED BY
- X PX
- ___ RADIO
- ___ DIRECT PX
- ___ WALK-IN
- ___ ALARM SYSTEM

T.O.	12	22	31	31	VOL	13	SQUAD'S 13
0455	0506					0627	0611

MILEAGE 31 ___ MILEAGE 31 ___ HOSPITAL ___

DISPATCHER: K. Garner TAPE: 628-2-664 (4065)

MILES TO SCENE 2.8 RESPONSE TIME 6 min. TIME-IN-SERVICE 0611
CORRECT LOCATION ___
OCCUPANT/PT'S NAME Westinghouse Corp. 1501 S. Dixie
OCCUPANT/PT'S ADDRESS Tool Room 2nd Floor PX# 226-3121
~~OWNER'S NAME~~ Supervisor on scene: Jerry Jewel
OWNER'S ADDRESS ___ PX# ___

LOCATION OF INCIDENT:
- RESIDENCE ___ TRAFFIC ___
- INDUSTRY X OTHER ___

AREA OF FIRE ORIGIN Tool Room - Cardboard container
CAUSE Accidental - hot metal (welding)
NUMBER OF FIRE RELATED INJURIES ___

METHOD OF EXTINGUISHMENT:
- ___ 1. Self extinguishment
- X 2. Makeshift Aids
- ___ 3. Portable extinguisher
- ___ 4. Automatic system
- ___ 5. Preconnected lines/engines
- ___ 6. Preconnected standpipes
- ___ 7. Hand laid hose lines
- ___ 8. Master stream devices
- ___ 9. Method undetermined

HOURS OF PUMPING TIME 0
GALLONS OF WATER USED ___
UNIT(S) # THAT PUMPED —
HYDRANT(S) # USED —
LADDERS USED —
AERIAL UNIT(S) # USED —
UNIT(S) # RESPONDED 16.4
MUTUAL AID UNIT(S) N/A
TOXIC FUME EXPOSURE X YES ___ NO
if yes explain Oil, grease, poss. cyanide

INSURANCE RECORD: AGENCY- ___

	BUILDING-VEHICLE	CONTENTS	STRUCTURE TYPE
ESTIMATED VALUE			HEIGHT--
ESTIMATED LOSS	0	0	CONSTRUCTION-
INSURED AMOUNT			SINGLE/MULTI UNIT-

if vehicle, appliance, or machinery. SERIAL # ___
MAKE ___ MODEL ___ YEAR ___ LICENSE # ___

E.M.S. INFORMATION: MALE ___ FEMALE ___ AGE ___ D.O.B. ___/___/___
NATURE OF INCIDENT:
- ___ CODE 99
- ___ SEIZURE
- ___ BURN
- ___ D.O.A.
- ___ CARDIAC
- ___ ILLNESS
- ___ DIABETES
- ___ TRAUMA
- ___ POISONING
- ___ OTHER (list)
- ___ RESPIRATORY
- ___ OVERDOSE

TYPE OF TREATMENT: BLS ___ ALS ___ HOSPITAL: SRMC ___ LMH ___ NONE ___

SHIFT: A ___ B X C ___ VOL ___
SUB-STATION RESPONSE ___

WEATHER CONDITIONS Cloudy cold drizzle
ROAD CONDITIONS Wet - Mod. Traffic

COMMENTS: Small fire in tool room possibly involving hazardous material. On arrival fire out. Investigate & check for continuents. Return.

REPORT FILED BY: [illegible] RANK Pl Chief # 19

CHIEF'S SIGNATURE ___ DATE: ___/___/___ STATE FORM ___

SHAWNEE TWP. FIRE DEPARTMENT SUPPLEMENTAL INFORMATION REPORT PAGE # 1

DATE 3/12/86 INCIDENT # 860140

SUPPLEMENTAL REPORT INFORMATION:

Supervisor on scene - Jerry Jewell

Worker accidentally dropped molten metal in cardboard container with low temp salt in it. Became involved in fire. Worker used water to extinguish fire. Involved container in close proximity to other cardboard containers which contained Aerocase 510 (200# container) and Hardcase 600-Fused (200# container) both of which are forms of Sodium Cyanide - Posion B. These containers were not directly involved in the fire. Some of the water used to extinguish fire got on the containers. Also residual water on floor was in contact with containers - Dinger readings in area (3m) gave no distinct readings (ie. no red showed however deep orange-pink color change) - possibly 1 PPM. - Advised Mr. Jewell that since the containers were exposed to [illegible] in water that a problem could arise. Advised to dispose of properly. Mr Jewell contacted John Oskwis who handles their EPA considerations. Three persons who were in the area prior to ventilation were sent to hospital for evaluation - the disposition of this is not sure at this time though

REPORT FILED BY: [signature] RANK Pfc (ret) # 19

CHIEF'S SIGNATURE: _____ DATE ____/____/____

they seemed to suffer no adverse reaction. Mr. Jewell will contact the F.D. later with additional info on the incident.

RON DEUBLER - RELEASED
GREG PATTERSON - BLOOD SAMPLE TAKER - INITIAL FIRE ATTACK
LARRY TALLY - RELEASED
BRUCE FRANKLYN - RELEASED
JOHN GOLDEN - RELEASED

REPORTED BY JERRY JEWELL, MFG. SUPERVISOR

>> Ron Schultz 4-2081

OhioEPA INITIAL POLLUTION INCIDENT REPORT 19 86

I.D. Number 3-2-0704

Time & Date Reported 0930 3-12-86 Discovered 0530 3-12-86 Occurred 0530 3-12-86

Reported by (Name & Position) Shawnee Twp FD.

Telephone _____ Did Spiller Report? FD yes ____ no X Complaint X yes ____ no

Suspected Spiller Westinghouse Co.

Mailing Address Cleveland

Product Spilled Sodium Cyanide Surface Type: C, H

Approximate Amount (Duration) ~~[illegible]~~ NOS, [illegible] Size: U Priority: II

Source of Spill fire in Drum Areas Affected: (A) L S G (None)

Waterway Affected None Weather _____

Location (County & City) Allen Co., Lima

(Street Location) _____

Did You Tell Spiller To Call The N.R.C.? ____ yes ____ no (1-800-424-8802, Washington D.C.)

COMMENTS AND FOLLOW-UP INFORMATION

Hot Metal Dripped into open Cyanide Barrel & caught Fire

RECEIVED
MAR 14 1986
OHIO EPA
N.W.D.O.

TELEPHONE RECORD

District Office NW	Talked to Dir Higgins	Time & Date 1545 3-12-86
Water Supply 98307)	Talked to	Time & Date
District Engineer	Talked to	Time & Date
ODNR (night: 265-7006)	Talked to	Time & Date
DSHWM	Talked to	Time & Date
ODA (866-6361	Talked to	Time & Date
ODH (5190)	Talked to	Time & Date
PIC (8508) Al Franks 263-0220: Home	Talked to	Time & Date
SFM (864-5510)	Talked to	Time & Date
Local FD or PD	Talked to	Time & Date Reported
	Talked to	Time & Date
	Talked to	Time & Date

Follow-up

Business ____ yes ____ no

District ____ yes ____ no

Received by [illegible]

TSS ____ yes [illegible] no


ROCKFORD 10 MI.
SPENCERVILLE 13 MI.
Central Jr High Sch
St Rita Hospital
Library
Public Square
Courthouse
Garfield Sch
Longfellow Sch
Lincoln Park
Stadium
Lowell Sch
Faurot Sch
Rogers Sch
LIMA
Memorial Hospital
High Sch
Industry Park
Lincoln Sch
Washington McKinley Sch
BM 879
Woodlawn Cem
Hobart Park
St Johns Sch
South Jr High Sch
Water
SPENCERVILLE AND ELGIN
ABANDONED
REFINERY
Whittier Sch
Jefferson Sch
TANK FARM
INTERCHANGE 124
PIPELINE
Radio Tower
TANK FARM
Substation
INTERCHANGE 122
Fort Shawnee
PIPELINES
INTERCHANGE 120
BREESE ROAD
Luther Cem
Fletcher Cem
ROATHE
4513000m N.
T. 3 S.
T. 4 S.
42'30"
4165 II NW (CRIDERSVILLE)
RULER INE



ROAD CLASSIFICATION

Heavy-duty — Light-duty

Medium-duty — Unimproved dirt

Interstate Route — U. S. Route — State Route

(WAYNESFIELD) 4265 III SW

QUADRANGLE LOCATION

purple and woodland compiled in
ate of Ohio agencies from aerial
1980 and other sources. This information

LIMA, OHIO

75 N.E.

40084-F1-TF-024

1961
PHOTOREVISED 1983
DMA 4165 II NE—SERIES V852