EPA POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

NOTE. The initial identification of potential site or incident should not be interpreted as a finding of illegal activity or confirmation that actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME	B. STREET (or other identifier)		
Vickers Petroleum Soil Farm	142 By Pass		
C. CITY	**D. STATE**	**E. ZIP CODE**	**F. COUNTY NAME**
Ardmore	OK	73401	Carter

G. OWNER/OPERATOR (if known)

1. NAME	2. TELEPHONE NUMBER
Vickers Petroleum	

H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☒ 5. PRIVATE ☐ 6. UNKNOWN

I. SITE DESCRIPTION

Soil Farm

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

OSDH Permit Application

K. DATE IDENTIFIED (mo., day, & yr.)

3/28/80

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

Unknown

M. PREPARER INFORMATION

1. NAME	2. TELEPHONE NUMBER	3. DATE (mo., day, & yr.)
B. Moore	(405) 271-5338	3/28/80

EPA Form 2070-8 (5-80)

Total Petroleum Corp (Vickers Petroleum)

OKD057705972

SUPERFUND FILE

OCT 21 1992

REORGANIZED

9532469