State of California—Environmental Protection Agency
Form Approved OMB No. 2050-0039 (Expires 9-30-99)
Please print or type. *Form designed for use on elite (12-pitch) typewriter.*

See Instructions on back of page 6.

Department of Toxic Substances Control
Sacramento, California

97213841

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD086510005
Manifest Document No.: 13841
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
BOEING REALTY CORP
19503 NORMANDIE AVE
TORRANCE CA 90502-1109
4. Generator's Phone 562 627-3014

A. State Manifest Document Number: 97213841
B. State Generator's ID:
C. State Transporter's ID:
D. Transporter's Phone: 805 589 5220
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: CAT000646117
H. Facility's Phone: (209)386-9711

5. Transporter 1 Company Name: KVS TRANSPORTATION
6. US EPA ID Number: CAD982495608
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
CHEMICAL WASTE MANAGEMENT, INC.
35251 OLD SKYLINE ROAD
KETTLEMAN CITY CA 93239
10. US EPA ID Number: CAT000646117

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
a. NON RCRA HAZARDOUS WASTE SOLID, (SOIL CONTAMINATED WITH LEAD AND CHROMIUM)	001	DT	00018	Y	State 611; EPA/Other NONE
b.					State; EPA/Other
c.					State; EPA/Other
d.					State; EPA/Other

J. Additional Descriptions for Materials Listed Above
a. CD8311

K. Handling Codes for Wastes Listed Above
a. 03
b.
c.
d.

15. Special Handling Instructions and Additional Information
CHEMTREC Emergency Response Number (800)424-9300

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: S.M. Stavale
Signature: SMStavale
Month 04 Day 09 Year 98

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Herman L. Cope
Signature: Herman L. Cope
Month 04 Day 10 Year 98

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: W. Gentry
Signature:
Month 04 Day 3 Year 98

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS. (Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

DTSC 8022A (4/97)
EPA 8700—22