DAC 25-2140 (12-73)

DPM/QPL REQUEST

DPM NO. 5507
DMS QPL NO.
ISSUE NO.

NEW ☐ REV. ☒ DATE: 9-20-77 ENGINEER J. GILES

GENERAL TITLE	SPEC. OR CLASS	ST. TEMP.	TOX.	FL. PT.	SHELF LIFE	LABEL
BARRIER COATING	COMM.	AMB.	3B	65°F	INDEF.	

DAC CODE NO.

P.O. NOTES: P.O. TO SPECIFY

GEN. NOTES: MEETS South Coast AQMD Rule 102. Used by DPS 4.50-12

USED BY DPS:

MANUFACTURER'S NAME	CITY, STATE	MFR.'S DESIGNATION
1. DELETE: FULLER-O'BRIEN		Delete: 175-F-3
2. ADD: WLS COATINGS	HARBOR CITY	#102-6-0
3.		
4.		OK 9-22-77 (K)
5.		
6.		

LAB REPORT NO.

REASON FOR REQUEST: Fuller-O'Brien discontinued manufacture of the coating and supplied DAC the formula. Formula will be transmitted to WLS.

SPECIFY CHANGE(S) MADE: Deleted Fuller-O'Brien added WLS Coatings

CHANGE INFO.	REQ'D	COMPL.
DPM LIST	✓	✓
DMS QPL LIST		
MMS LIST		
ALPHABETICAL LIST		✓
NUM. VENDOR# LIST	✓	✓

NO. 5507

✓M. Veneroso E. D. Klinger Mat'l Release M. Russ 9-22-77

FEB 09 1982

BOE-C6-0202972

FULLER-O'BRIEN DIVISION
THE O'BRIEN CORPORATION

August 11, 1977

M. J. Veneroso, Dept. C1-726(52-11)
Materials Handling & Packaging Engineering
Douglas Aircraft Company
3855 Lakewood Blvd.
Long Beach, California 90846

Re: C1-726-212

Dear Mr. Veneroso:

The items listed in your July 25 letter have not been manufactured for several years so should be considered obsolete except for:

162-B-4/75-X-24 — DPM 5405
163-W-53 — DPM 2860
171-C-80 — DPM 1258

Material Safety Data Sheets for these are enclosed.

Sincerely,

FULLER-O'BRIEN DIVISION
The O'Brien Corporation

HLLeichel

Herman L. Leichel
Sales Administration
Industrial Finishes Division

HLL:dm

encls.

450 East Grand Avenue, South San Francisco, California 94080 · (415) 761-2300

Aluminum Paste, #1571	DPM 439	(No longer manufactured)
Wood Filler, #1206	DPM 1063-3	(No longer manufactured)
Coating, #171-C-80	DPM 1258	
Glazing Compound #163-W-53	DPM 2860	
Varnish, #56-C-279	DPM 5289	(No longer manufactured)
Primer, #162-B-4	DPM 5405	
Catalyst, #75X-24	DPM 5405	
Coating, #175-F-3	DPM 5507	(No longer manufactured)