DPM 1509-2 JAN 25 1982
Coating, Wash 4, Yellow Gold

4859-11

Form Approved
OMB No. 44-R1387

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

MATERIAL SAFETY DATA SHEET

FEB 20 1980

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECTION I

MANUFACTURER'S NAME: Turco Products	EMERGENCY TELEPHONE NO.: (213) 634-3300
ADDRESS (Number, Street, City, State, and ZIP Code): 24600 S. Main St., Box 6200, Carson, Calif. 90749	
CHEMICAL NAME AND SYNONYMS	TRADE NAME AND SYNONYMS: Fabrifilm
CHEMICAL FAMILY	FORMULA

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS Acetone	20	1000 ppm	FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES	%	TLV (Units)
Toluene	25	100 ppm
Isopropyl Alcohol	30	400 ppm
n-Butyl Alcohol	Less than 5	50 ppm

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	133°-243°	SPECIFIC GRAVITY (H_2O=1)	0.86
VAPOR PRESSURE (mm Hg.)	approx. 185	PERCENT, VOLATILE BY VOLUME (%)	85%
VAPOR DENSITY (AIR=1)	over 1	EVAPORATION RATE butyl acetate	over 1
SOLUBILITY IN WATER	slight		
APPEARANCE AND ODOR			

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used) SETA 44°F.	FLAMMABLE LIMITS	Lel 1.5	Uel 12.8
EXTINGUISHING MEDIA CO_2, Dry Chemicals, Foam			
SPECIAL FIRE FIGHTING PROCEDURES			
UNUSUAL FIRE AND EXPLOSION HAZARDS			

(Continued on reverse side)

Form OSHA-20
Rev. May 72

1-4-78

BOE-C6-0203715

Fabrifilm

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
See Section II.

EFFECTS OF OVEREXPOSURE
Eyes: Severe irritation. Inhalation: Headache, dizziness, nausea. Prolonged over-exposure may cause kidney & liver damage.

EMERGENCY AND FIRST AID PROCEDURES
Skin: Wash with soap & water. Eyes: Flush with copious amounts of water 15 minutes. If irritation persists, get medical attention. Inhalation: Remove to fresh air; keep at rest. Ingestion: Call physician; do not induce vomiting.

SECTION VI - REACTIVITY DATA

STABILITY			CONDITIONS TO AVOID
	UNSTABLE		
	STABLE	X	

INCOMPATABILITY *(Materials to avoid)*
Avoid strong oxidizers

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION			CONDITIONS TO AVOID
	MAY OCCUR		
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Wipe up small spillage. Large spills: Eliminate any ignition source, evacuate area, provide ventilation; use inert absorbent material to contain and soak up.

WASTE DISPOSAL METHOD
Collect in metal containers and bury away from inhabited areas and water supply.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION *(Specify type)*
Activated charcoal.

VENTILATION			SPECIAL
	LOCAL EXHAUST	X	
	MECHANICAL *(General)*		OTHER

PROTECTIVE GLOVES	X	EYE PROTECTION	X

OTHER PROTECTIVE EQUIPMENT

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Observe precautions for flammable liquids. Store in closed containers; keep in a cool place.

OTHER PRECAUTIONS
Avoid prolonged breathing of vapors. Provide adequate ventilation.