IRRIDITE 1-A
DPM 2298

DANGER

CONTAINS ~~CHROMIC~~ Ferric ACID

Contact with combustible material may cause fire, may cause burns or external ulcers. Keep container closed. Avoid contact with skin and eyes. Avoid breathing dust or mist from solution.

In case of contact, immediately flush skin or eyes with plenty of water for at least 15 minutes; get medical attention. Wash clothing before reuse. Use fresh clothing daily. Take hot shower after work using plenty of soap.

DAC 30-1061-53 (2-73)

IRRIDITE 1-B
DPM 2298-1

WARNING

CONTAINS ~~SODIUM-BICHROMATE~~ Chromic

Harmful dust and Mist. May cause rash or external ulcers. Keep container closed, avoid contact with skin and eyes. Avoid breathing dust or solution spray.

In case of contact, immediately flush skin or eyes with plenty of water for at least 15 minutes; get medical attention. Wash clothing before reuse. Use fresh clothing daily. Take hot shower after work using plenty of soap.

DAC 30-1061-54 (2-73)