JAN 29 1982

DPM 2710
Additive, Tint dip

DOUGLAS AIRCRAFT COMPANY

3855 Lakewood Boulevard Long Beach, California 90846

January 16, 1978

JAN 19 1978

C1-725-30

Hastings Plastic Company
1704 Colorado Avenue
Santa Monica, California 90404

Gentlemen:

This facility must, on occasion, reship your following products:

OSHA form only

we do not carry this product (DPM 2275-3)

Hapex 1233A
Hardener, #1201
Hapex 1231 - DPM 2275-4
DPM 2360-1

Hardener, #1221 DPM 2360-1
Additive, XZ-413-1 Please find attached
DPM 2710 - Nothing attached for DPM 2710

In order to insure our compliance with the Hazardous Materials Regulations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your products are regulated or restricted articles for shipment by surface or air modes of transport.

Should the products be regulated, please indicate:

1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
2. DOT Hazard Classification per Section 172.101, 49 CFR.
3. Flash Point and Closed Cup method per Section 173.115, 49 CFR.
4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet, if available, for all components listed.

Your cooperation and prompt reply will be appreciated.

Very truly yours,

M. J. Veneroso, Dept. C1-726 (52-11)
Materials Handling & Packaging Engineering
Douglas Aircraft Company

WTJ:rc

MCDONNELL DOUGLAS CORPORATION

BOE-C6-0204393