JAN 29 1982

MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP. 7/15/81

DPM 2860

CA1781000

Section I

Compound, Glazing

MANUFACTURER'S NAME
Continental Coatings Corp.

STREET ADDRESS
1726 S. Baker St.

CITY, STATE, AND ZIP CODE
Ontario Calif. 91761

EMERGENCY TELEPHONE NO.
[illegible]

PRODUCT CLASS
Caulk

MANUFACTURERS CODE IDENTIFICATION
979W-1 Dpm 2860

TRADE NAME
Glazing Compound

Section II — HAZARDOUS INGREDIENTS

INGREDIENT	PERCENT	TLV PPM	TLV mg/M³		
Cyclohexanone	5.33	25			
Toluene	4.40	100	375		
Xylene	1.44	100	435		
Aliphatic Hydrocarbons	3.00	100			
Butyl Acetate	4.86	150	710		
N. Butyl Alcohol	.53	50	150		
Butyl Alcohol	2.20	1000	1,500		
2-nitropropane	5.50	25	90		
Vinyl Chloride	4.00		15		
Antimony Trioxide	5.30		.5		

Section III — PHYSICAL DATA

BOILING RANGE 110°F-161°F

VAPOR DENSITY [X] HEAVIER [ ] LIGHTER THAN AIR

EVAPORATION RATE [ ] FASTER [X] SLOWER, THAN ETHER

PERCENT VOLATILE BY VOLUME 49%

WEIGHT PER GALLON 11.5

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY Flammable Liquid

FLASH POINT 47° 20°

LEL 1.0 UEL 8.1

EXTINGUISHING MEDIA

Dry Powder, CO_2., Chemical Foam, Water Fog.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Handle as flammable liquid- avoid inhalation of smoke

SPECIAL FIRE FIGHTING PROCEDURES

Handle as flammable liquid

BOE-C6-0204480

Section V — HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE 25 ppm

EFFECTS OF OVEREXPOSURE

Local: Dermatitis Systems: Symptoms include insomnia, nausea, loss of appetite, dry throat and anemia

EMERGENCY AND FIRST AID PROCEDURES

Remove immediately from further exposure. Contact physician.

Section VI — REACTIVITY DATA

STABILITY [ ] UNSTABLE [X] STABLE

CONDITIONS TO AVOID Acidic or reducing condition

INCOMPATABILITY (*Materials to avoid*)

HAZARDOUS DECOMPOSITION PRODUCTS

CO_2 Aldehydes and other organics.

HAZARDOUS POLYMERIZATION [ ] MAY OCCUR [X] WILL NOT OCCUR

CONDITIONS TO AVOID

Section VII — SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Collect material in plastic bags for disposal.

WASTE DISPOSAL METHOD Recommend burial in approved hazardous facility.

Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION

In confined areas use Bureau of Mines mask 25B-1[illegible] BM 2304 cartridge, BM 23-13 Filters.

VENTILATION

Should be adequate to keep lower level below LEL

PROTECTIVE GLOVES Yes

EYE PROTECTION Glasses

OTHER PROTECTIVE EQUIPMENT None

Section IX — SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Keep away from open flame or heat - no smoking.

OTHER PRECAUTIONS Avoid contact with skin or eyes. Wash hands before smoking, eating or drinking. Avoid storage or use near strong acids or bases. Do not take internally.