DPM 3248 Series
Paint, Vinyl, Screen Process

FEB 01 1982

TIBBETTS-WESTERFIELD PAINT CO., INC. 2600 East 8th Street, Los Angeles, California 90023, (213) 264-4710

January 20, 1978

Mr. J. J. Veneroso
Dept. C1-726 (52-11)
Materials Handling & Packaging Engineering
Douglas Aircraft Company

Dear Mr. Veneroso,

None of the items in your letter of January 16, 1978 are regulated or restricted articles.

Very truly yours,

R. S. Kelsey

Richard S. Kelsey
Vice President

RSK/tv

(ROUGH DRAFT)

T. W. Screen Process Supply Co.,
2600 E. 8th St.
Los Angeles, Cal. 90023

1-16-78
~~6-17-77~~

Gentlemen:

This facility must, on occasion, reship your products:

Butyl Lactate **(DPM 3236)**

Vinyl Paint, TW-9500-66 Series **(PM 3248-Ser)**

Coating, 323A; 324A; and S-334A **(DPM 5859 Ser)**

In order to insure our compliance with the Hzardous Materials Regulations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your products are regulated or restricted articles for shipment by surface or air modes of transport.

Should the products be regulated, please indicate:

1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
2. DOT Hazard Classification per Section 172.101, 49 CFR.
3. Flash Point and Closed Cup method per Section 173.115, 49 CFR.
4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet, if available, for all components listed.

Your cooperation and prompt reply will be appreciated.

VTY,

MJV