HYSOL DIVISION • THE DEXTER CORPORATION
P. O. BOX 312, PITTSBURG, CALIF. 94565 415-687-4201

July 15, 1977

DPM 3279-3

Douglas Aircraft Company
3855 Lakewood Boulevard
Long Beach, California 90846

Attention: M. J. Veneroso
Department C1-726 (52-11)

Re: Your letter 6/21/77, concerning DOT information for EA 9309

Gentlemen:

The following is in response to your questions:

1. DOT proper shipping name per CFR 49
   Part A - Not restricted
   Part B - Corrosive Liquid, NOS (Epoxy Adhesive Hardener)

2. DOT Hazard Classification
   Part B - Corrosive material

3. Flash Point
   See attached Material Safety Data Sheets

4. IATA Article Number
   Part B - 522

If the above is not completely satisfactory please contact us.

Very truly yours,

R.M. Campanile

R. M. Campanile
Manager, QAT

RMC:mem

Attachments

7/18/78 Rec'd Cartons marked "ALKALINE LIQUID, N.O.S." Called Jerry Martin, QAT Dept. He stated P/S/N has been reclassified since lt. written

WJ