FEB 01 1982

Acheson

Acheson Colloids Company
Port Huron, Michigan, 48060
Telephone 313 984-5581
TWX 810 231-5265
DUNS 00-535-6340
Division of Acheson Industries, Inc.

DPM 3361
Coating, Epoxy-Teflon
Deleted - Not Replaced

5 May, 1977

Douglas Aircraft Company
3855 Lakewood Blvd.
Long Beach, California 90846

Attention: M. J. Veneroso, Dep't. CI-726 (52-11)

Gentlemen:

In response to your letter NR 37 of 25 April, concerning the D.O.T. hazardous classification of Emralon 315, the information requested, follows:

Emralon 315, is a two-component system, consisting of components A & B.

Component A is basically a fluorocarbon in water, which is non-hazardous, as defined in title 49 CFR.

The proper D.O.T. shipping name for component B is "resin solution". The B component has a Tag closed cup flash point of 58°F and is therefore classed as a "Flammable Liquid".

Although this product has been discontinued, we still have some stock on hand. At this time, an OSHA Material Safety Data Sheet is not available.

If we can be of further service concerning this matter, please let us know.

Respectfully,

Robert R. Powers

RRP/tat

cc: JEA

BOE-C6-0204963

DAC 25-2140 (12-73)

DPM/QPL REQUEST

DPM NO. 3361
DMS QPL NO.
ISSUE NO.

NEW ☐ REV. ☒ DATE: 6-27-77 ENGINEER J Giles

Coating - Epoxy Teflon
GENERAL TITLE

SPEC. OR CLASS | ST. TEMP. | TOX. | FL. PT. | SHELF LIFE | LABEL

DAC CODE NO.

P.O. NOTES: P.O. TO SPECIFY

GEN. NOTES:

USED BY DPS:

CANCEL
Not Replaced
on 6-27-77
R

	MANUFACTURER'S NAME	CITY, STATE	MFR.'S DESIGNATION
1.			Emralon 315
2.			
3.			
4.			
5.			
6.			

LAB REPORT NO.

REASON FOR REQUEST: Item discontinued by mfg.

SPECIFY CHANGE(S) MADE:

CHANGE INFO.	REQ'D	COMPL.
DPM LIST	✓	✓
DMS QPL LIST		
MMS LIST		
ALPHABETICAL LIST	✓	✓
NUM. VENDOR # LIST	✓	✓

NO. 3361

✓ M. Veneroso C R Love Mat'l Release M. Russ 6-28-77

BOE-C6-0204964