HAZARDOUS WASTE LOG SHEET

PAGE: 1 OF 2 LOCATION: C6 Torrance MONTH: October YR: 1993

MANIFEST NO.	DATE MANIFESTED	TRANSPORTER	DAC TANK NO.	CONTENTS	QUANTITY	CAT. NO./ DOT CLASS	DATE MANIF. RTN.	TSDF	DISP METHOD	TAX CAT.	ACTUAL QUANTITY	DISPOSAL CHARGE	TRANSP. CHARGE	TOTAL CHARGE	
11909 90411909	10-06-93	Laidlaw Environmental Services	Tank 259, Sump 26 S, an from cleaning Berm	Waste Aluminum Chem mill Solution	47,620 P	121 D002	11-09-93	Norris							NO DISCR
11910 90411910	10-11-93	JCI Environmental Services	40T, Tramp oil tank near Bldg 37, Drums of	@ machine Coolant, Oil, and water	1 Tank Truck 20,100 P	223 NR	10/14/94	Chem Tech				3995.00	512.25	4507.25	NO DISCR.
↓	↓	↓	waste oil & water from Bldg 45	Non-RCRA Hazardous waste Liquid	↓	↓	↓	Chem Tech							↓
01666 92301666	10-13-93	Laidlaw	Tank 259 waste NaOH	waste Sodium Hydroxide Solution from Chemical milling of Aluminum	42,920 P	121 D002	11-11-93	Norris							NO DISCR.
45355 92745355	10/14/93	JCI	Drums, Bldg 45	Hydrothoric acid drums, Empty	2 DF 001 P	791 D002	10/29/93	Chem-Tech	01						NO DISCR.
45358 92745358	"	"	"	Hydrothoric acid bottles, empty	1 DF 001 P	791 D002	10/29/93	↓	01			1409.42	335.47	1744.87	NO DISCR.
45358 92745358	10/15/93	JCI	Drums from Bldg 45 Pumped into Tank Truck	Purge water containing trace organic solvents from groundwater well development and sampling	1 TANK TRUCK 12,060 P	134 D018 D022 D039	10/22/93	Chem-Tech	01						NO DISCR.
45359 92745359	10/18/93	Laidlaw	waste Kolene from Drums Bldg 45	Waste Kolene from Tank 90	10 Drums 4,310 P	181 D001	11/18/93	Appropriate Technologies, Inc.							NO DISCR.
35677 ARG35677	10/18/93	Laidlaw	Drums-Bldg 45	Paint Sludge + Solvents	3 DRUMS (DM) 965 P	461 D001, D007 F002, F003, F005	11-10-93	Rineco							NO DISCR.
↓	↓	↓	↓	Gasoline + Water	1 Drum (DM) 110 P	213 D001	↓	↓							↓
↓	↓	↓	↓	Rags contaminated with solvents	1 (BA) BAG 1125 P	352 D007, F002 F003, F005	↓	↓							↓
↓	↓	↓	↓	Sealant Tube	1 Drum (DM) 75 P	352 D007, D008	↓	↓							↓
↓	↓	↓	↓	Instapak B, resin	1 Drum (DM 100 P	331 N/R	↓	↓							↓
↓	↓	↓	↓	~~Pre-impregnated Fabric Tolls~~ RBJ 10-18-93	~~6 CF 265 P~~ RBJ 10-18-93	~~352~~ RBJ 10-18-93 ~~N/R~~	↓	↓							↓
45362 92745362	10/20/93	IT Corp	Drum Bldg 45	Light Ballasts containing PCB's	1 DRUM 100 P	731 N/R	11/05/93	Rollins OA							NO DISCR.
BILL OF LADING	10-20-93	Mercury Recovery Services	Fluorescent Tubes & HID LAMPS FROM BLDG. 45	2 FT. Fluorescent Tubes	(QTY OF LAMPS, 4 COUNT)			Mercury Recovery Services							NO DISCR
↓	↓	↓	↓	3 FT. Fluorescent Tubes	5 Count			↓							↓
↓	↓	↓	↓	4 FT. Fluorescent Tubes	223 Count			↓							↓
↓	↓	↓	↓	U-TUBES	8 Count			↓							↓
↓	↓	↓	↓	8 FT. FLUORESCENT TUBES	991 Count			↓							↓
↓	↓	↓	↓	HID Lamps	43 Count			↓							↓