California—Environmental Protection Agency
Approved OMB No. 2050-0039 (Expires 9-30-94)
Please print or type. *Form designed for use on elite (12-pitch) typewriter.*

See Instructions on back of page 6.

Department of Toxic Substances Control
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD086510005 Manifest Document No. 85742
2. Page 1 of 2

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Company Attn: Rob Tuell M/S C6-59
19503 South Normandie Avenue, Torrance, CA 90502

4. Generator's Phone 310 533-7926 OR (310) 533-7231

A. State Manifest Document Number 93385742
B. State Generator's ID HAHQ36005698

5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.
6. US EPA ID Number CAD000083121
C. State Transporter's ID 423510
D. Transporter's Phone (310) 518-4700

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Rollins OPC, Inc.
5756 Alba Street
Los Angeles, CA 90058
10. US EPA ID Number CAD050806850
G. State Facility's ID
H. Facility's Phone (213) 585-1871

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
a. RQ, waste organic peroxide type D, solid; 5.2; UN3106; PG II (Benzoyl Peroxide) (D001)	002	DM	00290	P	State 352; EPA/Other D001
b. RQ, waste poisonous solids, corrosive, n.o.s.; 6.1; UN2928; PG I (Copper Cyanide, Sodium Hydroxide)	002	DF	00531	P	State 241; EPA/Other P029
c. Waste poisonous solids, n.o.s.; 6.1; UN2811; PGII (P029, P104, P106)	001	DF	00105	P	State 181; EPA/Other P029
d. (Duraguard DF) Non-RCRA hazardous waste liquid	001	~~DM~~ DF (RESOS-20-94)	00120	P	State 331; EPA/Other N/A

J. Additional Descriptions for Materials Listed Above
a. OP18500, 24 Hr Sid Ch. 20 Comp. B.
b. OP18501, 30 Cyanide and Sodium Hydroxide solid from tank 47,56.
c. OP18500, 49 Cyanide contaminated debris.
d. OP17692, 38 Foam-out, Duraguard DF. RES# 8284

K. Handling Codes for Wastes Listed Above
a. 14 b. 14 c. 14 d. 14

15. Special Handling Instructions and Additional Information
24 Hour emergency telephone number (800)424-9300 (Chemtrec). DOT ERG#11a)48 b)59 c)53 d)N/A
Additional Codes 11b)P106 c)P104, P106

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: Robert G. Tuell, Jr. Signature: Robert G. Tuell, Jr. Month Day Year: 05 20 94

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JACK JOHNSON Signature: Jack Johnson Month Day Year: 05 20 94

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Signature: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: MARIA A. LOPEZ Signature: Maria A. Lopez Month Day Year: 05 20 94

DO NOT WRITE BELOW THIS LINE.

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS. (Generators who submit hazardous waste for transport out-of-state, produce completed copy of this copy and send to DTSC within 30 days.)

DTSC 8022A (7/92)
EPA 8700—22

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7550

93385742

BOE-C6-0206660

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST
(Continuation Sheet)

21. Generator's US EPA ID No.: CAD086510005
Manifest Document No.: 85742
22. Page: 2 of 2

Information in the shaded areas is not required by Federal law.

23. Generator's Name: **Douglas Aircraft Company**

L. State Manifest Document Number: **93385742**

M. State Generator's ID: **HAHQ36005698**

24. Transporter ___ Company Name
25. US EPA ID Number
N. State Transporter's ID
O. Transporter's Phone

26. Transporter ___ Company Name
27. US EPA ID Number
P. State Transporter's ID
Q. Transporter's Phone

	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	HM	29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	(Cleaning compound,dry) Non-RCRA hazardous waste solid	X	003	DM	01255	P	181 N/R
b.	(510 Fluid) Non-RCRA hazardous waste liquid	X	003	DM	01120	P	141 N/R
c.	(Cobratec 99 Powder) Non-RCRA hazardous waste solid	X	001	DM	00344	P	352 N/R
d.	(Safety draw 700) Non-RCRA hazardous waste liquid	X	001	DM	00275	P	141 N/R
e.							
f.							
g.							
h.							
i.							

GENERATOR

S. Additional Descriptions for Materials Listed Above
28 a)OP18497. Cleaning compound,dry. Isoprep 44 solid.
b)OP18498. Dow Corning 510 Fluid, 30,000cs.
c)OP18499. Cobratec 99 powder.
d)OP18757. Safety Draw 700.

T. Handling Codes for Wastes Listed Above
A-14
B-14
C-14
D-14

32. Special Handling Instructions and Additional Information

24 HOUR EMERGENCY TELEPHONE NUMBER (800) 424- 9300 (CHEMTREC).

DOT ERG#'s 28a)N/A b)N/A c)N/A d)N/A

TRANSPORTER

33. Transporter ___ Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

34. Transporter ___ Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

35. Discrepancy Indication Space

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST
(Continuation Sheet)

21. Generator's US EPA ID No.: CAD006610005
Manifest Document No.: 85742
22. Page: 2 of 2

Information in the shaded areas is not required by Federal law.

23. Generator's Name: Douglas Aircraft Company

L. State Manifest Document Number: 93385742

M. State Generator's ID: HAHQ36005600

24. Transporter ___ Company Name
25. US EPA ID Number
N. State Transporter's ID
O. Transporter's Phone

26. Transporter ___ Company Name
27. US EPA ID Number
P. State Transporter's ID
Q. Transporter's Phone

	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	HM	29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	(Cleaning compound,dry) Non-RCRA hazardous waste solid	X	003	DM	01255	P	181 N/R
b.	(510 Fluid) Non-RCRA hazardous waste liquid	X	003	DM	01120	P	141 N/R
c.	(Cobratec 99 Powder) Non-RCRA hazardous waste solid	X	001	DM	00344	P	352 N/R
d.	(Safety draw 700) Non-RCRA hazardous waste liquid	X	001	DM	00275	P	141 N/R
e.							
f.							
g.							
h.							
i.							

GENERATOR

S. Additional Descriptions for Materials Listed Above

28 a) OP18497 Cleaning compound dry, Isoprep 44 solid.
b) OP18498 Dow Corning 510 Fluid, 30,000cs.
c) OP18499 Cobratec 99 powder.
d) OP18757. Safety Draw 700

T. Handling Codes for Wastes Listed Above

D-14

32. Special Handling Instructions and Additional Information

24 HOUR EMERGENCY TELEPHONE NUMBER (800) 424-9300 (CHEMTREC)

DOT ERG#'s 28a) N/A b) N/A c) N/A d) N/A

TRANSPORTER

33. Transporter ___ Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

34. Transporter ___ Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

35. Discrepancy Indication Space

California—Environmental Protection Agency
Approved OMB No. 2050–0039 (Expires 9-30-94)
Please print or type. *Form designed for use on elite (12-pitch) typewriter.*

See Instructions on back of page 6.

Department of Toxic Substances Control
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD086510005 — Manifest Document No.: 85742
2. Page 1 of 2

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Company Attn: Rob Tuell M/S C6-59
19503 South Normandie Avenue, Torrance, CA 90502

4. Generator's Phone (310) 533-7926 OR (310) 533-7231

A. State Manifest Document Number: 93385742
B. State Generator's ID: HAHQ36005698

5. Transporter 1 Company Name: Laidlaw Environmental Services of CA, Inc.
6. US EPA ID Number: CAD000083121

C. State Transporter's ID: 423510
D. Transporter's Phone: (310) 518-4700

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Rollins OPC, Inc.
5756 Alba Street
Los Angeles, CA 90058

10. US EPA ID Number: CAD050806850

G. State Facility's ID
H. Facility's Phone: (213) 585-1971

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
a. RQ, waste organic peroxide type D, solid; 5.2; UN3106; PG II (Benzoyl Peroxide) (D001)	002	DM	00290	P	State 352; EPA/Other D001
b. RQ, waste poisonous solids, corrosive, n.o.s.; 6.1; UN2928; PG I (Copper Cyanide, Sodium Hydroxide)	002	DF	00531	P	State 241; EPA/Other P029
c. Waste poisonous solids, n.o.s.; 6.1; UN2811; PGII (P029, P104, P106)	001	DF	00105	P	State 181; EPA/Other P029
d. (Duraguard DF) Non-RCRA hazardous waste liquid	001	~~DM~~ DF (RES 05-20-94)	00120	P	State 331; EPA/Other N/A

J. Additional Descriptions for Materials Listed Above
11a. OP18660. Weld Off - 28 Comp. B.
b. OP18501. Cyanide and Sodium Hydroxide solid from tank 47.56.
c. OP18500. Cyanide contaminated debris.
d. OP17692. Foam-out, Duraguard DF. RES# 8284

K. Handling Codes for Wastes Listed Above
a. b. c. d.

15. Special Handling Instructions and Additional Information
24 Hour emergency telephone number (800)424-9300 (Chemtrec). DOT ERG#11a)48 b)59 c)53 d)N/A
Additional Codes 11b)P106 c)P104, P106

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Robert G. Tuell, Jr.	Robert G. Tuell, Jr.	05 20 94

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year
JACK JOHNSON	Jack Johnson	05 20 94

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month Day Year

DO NOT WRITE BELOW THIS LINE.

93385742

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7...

GENERATOR

TRANSPORTER

FACILITY

DTSC 8022A (7/92)
EPA 8700—22

Yellow: GENERATOR RETAINS

BOE-C6-0206663

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)	21. Generator's US EPA ID No. CAD086510005	Manifest Document No. 85742	22. Page 2 of 2	Information in the shaded areas is not required by Federal law.

Generator's Name: **Douglas Aircraft Company**

L. State Manifest Document Number: 93385742

M. State Generator's ID: HAHQ36005698

24. Transporter ___ Company Name | 25. US EPA ID Number | N. State Transporter's ID | O. Transporter's Phone

26. Transporter ___ Company Name | 27. US EPA ID Number | P. State Transporter's ID | Q. Transporter's Phone

	HM	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	X	(Cleaning compound,dry) Non-RCRA hazardous waste solid	003	DM	01255	P	181 N/R
b.	X	(510 Fluid) Non-RCRA hazardous waste liquid	003	DM	01120	P	141 N/R
c.	X	(Cobratec 99 Powder) Non-RCRA hazardous waste solid	001	DM	00344	P	352 N/R
d.	X	(Safety draw 700) Non-RCRA hazardous waste liquid	001	DM	00275	P	141 N/R
e.							
g.							
h.							
i.							

S. Additional Descriptions for Materials Listed Above

28 a)OP18497. Cleaning compound,dry, Isoprep 44 solid.
b)OP18498. Dow Corning 510 Fluid, 30,000cs.
c)OP18499. Cobratec 99 powder.
d)OP18757. Safety Draw 700.

T. Handling Codes for Wastes Listed Above

32. Special Handling Instructions and Additional Information

24 HOUR EMERGENCY TELEPHONE NUMBER (800) 424- 9300 (CHEMTREC).

DOT ERG#'s 28a)N/A b)N/A c)N/A d)N/A

TRANSPORTER

33. Transporter ___ Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

Transporter ___ Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

35. Discrepancy Indication Space

ROLLINS ENVIRONMENTAL SERVICES

LAND DISPOSAL RESTRICTION (LDR) NON-WASTEWATER NOTIFICATION

Section A, B, C, & D Completed by Generator (Instructions on Page 2)

SECTION A. GENERATOR NOTIFICATION

1. GENERATOR: DOUGLAS AIRCRAFT COMPANY
2. EPA I.D. NO.: CAD086510005
3. MANIFEST NO.: 93385742 / 85742
4. STREAM NO.: VARIOUS
5. PURSUANT TO 40 CFR §268.7, I am notifying (Check One):

☐ RES (NJ) ☐ RES (LA) ☐ RES (TX) ☐ RES of LA ☑ OPC ☐ TET

that under the above RES Waste Stream number, I am shipping to you one of the following types of waste.

(Check either (a) or (b) **only**):

a. ☑ A ***non-wastewater*** (other than contaminated debris) identified by the EPA waste code(s) and subcategory(ies) that I have checked in Section D. of this form. Submit Attachment 1 for F001-F005, F039, and California List wastes only.

b. ☐ A ***hazardous debris*** waste identified by the EPA waste code(s) and subcategory(ies) that I have checked in Section D. of this form. Submit Attachment 1 for F001-F005, F039, and California List wastes only.

PLEASE NOTE: Hazardous debris is solid material exceeding 60 mm particle size and which contains on its surface or in its pores a waste subject to the Land Disposal Restriction. (Regulatory Reference 40 CFR §268.2 [g] and [h]). The requirement for treatment of hazardous debris pursuant to 40 CFR §268.45 becomes effective May 8, 1993.

SECTION B. CALIFORNIA LIST APPLICABILITY FOR EPA HAZARDOUS WASTES

Check one or more box(es) below, if applicable (DOES NOT apply to ***newly listed*** wastes).

1. ☐ A D001-D011 liquid[1] or non-liquid waste containing halogenated organic compounds (HOCs) ≥ 1000 ppm as specified in 40 CFR §268, Appendix III.
2. ☐ A liquid[1] hazardous waste containing polychlorinated biphenyls (PCBs)[2] ≥ 50 ppm.
3. ☐ A D001-D017 liquid[1] waste containing ≥ 134 mg/l of nickel and/or ≥ 130 mg/l of thallium.
4. ☐ A liquid[1] or non-liquid hazardous waste subject to a National Capacity Variance which meets the definition of a California List Waste (Refer to Attachment 1 [page 2] for the California List definition).

[1] To determine whether a waste is liquid or contains ***free liquid***, use the Paint Filter Test (EPA SW-846, Method 9095).
[2] Incineration in a TSCA permitted incinerator [RES (TX) only].

SECTION C. GENERATOR CERTIFICATION (Authorized Representative)

I hereby certify and warrant that all the information supplied on this form and all associated documents represents a complete and accurate identification of this waste material.

1. Print or Type Name: Robert G. Tuell, Jr.
2. Date: 05 / 20 / 94
3. Signature: Robert G. Tuell, Jr.
4. Title: Sr. Plant Engineer

PLEASE NOTE: If your waste already meets relevant treatment standards or your waste is a wastewater or a Appendix IV or Appendix V Lab Pack, please contact your Rollins Sales/Customer Service office for the additional alternate certification form. For your convenience regional office addresses and phone numbers are listed on the back of Attachment 1.

© *Rollins Environmental Services (Sales) Inc. 1992*

Turn to Page

RES-50-423 REV 9/92

BOE-C6-0206665

INSTRUCTIONS

1. After completion of Sections A, B, and C on page 1, check *ALL* EPA waste codes applicable to this waste in Section D provided for you on pages 2, 3, and 4. For any waste codes not listed in Section D, additional space has been provided on page 4.

   PLEASE NOTE: In Section D you are only required to check the applicable EPA waste code listed under Column 1. Columns 2, 3, and 4 have been completed in advance by Rollins Environmental Services in accordance with the Land Disposal Restrictions.

2. Attachment 1, Notification of F001-F005, F039, and California List wastes, should be submitted only for those wastes.

DEFINITIONS

(As Referenced in Waste Treatment Standard Tables)

1. EPA WASTE CODE SUBCATEGORIES:

- A = Anhydrous
- ALK = Alkaline
- C = Corrosive
- CB = Cadmium Battery
- CS = Calcium Sulfate
- E = Explosives
- H = Hydrated
- HM = High Mercury (≥260 mg/kg)
- LB = Lead Acid Battery
- LIQ = Liquid
- LM = Low Mercury (<260 mg/kg)
- NCS = Non-Calcium Sulfate
- OX = Oxidizer
- R = Reactive
- RC = Reactive Cyanides
- RS = Reactive Sulfides
- S = Solid
- TOC = Total Organic Carbon
- WR = Water Reactive
- WW = Wastewater (<1% Total Organic Carbon and < 1% Total Suspended Solids)

2. TECHNOLOGY CODES:

- ADGAS = Venting of Compressed Gases followed by neutralization (INCIN acceptable technology)
- DEACT = Deactivation of hazardous characteristics (INCIN acceptable technology)
- IMERC = Incineration of organics and mercury contaminated waste
- INCIN = Incineration
- STABL = Stabilization

"D" CHARACTERISTIC WASTE CODES

Check

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
☐ D001GAS	N.A.	DEACT	N.A.
☑ D001LIQ <10%TOC	N.A.	DEACT	N.A.
☐ D001LIQ >10%TOC	N.A.	INCIN	N.A.
☐ D001OX	N.A.	DEACT	N.A.
☐ D001R	N.A.	DEACT	N.A.
☐ D002ACID	N.A.	DEACT	N.A.
☐ D002ALK	N.A.	DEACT	N.A.
☐ D002C	N.A.	DEACT	N.A.
D003E	DO NOT ACCEPT		
☐ D003R	N.A.	DEACT	N.A.
☐ D003RC	N.A.	N.A.	✓
☐ D003RS	N.A.	DEACT	N.A.
☐ D003WR	N.A.	DEACT	N.A.
☐ D004	✓	N.A.	N.A.
☐ D005	✓	N.A.	N.A.
☐ D006	✓	N.A.	N.A.
D006CB	DO NOT ACCEPT		
☐ D007	✓	N.A.	N.A.
D008LB	DO NOT ACCEPT		
☐ D008	✓	N.A.	N.A.
D009HM	DO NOT ACCEPT		
☐ D009LM	✓	N.A.	N.A.
☐ D010	✓	N.A.	N.A.
☐ D011	✓	N.A.	N.A.
☐ D012	N.A.	N.A.	✓
☐ D013	N.A.	N.A.	✓
☐ D014	N.A.	N.A.	✓

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	
☐ D016	N.A.	
☐ D016	N.A.	N.A.
☐ D017	N.A.	N.A.
☐ D018		
☐ D019		
☐ D020		
☐ D021		
☐ D022		
☐ D023		
☐ D024		
☐ D025		
☐ D026		
☐ D027		
☐ D028		
☐ D029		
☐ D030		
☐ D031		
☐ D032		
☐ D033		
☐ D034		
☐ D035		
☐ D036		
☐ D037		
☐ D038		
☐ D039		
☐ D040		
☐ D041		
☐ D042		
☐ D043		

NEWLY LISTE

WASTE

Not Currently Regul

Under

Land Disposal Restric

"F" LISTED WASTE CODES

Check All Applicable Wastes

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
☐ F001*	✓	N.A.	✓
☐ F002*	✓	N.A.	✓
☐ F003*	✓	N.A.	✓
☐ F004*	✓	N.A.	✓
☐ F005*	✓	INCIN**	✓
☐ F006	✓	N.A.	✓
☐ F007	✓	N.A.	✓
☐ F008	✓	N.A.	✓
☐ F009	✓	N.A.	✓
☐ F010	N.A.	N.A.	✓
☐ F011	✓	N.A.	✓
☐ F012	✓	N.A.	✓
☐ F019	✓	N.A.	✓
F020	DO NOT ACCEPT		

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH
F021	DO NOT ACCE	
F022	DO NOT ACCE	
F023	DO NOT ACCE	
☐ F024	✓	INCIN
☐ F025	N.A.	N.A.
F026	DO NOT ACCE	
F027	DO NOT ACCE	
F028	DO NOT ACCE	
☐ F032	NEWLY LISTED W	
☐ F034	Not Currently Req Under Land Disposal Res	
☐ F035		
☐ F037	National Capa Variance	
☐ F038		
☐ F039*	✓	N.A.

* Submit Attachment 1; see note in CCWE Table for F001-F005.

** INCIN only for 2-Nitropropane, 2-Ethyoxyethanol

Turn to

Check All Applicable Waste Code(s)

(1)	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
	✓	N.A.	✓
K002	✓	N.A.	N.A.
K	✓	N.A.	N.A.
K00	✓	N.A.	N.A.
K005	✓	N.A.	N.A.
K006A	✓	N.A.	N.A.
K006H	✓	N.A.	N.A.
K007	✓	N.A.	N.A.
K008	✓	N.A.	N.A.
K009	N.A.	N.A.	✓
K010	N.A.	N.A.	✓
K011	N.A.	N.A.	✓
K013	N.A.	N.A.	✓
K014	N.A.	N.A.	✓
K015	✓	N.A.	✓
K016	N.A.	N.A.	✓
K017	N.A.	N.A.	✓
K018	N.A.	N.A.	✓
K019	N.A.	N.A.	✓
K020	N.A.	N.A.	✓
K021	✓	N.A.	✓
K022	✓	N.A.	✓
K023	N.A.	N.A.	✓
K024	N.A.	N.A.	✓
025	N.A.	INCIN	N.A.
026	N.A.	INCIN	N.A.
027	N.A.	INCIN	N.A.
028	DO NOT ACCEPT		
029	N.A.	N.A.	✓
030	N.A.	N.A.	✓
031	✓	N.A.	N.A.
032	N.A.	N.A.	✓
033	N.A.	N.A.	✓
034	N.A.	N.A.	✓
035	N.A.	N.A.	✓
036	N.A.	N.A.	✓
037	N.A.	N.A.	✓
038	N.A.	N.A.	✓
039	N.A.	INCIN	N.A.
040	N.A.	N.A.	✓
041	N.A.	N.A.	✓
042	N.A.	N.A.	✓
043	DO NOT ACCEPT		
044	N.A.	DEACT	N.A.
045	N.A.	DEACT	N.A.
046	✓	N.A.	N.A.
047	N.A.	DEACT	N.A.
048	✓	N.A.	✓
049	✓	N.A.	✓
050	✓	N.A.	✓
051	✓	N.A.	✓
052	✓	N.A.	✓
060	N.A.	N.A.	✓
	DO NOT ACCEPT		
062	✓	N.A.	N.A.

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
☐ K064	NEWLY LISTED WASTE		
☐ K065	Not Currently Regulated Under Land Disposal Restrictions		
☐ K066			
☐ K069CS	✓	N.A.	N.A.
K069NCS	DO NOT ACCEPT		
☐ K071	✓	N.A.	N.A.
☐ K073	N.A.	N.A.	✓
☐ K083	✓	N.A.	✓
☐ K084	✓	N.A.	N.A.
☐ K085	N.A.	N.A.	✓
☐ K086	✓	N.A.	✓
☐ K087	✓	N.A.	✓
☐ K088	NEWLY LISTED WASTE		
☐ K090	Not Currently Regulated Under Land Disposal Regulations		
☐ K091			
☐ K093	N.A.	N.A.	✓
☐ K094	N.A.	N.A.	✓
☐ K095	N.A.	N.A.	✓
☐ K096	N.A.	N.A.	✓
☐ K097	N.A.	N.A.	✓
☐ K098	N.A.	N.A.	✓
K099	DO NOT ACCEPT		
☐ K100	✓	N.A.	N.A.
☐ K101	✓	N.A.	N.A.
☐ K102	✓	N.A.	✓
☐ K103	N.A.	N.A.	✓
☐ K104	N.A.	N.A.	✓
☐ K106	N.A.	N.A.	✓
K106HM	DO NOT ACCEPT		
☐ K106LM	✓	N.A.	N.A.
☐ K107	N.A.	INCIN	N.A.
☐ K108	N.A.	INCIN	N.A.
☐ K109	N.A.	INCIN	N.A.
☐ K110	N.A.	INCIN	N.A.
☐ K111	N.A.	N.A.	✓
☐ K112	N.A.	INCIN	N.A.
☐ K113	N.A.	INCIN	N.A.
☐ K114	N.A.	INCIN	N.A.
☐ K115	✓	INCIN	N.A.
☐ K116	N.A.	INCIN	N.A.
☐ K117	N.A.	N.A.	✓
☐ K118	N.A.	N.A.	✓
☐ K123	N.A.	INCIN	N.A.
☐ K124	N.A.	INCIN	N.A.
☐ K125	N.A.	INCIN	N.A.
☐ K126	N.A.	INCIN	N.A.
☐ K131	N.A.	N.A.	✓
☐ K132	N.A.	N.A.	✓
☐ K136	N.A.	N.A.	✓
☐ K141	NEWLY LISTED WASTE		
☐ K142			
☐ K143			
☐ K144			
☐ K145	Not Currently Regulated Under Land Disposal Restrictions		
☐ K147			
☐ K148			

"P" LISTED WASTE CODES

Check All Applicable Waste Code

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
☐ P001	N.A.	INCIN	N.A.
☐ P002	N.A.	INCIN	N.A.
☐ P003	N.A.	INCIN	N.A.
☐ P004	N.A.	N.A.	✓
☐ P005	N.A.	INCIN	N.A.
☐ P006	N.A.	INCIN	N.A.
☐ P007	N.A.	INCIN	N.A.
☐ P008	N.A.	INCIN	N.A.
☐ P009	N.A.	INCIN	N.A.
☐ P010	✓	N.A.	N.A.
☐ P011	✓	N.A.	N.A.
☐ P012	✓	N.A.	N.A.
☐ P013	✓	N.A.	✓
☐ P014	N.A.	INCIN	N.A.
P015	DO NOT ACCEPT		
☐ P016	N.A.	INCIN	N.A.
☐ P017	N.A.	INCIN	N.A.
☐ P018	N.A.	INCIN	N.A.
☐ P020	N.A.	N.A.	✓
☐ P021	N.A.	N.A.	✓
☐ P022	N.A.	INCIN	N.A.
☐ P023	N.A.	INCIN	N.A.
☐ P024	N.A.	N.A.	✓
☐ P026	N.A.	INCIN	N.A.
☐ P027	N.A.	INCIN	N.A.
☐ P028	N.A.	INCIN	N.A.
☑ P029	N.A.	N.A.	✓
☐ P030	N.A.	N.A.	✓
☐ P031	N.A.	INCIN	N.A.
☐ P033	N.A.	INCIN	N.A.
☐ P034	N.A.	INCIN	N.A.
☐ P036	✓	N.A.	N.A.
☐ P037	N.A.	N.A.	✓
☐ P038	✓	N.A.	N.A.
☐ P039	N.A.	N.A.	✓
☐ P040	N.A.	INCIN	N.A.
☐ P041	N.A.	INCIN	N.A.
☐ P042	N.A.	INCIN	N.A.
☐ P043	N.A.	INCIN	N.A.
☐ P044	N.A.	INCIN	N.A.
☐ P045	N.A.	INCIN	N.A.
☐ P046	N.A.	INCIN	N.A.
☐ P047	N.A.	INCIN	✓
☐ P048	N.A.	N.A.	✓
☐ P049	N.A.	INCIN	N.A.
☐ P050	N.A.	N.A.	✓
☐ P051	N.A.	N.A.	✓
☐ P054	N.A.	INCIN	N.A.
☐ P056	N.A.	ADGAS	N.A.
☐ P057	N.A.	INCIN	N.A.
☐ P058	N.A.	INCIN	N.A.
☐ P059	N.A.	N.A.	✓
☐ P060	N.A.	N.A.	✓
☐ P062	N.A.	INCIN	N.A.

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43
☐ P063	N.A.	N.A.	✓
☐ P064	N.A.	NCIN	N
P065HM	DO NOT ACCEPT		
☐ P065LM	✓	IMERC	N
☐ P066	N.A.	INCIN	N
☐ P067	N.A.	NCIN	N
☐ P068	N.A.	NCIN	N
☐ P069	N.A.	NCIN	N
☐ P070	N.A.	NCIN	N
☐ P071	N.A.	N.A.	✓
☐ P072	N.A.	NCIN	N
☐ P073	✓	N.A.	N
☐ P074	✓	N.A.	✓
☐ P075	N.A.	INCIN	N
P076	DO NOT ACCEPT		
☐ P077	N.A.	N.A.	✓
P078	DO NOT ACCEPT		
☐ P081	N.A.	NCIN	N
☐ P082	N.A.	NCIN	N
☐ P084	N.A.	NCIN	N
☐ P085	N.A.	NCIN	N
P087	DO NOT ACCEPT		
☐ P088	N.A.	NCIN	N
☐ P089	N.A.	N.A.	✓
P092HM	DO NOT ACCEPT		
☐ P092LM	✓	MERC	N
☐ P093	N.A.	NCIN	N
☐ P094	N.A.	N.A.	✓
☐ P095	N.A.	NCIN	N
☐ P096	N.A.	NCIN	N
☐ P097	N.A.	N.A.	✓
☐ P098	N.A.	N.A.	✓
☐ P099	✓	N.A.	✓
☐ P101	N.A.	N.A.	✓
☐ P102	N.A.	NCIN	N
☐ P103	✓	N.A.	N
☑ P104	✓	N.A.	✓
☐ P105	N.A.	INCIN	N
☑ P106	N.A.	N.A.	✓
☐ P108	N.A.	INCIN	N
☐ P109	N.A.	INCIN	N
☐ P110	✓	N.A.	N
☐ P111	N.A.	INCIN	N
☐ P112	N.A.	INCIN	N
☐ P113	N.A.	STABL	N
☐ P114	✓	N.A.	N
☐ P115	N.A.	STABL	N
☐ P116	N.A.	INCIN	N
☐ P118	N.A.	INCIN	N
☐ P119	N.A.	STABL	N
☐ P120	N.A.	STABL	N
☐ P121	N.A.	N.A.	✓
☐ P122	N.A.	NCIN	N
☐ P123	N.A.	N.A.	✓

Turn to Page

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
U001	N.A.	INCIN	N.A.
U002	N.A.	N.A.	✓
U003	N.A.	INCIN	N.A.
U004	N.A.	N.A.	✓
U005	N.A.	N.A.	✓
U006	N.A.	INCIN	N.A.
U007	N.A.	INCIN	N.A.
U008	N.A.	INCIN	N.A.
U009	N.A.	N.A.	✓
U010	N.A.	INCIN	N.A.
U011	N.A.	INCIN	N.A.
U012	N.A.	N.A.	✓
U014	N.A.	INCIN	N.A.
U015	N.A.	INCIN	N.A.
U016	N.A.	INCIN	N.A.
U017	N.A.	INCIN	N.A.
U018	N.A.	N.A.	✓
U019	N.A.	N.A.	✓
U020	N.A.	INCIN	N.A.
U021	N.A.	INCIN	N.A.
U022	N.A.	N.A.	✓
U023	N.A.	INCIN	N.A.
U024	N.A.	N.A.	✓
U025	N.A.	N.A.	✓
U026	N.A.	INCIN	N.A.
U027	N.A.	N.A.	✓
U028	N.A.	N.A.	✓
U029	N.A.	N.A.	✓
U030	N.A.	N.A.	✓
U031	N.A.	N.A.	✓
U032	✓	N.A.	N.A.
U033	N.A.	INCIN	N.A.
U034	N.A.	INCIN	N.A.
U035	N.A.	INCIN	N.A.
U036	N.A.	N.A.	✓
U037	N.A.	N.A.	✓
U038	N.A.	INCIN	N.A.
U039	N.A.	N.A.	✓
U041	N.A.	INCIN	N.A.
U042	N.A.	INCIN	N.A.
U043	N.A.	N.A.	✓
U044	N.A.	N.A.	✓
U045	N.A.	N.A.	✓
U046	N.A.	INCIN	N.A.
U047	N.A.	N.A.	✓
U048	N.A.	N.A.	✓
U049	N.A.	INCIN	N.A.
U050	N.A.	N.A.	✓
U051	✓	N.A.	✓
U052	N.A.	N.A.	✓
U053	N.A.	INCIN	N.A.
U055	N.A.	INCIN	N.A.
U056	N.A.	INCIN	N.A.
U057	N.A.	INCIN	N.A.
U058	N.A.	INCIN	N.A.
U059	N.A.	INCIN	N.A.
U060	N.A.	N.A.	✓
U061	N.A.	N.A.	✓

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
U062	N.A.	INCIN	N.A.
U063	N.A.	N.A.	✓
U064	N.A.	INCIN	N.A.
U066	N.A.	N.A.	✓
U067	N.A.	N.A.	✓
U068	N.A.	N.A.	✓
U069	N.A.	N.A.	✓
U070	N.A.	N.A.	✓
U071	N.A.	N.A.	✓
U072	N.A.	N.A.	✓
U073	N.A.	INCIN	N.A.
U074	N.A.	INCIN	N.A.
U075	N.A.	N.A.	✓
U076	N.A.	N.A.	✓
U077	N.A.	N.A.	✓
U078	N.A.	N.A.	✓
U079	N.A.	N.A.	✓
U080	N.A.	N.A.	✓
U081	N.A.	N.A.	✓
U082	N.A.	N.A.	✓
U083	N.A.	N.A.	✓
U084	N.A.	N.A.	✓
U085	N.A.	INCIN	N.A.
U086	N.A.	INCIN	N.A.
U087	N.A.	INCIN	N.A.
U088	N.A.	N.A.	✓
U089	N.A.	INCIN	N.A.
U090	N.A.	INCIN	N.A.
U091	N.A.	INCIN	N.A.
U092	N.A.	INCIN	N.A.
U093	N.A.	INCIN	N.A.
U094	N.A.	INCIN	N.A.
U095	N.A.	INCIN	N.A.
U096	N.A.	INCIN	N.A.
U097	N.A.	INCIN	N.A.
U098	N.A.	INCIN	N.A.
U099	N.A.	INCIN	N.A.
U101	N.A.	N.A.	✓
U102	N.A.	N.A.	✓
U103	N.A.	INCIN	N.A.
U105	N.A.	N.A.	✓
U106	N.A.	N.A.	✓
U107	N.A.	N.A.	✓
U108	N.A.	N.A.	✓
U109	N.A.	INCIN	N.A.
U110	N.A.	INCIN	N.A.
U111	N.A.	N.A.	✓
U112	N.A.	N.A.	✓
U113	N.A.	INCIN	N.A.
U114	N.A.	INCIN	N.A.
U115	N.A.	INCIN	N.A.
U116	N.A.	INCIN	N.A.
U117	N.A.	N.A.	✓
U118	N.A.	N.A.	✓
U119	N.A.	INCIN	N.A.
U120	N.A.	N.A.	✓
U121	N.A.	N.A.	✓
U122	N.A.	INCIN	N.A.

(1) EPA CODE NUMBER	(2) 40 CFR §268.41 CCWE	(3) 40 CFR §268.42 TECH	(4) 40 CFR §268.43 CCW
U123	N.A.	INCIN	N.A.
U124	N.A.	INCIN	N.A.
U125	N.A.	INCIN	N.A.
U126	N.A.	INCIN	N.A.
U127	N.A.	N.A.	✓
U128	N.A.	N.A.	✓
U129		N.A.	✓
U130	N.A.	N.A.	✓
U131	N.A.	N.A.	✓
U132	N.A.	INCIN	N.A.
U133	N.A.	INCIN	N.A.
U134	N.A.	ADGAS	N.A.
U135	N.A.	INCIN	N.A.
U136	✓	N.A.	N.A.
U137	N.A.	N.A.	✓
U138	N.A.	N.A.	✓
U140	N.A.	N.A.	✓
U141	N.A.	N.A.	✓
U142	N.A.	N.A.	✓
U143	N.A.	INCIN	N.A.
U144	✓	N.A.	N.A.
U145	✓	N.A.	N.A.
U146	✓	N.A.	N.A.
U147	N.A.	INCIN	N.A.
U148	N.A.	INCIN	N.A.
U149	N.A.	INCIN	N.A.
U150	N.A.	INCIN	N.A.
U151HM	DO NOT ACCEPT		
U151LM	✓	N.A.	N.A.
U152	N.A.	N.A.	✓
U153	N.A.	INCIN	N.A.
U154	N.A.	INCIN	N.A.
U155	N.A.	N.A.	✓
U156	N.A.	INCIN	N.A.
U157	N.A.	N.A.	✓
U158	N.A.	N.A.	✓
U159	N.A.	N.A.	✓
U160	N.A.	INCIN	N.A.
U161	N.A.	N.A.	✓
U162	N.A.	N.A.	✓
U163	N.A.	INCIN	N.A.
U164	N.A.	INCIN	N.A.
U165	N.A.	N.A.	✓
U166	N.A.	INCIN	N.A.
U167	N.A.	INCIN	N.A.
U168	N.A.	INCIN	N.A.
U169	N.A.	N.A.	✓
U170	N.A.	N.A.	✓
U171	N.A.	INCIN	N.A.
U172	N.A.	N.A.	✓
U173	N.A.	INCIN	N.A.
U174	N.A.	N.A.	✓
U176	N.A.	INCIN	N.A.
U177	N.A.	INCIN	N.A.
U178	N.A.	INCIN	N.A.
U179	N.A.	N.A.	✓
U180	N.A.	N.A.	✓
U181	N.A.	N.A.	✓

EPA CODE NUMBER	40 CFR §268.41 CCWE	40 CFR §268.42 TECH
U182	N.A.	
U183	N.A.	
U184	N.A.	
U185	N.A.	
U186	N.A.	INCIN
U187	N.A.	N.A.
U188	N.A.	N.A.
U189	N.A.	INCIN
U190	N.A.	N.A.
U191	N.A.	INCIN
U192	N.A.	N.A.
U193	N.A.	INCIN
U194	N.A.	INCIN
U196	N.A.	N.A.
U197	N.A.	INCIN
U200	N.A.	INCIN
U201	N.A.	INCIN
U202	N.A.	INCIN
U203	N.A.	N.A.
U204	✓	N.A.
U205	✓	N.A.
U206	N.A.	INCIN
U207	N.A.	N.A.
U208	N.A.	N.A.
U209	N.A.	N.A.
U210	N.A.	N.A.
U211	N.A.	N.A.
U213	N.A.	INCIN
U214	N.A.	STABL
U215	N.A.	STABL
U216	N.A.	STABL
U217	N.A.	STABL
U218	N.A.	INCIN
U219	N.A.	INCIN
U220	N.A.	N.A.
U221	N.A.	INCIN
U222	N.A.	INCIN
U223	N.A.	INCIN
U225	N.A.	N.A.
U226	N.A.	N.A.
U227	N.A.	N.A.
U228	N.A.	N.A.
U234	N.A.	INCIN
U235	DO NOT ACCEPT	
U236	N.A.	INCIN
U237	N.A.	INCIN
U238	N.A.	INCIN
U239	N.A.	N.A.
U240	N.A.	INCIN
U243	N.A.	N.A.
U244	N.A.	INCIN
U246	N.A.	INCIN
U247	N.A.	N.A.
U248	N.A.	INCIN
U249	N.A.	INCIN
U328	N.A.	INCIN
U353	N.A.	INCIN
U359	N.A.	INCIN

EMERGENCY RESPONSE GUIDE FORM

D.O.T. EMERGENCY RESPONSE GUIDE 48

(FOLD ON DOTTED LINE—STAPLE TO HAZARDOUS MATERIALS SHIPPING PAPER)

Use basic description and technical name as described in 49 CFR 172.202 and 172.203 (K).

Basic Description: RQ, waste organic peroxide type D, solid, 5.2, UN3106, PGII

Technical Name(s): BENZOYL PEROXIDE

24 hr. Emergency Contact Tel. No.: 800-424-9300 (Chemtrec)

EMERGENCY RESPONSE GUIDE FORM

D.O.T. EMERGENCY RESPONSE GUIDE 48

POTENTIAL HAZARDS

FIRE OR EXPLOSION

May be ignited by heat, sparks or flames.
Container may explode in heat of fire.
May explode from heat or contamination.
Runoff to sewer may create fire or explosion hazard.

HEALTH HAZARDS

Contact may cause burns to skin and eyes.
Fire may produce irritating or poisonous gases.
Runoff from fire control or dilution water may cause pollution.

EMERGENCY ACTION

Keep unnecessary people away; isolate hazard area and deny entry.
Stay upwind; keep out of low areas.
Positive pressure self-contained breathing apparatus (SCBA) and structural firefighters' protective clothing will provide limited protection.
CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE.
If water pollution occurs, notify the appropriate authorities.

FIRE

Small Fires: Dry chemical, CO_2, water spray or regular foam.
Large Fires: Flood fire area with water.
Apply cooling water to sides of containers that are exposed to flames until well after fire is out. Stay away from ends of tanks.
For massive fire in cargo area, use unmanned hose holder or monitor nozzles; if this is impossible, withdraw from area and let fire burn.

SPILL OR LEAK

Shut off ignition sources; no flares, smoking or flames in hazard area.
Do not touch or walk through spilled material; stop leak if you can do it without risk.
Small Spills: Take up with inert, damp noncombustible material; move containers from spill area.
Large Spills: Wet down with water and dike for later disposal.

FIRST AID

Move victim to fresh air; call emergency medical care.
In case of contact with material, immediately flush eyes with running water for at least 15 minutes. Wash skin with soap and water.
Remove and isolate contaminated clothing and shoes at the site.
Keep victim quiet and maintain normal body temperature.

Information on this Guide Page is from the 1990 Emergency Response Guidebook Dot P 5800.5. It applies only to the basic Description and Technical Name entered by the shipper at the top of this form.

Check to see whether the shipper commodity (Basic description entered at the top of this form) is listed by **I.D.# and NAME OF THE MATERIAL** in the **Table of Initial Isolation and Protective Action Distances**. This Table is partially reproduced on the back of this Guide Page to reflect only commodities assigned to this Guide Number. Use this information from the table in addition to the Guide Page **IF THERE IS NO FIRE**.

READ AND CHECK THE NAMES AND NUMBERS CAREFULLY BECAUSE COMPLETELY DIFFERENT HAZARDOUS MATERIALS CAN HAVE NAMES AND/OR NUMBERS WHICH ARE ALMOST THE SAME!

ERF 48 Printed by LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646 (800) 621-5808

...ctions on back of page 6.

Manifest Document No. 85742 | 2. Page 1 of 2

A. State Manifest Document
B. State Generator's ID HAH030
C. State Transporter's ID
D. Transporter's Phone
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID
H. Facility's Phone

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
2	DM	00290	P
2	DF	00531	P
	DF	00105	P
	DF	00120	P

K. Handling Codes for Wastes Listed Above
b.
d.

ERG#11a)48 b)59 c)53 d)N/A

...ed above by proper shipping name and are classified, ...le federal, state and international laws.

...te generated to the degree I have determined to be ...ilable to me which minimizes the present and future ...o minimize my waste generation and select the best

Month 05 Day 20 Year 94

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as ...

Printed/Typed Name

Signature

Month Day Year

Month Day Year

C 8022A (9/92)

BOE-C6-0206669

D.O.T. EMERGENCY RESPONSE GUIDE 53

(FOLD ON DOTTED LINE—STAPLE TO HAZARDOUS MATERIALS SHIPPING PAPER)

Use basic description and technical name as described in 49 CFR 172.202 and 172.203 (K).

Basic Description: RQ, waste poisonous solids, corrosive n.o.s., 6.1, UN2928, PG1

Technical Name(s): Copper Cyanide, Sodium Hydroxide

EMERGENCY RESPONSE GUIDE FORM

24 hr. Emergency Contact Tel. No.: 800-424-9300 (Chemtrec)

D.O.T. EMERGENCY RESPONSE GUIDE 53

POTENTIAL HAZARDS

HEALTH HAZARDS

Poisonous if swallowed.
Inhalation of dust poisonous.
Fire may produce irritating or poisonous gases.
Runoff from fire control or dilution water may cause pollution.

FIRE OR EXPLOSION

Some of these materials may burn, but none of them ignites readily.

EMERGENCY ACTION

Keep unnecessary people away; isolate hazard area and deny entry.
Stay upwind; keep out of low areas.
Positive pressure self-contained breathing apparatus (SCBA) and structural firefighters' protective clothing will provide limited protection.
CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE.
If water pollution occurs, notify the appropriate authorities.

FIRE

Small Fires: Dry chemical, CO2, water spray or regular foam.
Large Fires: Water spray, fog or regular foam.
Move container from fire area if you can do it without risk.

SPILL OR LEAK

Do not touch or walk through spilled material; stop leak if you can do it without risk.
Small Spills: Take up with sand or other noncombustible absorbent material and place into containers for later disposal.
Small Dry Spills: With clean shovel place material into clean, dry container and cover loosely; move containers from spill area.
Large Spills: Dike far ahead of liquid spill for later disposal.

FIRST AID

Move victim to fresh air; call emergency medical care.
In case of contact with material, immediately flush skin or eyes with running water for at least 15 minutes.
Remove and isolate contaminated clothing and shoes at the site.

Information on this Guide Page is from the 1990 Emergency Response Guidebook Dot P 5800.5. It applies only to the basic Description and Technical Name entered by the shipper at the top of this form.

Check to see whether the shipper commodity (Basic description entered at the top of this form) is listed by **I.D.# and NAME OF THE MATERIAL** in the **Table of Initial Isolation and Protective Action Distances.** This Table is partially reproduced on the back of this Guide Page to reflect only commodities assigned to this Guide Number. Use this information from the table in addition to the Guide Page **IF THERE IS NO FIRE.**

READ AND CHECK THE NAMES AND NUMBERS CAREFULLY BECAUSE COMPLETELY DIFFERENT HAZARDOUS MATERIALS CAN HAVE NAMES AND/OR NUMBERS WHICH ARE ALMOST THE SAME!

ERF 53 Printed by LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646 (800) 621-5808

...ee Instructions on back of page 6.

Manifest Document No. 0005 85742

S C6-59
02
3-7231
Number 00083121
Number
Number 50806850

A. State Manifest D
B. State Generator's HAH
C. State Transporter'
D. Transporter's Phon
E. State Transporter's
F. Transporter's Phone
G. State Facility's ID
H. Facility's Phone

...umber)	12. Containers No.	Type	13. Total Quantity
...2;	002	DM	0029
...; 6.1; ...droxide)	002	DF	0053
PGII	001	DF	0010
	001	~~DM~~ DF	0012

...ank 47,56.
8284

K. Handling Codes for Wa...
a.
c.

...0 (Chemtrec). DOT ERG#11a)48

...ent are fully and accurately described above by proper shi...
...rt by highway according to applicable federal, state and int...

...duce the volume and toxicity of waste generated to the de...
...nt, storage, or disposal currently available to me which mi...
...r, I have made a good faith effort to minimize my waste

...obert G. Tuell, Jr.

IN CAS...

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

BOE-C6-0206670

D.O.T. EMERGENCY RESPONSE GUIDE 59

(FOLD ON DOTTED LINE—STAPLE TO HAZARDOUS MATERIALS SHIPPING PAPER)

Use basic description and technical name as described in 49 CFR 172.202 and 172.203 (K).

Basic Description: Waste poisonous solids, n.o.s. 6.1, UN2811, PG11

Technical Name(s): Cyanide contaminated debris

24 hr. Emergency Contact Tel. No.: 800-424-9300 (chemtrec)

EMERGENCY RESPONSE GUIDE FORM

D.O.T. EMERGENCY RESPONSE GUIDE 59

POTENTIAL HAZARDS

HEALTH HAZARDS
- Poisonous if inhaled or swallowed.
- Skin contact poisonous.
- Contact may cause burns to skin and eyes.
- Fire may produce irritating or poisonous gases.
- Runoff from fire control or dilution water may cause pollution.

FIRE OR EXPLOSION
- Some of these materials may burn, but none of them ignites readily.
- Some of these materials may ignite combustibles (wood, paper, oil, etc.).

EMERGENCY ACTION

- Keep unnecessary people away; isolate hazard area and deny entry.
- Stay upwind; keep out of low areas.
- Positive pressure self-contained breathing apparatus (SCBA) and chemical protective clothing which is specifically recommended by the shipper or manufacturer may be worn. It may provide little or no thermal protection.
- Structural firefighters' protective clothing is **not** effective for these materials.
- **CALL CHEMTREC AT 1-800-424-9300** AS SOON AS POSSIBLE, especially if there is no local hazardous materials team available.

FIRE
- Some of these materials may react violently with water.
- **Small Fires:** Dry chemical, CO2, water spray or regular foam.
- **Large Fires:** Water spray, fog or regular foam.
- Move container from fire area if you can do it without risk.
- Apply cooling water to sides of containers that are exposed to flames until well after fire is out. Stay away from ends of tanks.

SPILL OR LEAK
- Do not touch or walk through spilled material; stop leak if you can do it without risk.
- Fully-encapsulating, vapor-protective clothing should be worn for spills and leaks with no fire.
- Use water spray to reduce vapors.
- **Small Spills:** Take up with sand or other noncombustible absorbent material and place into containers for later disposal.
- **Large Spills:** Dike liquid spill for later disposal.

FIRST AID
- Move victim to fresh air and call emergency medical care; if not breathing, give artificial respiration; if breathing is difficult, give oxygen.
- In case of contact with material, immediately flush skin or eyes with running water for at least 15 minutes.
- Remove and isolate contaminated clothing and shoes at the site.
- Keep victim quiet and maintain normal body temperature.
- Effects may be delayed; keep victim under observation.

Information on this Guide Page is from the 1990 Emergency Response Guidebook Dot P 5800.5. It applies only to the basic Description and Technical Name entered by the shipper at the top of this form.

Check to see whether the shipper commodity (Basic description entered at the top of this form) is listed by **I.D.# and NAME OF THE MATERIAL** in the **Table of Initial Isolation and Protective Action Distances.** This Table is partially reproduced on the back of this Guide Page to reflect only commodities assigned to this Guide Number. Use this information from the table in addition to the Guide Page **IF THERE IS NO FIRE.**

READ AND CHECK THE NAMES AND NUMBERS CAREFULLY BECAUSE COMPLETELY DIFFERENT HAZARDOUS MATERIALS CAN HAVE NAMES AND/OR NUMBERS WHICH ARE ALMOST THE SAME!

ERF 59 Printed by LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646 (800) 621-5808

e Instructions on back of page 6.

Manifest Document No. 005 85742 | 2. Page of

C6-59
2
-7231
Number 00083121
umber
umber 0806850

A. State Manifest Docu
B. State Generator's ID HAHQ
C. State Transporter's ID
D. Transporter's Phone
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID
H. Facility's Phone

ber)	12. Containers No.	Type	13. Total Quantity
	002	DM	00290
6.1; roxide)	002	DF	00531
GII	001	DF	00105
	001	RGJ 05-20-94 ~~DM~~ DF	00120

k 47,56.
284

K. Handling Codes for Wast
a.
c.

(Chemtrec). DOT ERG#11a)48

are fully and accurately described above by proper shi highway according to applicable federal, state and in

the volume and toxicity of waste generated to the d storage, or disposal currently available to me which m have made a good faith effort to minimize my waste

Lat G. Tuell, Jr.

19. Discrepancy Indication Space

IN CASE FACI

BOE-C6-0206671

LAIDLAW ENVIRONMENTAL SERVICES

Laidlaw Environmental Services of California, Inc.

SERVICE ORDER 92 78599

JOB NO. 270120

DATE 05/20/94.

TRANSPORTATION SERVICE ORDER

Transportation ID #: CAD000083121

☐ 4501 Pacheco Blvd.
Martinez, CA 94553
(510) 372-4800

☐ 3237 Patton Way
Bakersfield, CA 93308
(805) 835-5801 or
(805) 589-4970

☐ 221 E. "D" Street
Wilmington, CA 90744
(310) 518-4700

Customer Name: DOUGLAS AIR

Telephone:

Billing Address:

Contact Person:

City: TORRANCE State CA

BOE #:

Job Location: BUILDING 45

Destination:

Type of Material: DRUMS

Sales Person:

Generator: DOUGLAS AIR

EPA Number:

Generator ID Number (State):

Facility EPA NO.:

Disposal: LES Facility ____ Outside Facility ____ None ____

Customer P.O. 27064-H605 05-20-94

Manifest # ____ # ____ # ____ # ____

Services Performed PICK UP DRUMS AT DOUGLAS AND DELIVER TO CHEMTECH, ENSCO, ROLLINS. + RETURN TO YARD

Start Miles: 278732

End Miles:

Total Miles:

Truck No.: 16061

Trailer No: 16036T

Net Wgt:

Capacity:

Driver Time: Start (AM/PM) 0600

Stop (AM/PM)

Gross Time

Meals: Start Time (AM/PM)

Stop (AM/PM)

Less Time

Other Time

Detail

Adj. Time

Driver's Name JACK JOHNSON

Driver No.

Total Time

Customer Site: Time In 0700

Disposal Site: Time In

Time In

Time Out 13:00

Time Out

Time Out

Explanation of Time:

CUSTOMER AUTHORIZATION AND APPROVAL SIGNATURE: Robert G. Insell, Jr. 05-20-94

FOR ACCOUNTING ONLY

PROD CODE	DESCRIPTION	QTY	UOM	RATE	EXT	PROD CODE	DESCRIPTION	QTY	UOM	RATE	EXT
14000	TRANS		ST			24015	HAZ SOLIDS				
14000	TRANS		OT			24015	N/HAZ SOLIDS				
14000	TRANS		DT			24010	HAZ LIQUIDS				
	2ND DRIVER					24010	N/HAZ LIQUIDS				
	SUBHAULER					24020	DRUMS				
54045	LABOR					24025	SOLID SURCHG				
94065	BIN RENTAL					24025	STABILIZATION				
14000	TRANS (NO DISP)					24025	LIQ SURCHG				
14000	WASHOUT						TAXES				
14000	SCALE/CERTS						TAXES				
14000	SUBSISTENCE					34035	ANALYTICAL				
74055	TOLLS					74055	MISC CHARGES				
90465	TYVEK					74055	MISC CHARGES				
90465	BOOTS										
90465	GOGGLES										
90465	GLOVES										
90465	BIN LINERS										
70455	OTHERS										

WHITE-BAKERSFIELD ACCTNG WHITE-FACILITY FILE PINK-CUSTOMER COPY CANARY-FACILITY ACCTNG

This work order was used to transport the following manifest numbers:

93385741 - Chem-Tech
93385744 - Rho-Chem
93385742 - Rollins OPC
93385743 - Rollins OPC

print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)

21. Generator's US EPA ID No.: CAD086510005

Manifest Document No.: 85742

22. Page: 2 of 2

Information in the shaded areas is not required by Federal law.

23. Generator's Name: Douglas Aircraft Company

L. State Manifest Document Number: 93385742

M. State Generator's ID: HAHQ36005698

24. Transporter ___ Company Name

25. US EPA ID Number

N. State Transporter's ID

O. Transporter's Phone

26. Transporter ___ Company Name

27. US EPA ID Number

P. State Transporter's ID

Q. Transporter's Phone

GENERATOR

	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	HM	29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	(Cleaning compound,dry) Non-RCRA hazardous waste solid	N	003	DM	01255	P	181 N/R
b.	(510 Fluid) Non-RCRA hazardous waste liquid	N	003	DM	01120	P	141 N/R
c.	(Cobratec 99 Powder) Non-RCRA hazardous waste solid	N	001	DM	00344	P	352 N/R
d.	(Safety draw 700) Non-RCRA hazardous waste liquid	N	001	DM	00275	P	141 N/R
e.							
f.							
g.							
h.							
i.							

S. Additional Descriptions for Materials Listed Above

28 a) OP 18497 Cleaning compound, dry, Isoprep 44 solid
b) OP 18498 Dow Corning 510 Fluid 30,000cs
c) OP 18499 Cobratec 99 powder
d) OP 18757 Safety Draw 700.

T. Handling Codes for Wastes Listed Above

32. Special Handling Instructions and Additional Information

24 HOUR EMERGENCY TELEPHONE NUMBER (800) 424-9300 (CHEMTREC)

DOT ERG#'s 28a) N/A b N/A c) N/A d N/A

TRANSPORTER

33. Transporter ___ Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

34. Transporter ___ Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

35. Discrepancy Indication Space

Style F16 REV-6 LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646

EPA Form 8700-22A (Rev. 9-88) Previous editions are obsolete.

BOE-C6-0206673

print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)	21. Generator's US EPA ID No. CAD086510005	Manifest Document No. 85742	22. Page 2 of 2	Information in the shaded areas is not required by Federal law.

23. Generator's Name: Douglas Aircraft Company

L. State Manifest Document Number: 93385742

M. State Generator's ID: HAHQ36005698

24. Transporter ___ Company Name | 25. US EPA ID Number

N. State Transporter's ID

O. Transporter's Phone

26. Transporter ___ Company Name | 27. US EPA ID Number

P. State Transporter's ID

Q. Transporter's Phone

	HM	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.		(Cleaning compound,dry) Non-RCRA hazardous waste solid	003	DM	01255	P	191 N/R
b.		(510 Fluid) Non-RCRA hazardous waste liquid	003	DM	01120	P	141 N/R
c.		(Cobratec 99 Powder) Non-RCRA hazardous waste solid	001	DM	00344	P	352 N/R
d.		(Safety draw 700) Non-RCRA hazardous waste liquid	001	DM	00275	P	141 N/R
e.							
f.							
g.							
h.							
i.							

GENERATOR

S. Additional Descriptions for Materials Listed Above

28 a) OP 18497 Cleaning compound, dry, Isoprep 44 solid
b) OP 18498 Dow Corning 510 Fluid 30,000 cs.
c) OP 18499 Cobratec 99 powder
d) OP 18757 Safety Draw 700.

T. Handling Codes for Wastes Listed Above

32. Special Handling Instructions and Additional Information

24 HOUR EMERGENCY TELEPHONE NUMBER (800) 424-9300 (CHEMTREC)

DOT ERG#'s 28a) N/A b) N/A c) N/A d) N/A

TRANSPORTER

33. Transporter ___ Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

34. Transporter ___ Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

35. Discrepancy Indication Space

Style F16 REV-6 LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646

EPA Form 8700-22A (Rev. 9-88) Previous editions are obsolete.

BOE-C6-0206674