HAZARDOUS WASTE LOG SHEET

PAGE: 5 OF 5 LOCATION: C6 TORRANCE MONTH: _____ YR: _____

MANIFEST NO.	DATE MANIFESTED	TRANSPORTER	DAC TANK NO.	CONTENTS	QUANTITY	CAT. NO./ DOT CLASS	DATE MANIF. RTN.	TSDF	DISP METHOD	TAX CAT.	ACTUAL QUANTITY	DISPOSAL CHARGE	TRANSP. CHARGE	TOTAL CHARGE
BOL	5/17/94	Mercury Recovery Services		Fluorescent Light tubes	2 HID Lamps 1,095 Ft		NOT REQUIRED	Mercury Recovery Services Inc						
AR635302 / 35302	5/31/94	Laidlaw Env. Services, Inc.		11a) Paint Sludge b) Sealant tubes c) Production Rags d) Paint Filters and solids 28a) BF Goodrich b) Pre Impreg.	3 drums 1 drums 1 drums 8 drums 1 drums 2 drums	3,461, Dow, Fuels-Fuel 9,352, Dow, Dow's Dow's 9,352, Fuels, Dow's Dow's 9,352, Dow, 9,352, D008 N/R, 352	06-21-94	Rineco Chemical Ind. Inc.			NOTE: RINECO CHANGED CODES - SEE RETD. COPY			
01766/92301766	5/31/94	Laidlaw Env. Services Inc.	Tank 252	RQ, Waste Sodium Hydroxide Solution, 8, UN1824, PG II (D002)	45,510 P	121 D002	06-23-94	Norris Env. Services			NO DISCR NOTED ON RETD COPY OF MFST.			
85761/93385761	5/31/94	Laidlaw Env. Services		Lead Dross	1 DM 630 P	181 D008	06/09/94	Quemetco Inc			NO DISCR NOTED ON RETD. COPY OF MFST.			
85771/93385771	5/31/94	Laidlaw Env. Services, Inc.		Kolene	2 DF 605 P	181 D001 TO	DRUMS WERE REJECTED	Appropriate Technologies Inc.						
NOTE: THESE DRUMS WERE RETURNED TO DAC DUE RADIOACTIVE READINGS														
01765 92301765	5/31/94	Disposal Control Ind.	Tank 95 (Was being stored in Baker tank)	RQ, Waste Corrosive Liquid N.O.S., (Nitric Acid, HF acid), 8, UN1760 PG III (D002, D007)	19,250 P	D002 D007 792	06-23-94	Norris Environmental Services			NOTE: DISCREPANCY ~~ADDE~~ TSDF ADDED D006			
01767 92301767	5/31/94	Laidlaw Environmental Services Inc	Tank 252 and 257	RQ, Waste Sodium Hydroxide Solution, 8, UN1824, PG II (D002)	17,740 P	121 D002	06-23-94	Norris Environmental Services Inc.			NO DISCR. NOTED ON RETD. COPY OF MFST.			

LOCATION: C6 MONTH: May YR: 1994

PAGE: 5 OF 5

DATE BLUE COPY MAILED TO DTSC

BOE-C6-0206806