KENDALL ONE FEDERAL STREET, BOSTON, MASSACHUSETTS 02110-2003 (617) 574-7000
CABLE: KENDALL
TELEX: 94-0503

December 1, 1987

Mr. Jay Estep
Sid Sterne Company
22622 Lambert Street
Suite 301-B
El Toro, CA 92630

Dear Mr. Estep:

We have received your request for Material Safety Data Sheet. The product you purchased, Polyken 231 Tape, is not a hazardous substance as defined by the OSHA regulation; and therefore, we do not have MSD information available.

To be considered a hazardous substance (and therefore require an MSDS), a product must have shown statistically significant evidence, based on at least one study conducted in accordance with established scientific principles, that acute or chronic health effects may occur in exposed employees, and/or presents a significant physical hazard.

If additional information is required, please let me know, and I will contact the appropriate Research Scientist for an answer.

Sincerely,

THE KENDALL COMPANY

C. J. Cole

Charles J. Cole,
Manager, Regulatory Compliance

CJC:dm

Encl.
429