State of California—Health and Welfare Agency

Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD086510005 Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Co.
190th & Normandie Ave.
Torrance, CA 90502

A. State Manifest Document Number: 8492401 5

B. State Generator's ID

4. Generator's Phone (213-533-6677

5. Transporter 1 Company Name: Oil Process Co.

6. US EPA ID Number: CAD050806850

C. State Transporter's ID: 1065 2 2

D. Transporter's Phone: 213-585-5063

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
CASMALIA P.O. Box E NTU Road
Casmalia, CA 93429

10. US EPA ID Number: CAD020748125

G. State Facility's ID: CAD 020 748 125

H. Facility's Phone

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid NOS Corrosive	NA1760	001	TT	~~[illegible]~~ 02000	G	[illegible]
b.						
c.						
d.						

J. Additional Descriptions for Materials Listed Above: Nitric Acid 55% to 30% water remainder

K. Handling Codes for Wastes Listed Above: 8/2 (Acid)

15. Special Handling Instructions and Additional Information
Guide #60 PERMIT 3-6468
Use gloves, goggles, respirator - May cause severe burns to skin and eyes.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Donald C. Gerber sb — Signature: Donald C. Gerber — Date (Month Day Year): 07 05 85

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Tony Chiro — Signature: Tony Chiro 53862 — Date (Month Day Year): 07 05 85

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date (Month Day Year)

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
#52376-14,440lbs.

Printed/Typed Name: Casmalia Resourcees Carol Johnston — Signature: Carol Johnston — Date (Month Day Year): 07 05 85

GENERATOR

TRANSPORTER

FACILITY

8492401 5

DHS 8022 A (11/84)
(EPA 8700-22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

84 89641

BOE-C6-0217802

State of California—Health and Welfare Agency

~~8014~~ TK 400 0179

21721-53150

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5

Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Co.
190th & Normandie Ave.
Torrance, CA 90502

4. Generator's Phone (213-533-6677

A. State Manifest Document Number 84924015

B. State Generator's ID

5. Transporter 1 Company Name
~~Oil Process Co.~~ J.C. Liquid Waste

6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7

C. State Transporter's ID

D. Transporter's Phone 213-585-5063

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
CASMALIA P.O. Box E NTU Road
Casmalia, CA 93429

10. US EPA ID Number C A D 0 2 0 7 4 8 1 2 5

G. State Facility's ID

H. Facility's Phone

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid NOS Coorosive NA1760	001	TT	~~04500~~ 02000	G	111
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Nitric Acid 25% to 30%
Water remainder

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Guide #60 PERMIT 3-6468
Use gloves, goggles, respirator - May cause severe burns to skin and eyes.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Donald C. Gerber sb
Signature: [signature]
Date: Month Day Year 10 10 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: [illegible]
Signature: [illegible]
Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Date: Month Day Year

SCANNED

84924015

DHS 8022 A (11/84)
(EPA 8700-22)

YELLOW: GENERATOR RETAINS

84 89641

BOE-C6-0217803