State o[illegible]rnia—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD086510005
Manifest Document No.:
2. Page 1 of 2
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
DOUGLAS AIRCRAFT COMPANY
190th & NormandiesAve. Torrance, CA 90502
4. Generator's Phone (213) 533-6677

A. State Manifest Document Number: 84499418
B. State Generator's ID:

5. Transporter 1 Company Name: IT CORPORATION
6. US EPA ID Number: CAD 020748125 (000060740)
C. State Transporter's ID: 62965
D. Transporter's Phone: 213-518-4700

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
CASMALIA
P.O. BOX E, NTU ROAD
Casmalia, CA 93429
10. US EPA ID Number: CAD020748125
G. State Facility's ID:
H. Facility's Phone: 805-937-8449

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE FLAMMABLE SOLID N.O.S. UN 1325 FLAMMABLE MATERIAL	038	DM	14400	P	461
b. WASTE CORROSIVE SOLID N.O.S. UN 1759 CORROSIVE MATERIAL	021	DM	08400	P	352
c. WASTE OXIDIZER CORROSIVE N.O.S. UN 9194	011	DM	04400	P	352
d.					

J. Additional Descriptions for Materials Listed Above
A. Paint sludge solid absorbent vermiculity
B. Waste alkaline sodium hydroxide vermiculity
B. Waste chromic acid solid vermiculity
c. Waste Hydrochloric Acid solid absorbent vermiculity

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
GUIDE #32
USE GLOVES, GOGGLES

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name	Signature	Date Month Day Year
DONALD GERBER	[signature]	08 09 85

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month Day Year
EDMAN L DEHOFF	Edman L. Dehoff	08 09 85

18. Transporter 2 Acknowledgement or Receipt of Materials

Printed/Typed Name	Signature	Date Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date Month Day Year

GENERATOR / TRANSPORTER / FACI

DHS 8022 A (7/84)
(EPA 8700-22)

Yellow: GENERATOR RETAINS

84 89541

BOE-C6-0217871

Please print or type.
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST
(Continuation Sheet)

21. Generator's US EPA ID No.: CAD086510005
Manifest Document No.:
22. Page: 2
Information in the shaded areas is not required by Federal law.

23. Generator's Name
DOUGLAS AIRCRAFT COMPANY
190th & Normandie Street - Torrance, CA 90502

L. State Manifest Document Number: 84499418
M. State Generator's ID: CAD086510005

24. Transporter _____ Company Name: IT CORPORATION
25. US EPA ID Number: CAD000005 XX766 0
N. State Transporter's ID: 62965
O. Transporter's Phone: (213) 518-4700

26. Transporter _____ Company Name:
27. US EPA ID Number:
P. State Transporter's ID:
Q. Transporter's Phone:

	28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) HM	29. Containers No	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	Hazardous Waste Corrosive ORM-E UN9189	001	DM	0075	P	111
b.	Hazardous Waste Corrosive ORM-E UN9189	001	DM	0005	PP	111
c.	Hazardous Waste Corrosive ORM-E UN9189	001	DM	0005	P	111
d.	Hazardous Waste Corrosive ORM-E UN9189	001	DM	0005	P	111
e.	Hazardous waste solid ORM-F UN 9189	001	DM	0100	P	162
f.						
g.						
h.						
i						

S. Additional Descriptions for Materials Listed Above
A. 221 qt. Bottles Nickle Solution
1 1 qt. Bottle Copper Solution
1 1 qt. Bottle Tin Solution
6 1 qt. Bottle Cadmium Solution
3 3 oz. Bottle Cadmium Solution
B. Ammonium Hydroxide 1 qt. Bottle
C. Perchloric Acid 1 qt. Bottle
D. Pyridine 1 qt. bottle

T. Handling Codes for Wastes Listed Above

32. Special Handling Instructions and Additional Information
Permit 36468

USE GLOVES GOGGLES - ALTERNATE TSDF - return to generator

33. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JEDMAN L. DEHOFF
Signature: Jedman L. DeHoff 4482
Date: Month 08 Day 09 Year 85

34. Transporter _____ Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

35. Discrepancy Indication Space

GENERATOR
TRANSPORTER
FACILITY

EPA Form 8700-22 (3-84)

GENERATOR'S COPY

20-FS-C-7

BOE-C6-0217872