State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD086510005 — Manifest Document No.
2. Page 1 of 2 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
DOUGLAS AIRCRAFT COMPANY
190th & NormandieAve. Torrance, CA 90502

4. Generator's Phone (213) 533-6677

A. State Manifest Document Number: 84499418
B. State Generator's ID:

5. Transporter 1 Company Name: IT CORPORATION
6. US EPA ID Number: CAD000097760
C. State Transporter's ID: 62965
D. Transporter's Phone: 213-518-4700

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
CASMALIA
P.O. BOX E, NTU ROAD
Casmalia, CA 93429
10. US EPA ID Number: CAD020748125

G. State Facility's ID: CAD020748125
H. Facility's Phone: 805-937-8449

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE FLAMMABLE SOLID N.O.S. UN 1325 FLAMMABLE MATERIAL	038	DM	14400	P	461
b. WASTE CORROSIVE SOLID N.O.S. UN 1759 CORROSIVE MATERIAL	021	DM	08400	P	352
c. WASTE OXIDIZER CORROSIVE N.O.S. UN 9194	011	DM	04400	P	352
d.					

J. Additional Descriptions for Materials Listed Above
A. Paint sludge solid absorbent vermiculite
B. Waste alkaline sodium hydroxide vermiculite
B. Waste chromic acid solid vermiculite
c. Waste Hydrochloric Acid solid absorbent vermiculite

K. Handling Codes for Wastes Listed Above: 03

15. Special Handling Instructions and Additional Information
GUIDE #32
USE GLOVES, GOGGLES

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: DONALD GERBER — Signature: Donald R Gerber 2/48R — Date (Month Day Year): 08 09 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: EDMAN L. DEHOFF 105-4680 — Signature: Edman L. Dehoff — Date (Month Day Year): 08 09 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date (Month Day Year):

FACIL

19. Discrepancy Indication Space
Refused 1 drum Item E on Em't. unable to identify

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. #55831- R142165

Printed/Typed Name: Casmalia Resources Alice Priest — Signature: Alice Priest — Date (Month Day Year): 08 12 85

DHS 8022 A (7/84)
(EPA 8700-22)

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

SCANNED

84 89541

BOE-C6-0217884

Please print or type.
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST
(Continuation Sheet)

21. Generator's US EPA ID No.: CAD086510005
Manifest Document No.: . . . .

22. Page: 2

Information in the shaded areas is not required by Federal law.

23. Generator's Name
DOUGLAS AIRCRAFT COMPANY
190th & Normandie Street - Torrance, CA 90502

L. State Manifest Document Number: 84499418
M. State Generator's ID: CAD086510005

24. Transporter ____ Company Name: IT CORPORATION
25. US EPA ID Number: CAD000057760
N. State Transporter's ID: 62965
O. Transporter's Phone: (213) 518-4700

26. Transporter ____ Company Name:
27. US EPA ID Number: . . . . . .
P. State Transporter's ID:
Q. Transporter's Phone:

28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	HM	29. Containers No	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a. HAZARDOUS WASTE LIQUID NOS ~~Hazardous Waste Corrosive~~ ORM-E ~~UN~~ NA 9189		001	DM	0075	P	111
b. HAZARDOUS WASTE LIQUID NOS ~~Hazardous Waste Corrosive~~ ORM-E ~~UN~~ NA 9189		001	DM	0005	P	111
c. HAZARDOUS WASTE LIQUID NOS ~~Hazardous Waste Corrosive~~ ORM-E ~~UN~~ NA 9189		001	DM	0005	P	111
d. HAZARDOUS WASTE LIQUID NOS ~~Hazardous Waste Corrosive~~ ORM-E ~~UN~~ NA 9189		001	DM	0005	P	111
e. Hazardous waste solid ORM-F UN 9189		001	DM	0100	P	162
f.						
g.						
h.						
i						

S. Additional Descriptions for Materials Listed Above
A. 2 1 qt. Bottles Nickle Solution R
1 1 qt. Bottle Copper Solution
1 1 qt. Bottle Tin Solution
6 1 qt. Bottle Cadmium Solution R
3 3 oz. Bottle Cadmium Solution R
B. Ammonium Hydroxide 1 qt. Bottle
C. Perchloric Acid 1 qt. Bottle
D. Pyeidine 1 qt. bottle

T. Handling Codes for Wastes Listed Above: 03

32. Special Handling Instructions and Additional Information
Permit 36468

USE GLOVES GOGGLES - ALTERNATE TSDF - return to generator

33. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: TEDMAN L DEHOFF
Signature: Tedman L. DeHoff 4482
Date: Month 08 Day 09 Year 85

34. Transporter ____ Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month . Day . Year .

35. Discrepancy Indication Space

SCANNED

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22 (3-84)

ORIGINATOR — RETURN TO GENERATOR

20-FS-C-7

BOE-C6-0217885