State of California—Health and Welfare Agency

RESALE

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD086510005 — Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Co.
190th & Normandie Ave.
Torrance, CA 90502

4. Generator's Phone (213-533-6677

A. State Manifest Document Number 84924126

B. State Generator's ID

5. Transporter 1 Company Name: Industrial Service Co.

6. US EPA ID Number: CAD099452708

C. State Transporter's ID 64061

D. Transporter's Phone 262-9747

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
INDUSTRIAL SERVICE
1700 S. Soto Lane
CA 90023

10. US EPA ID Number: CAD099452708

G. State Facility's ID

H. Facility's Phone 213-262-9747

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Oil NOS Petroleum Combustiable NA 1270	001	TT	09.690	P	221
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Waste Oil
Waste Hydraulic

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
#27
Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Donald C. Gerber sb — Signature — Date (Month Day Year): 02 17 86

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: John Shubin Jr — Signature — Date (Month Day Year): 02 17 86

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date (Month Day Year)

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: JOHN SHUBIN — Signature — Date (Month Day Year): 02 17 86

GENERATOR — TRANSPORTER — FACILITY

84924126

YELLOW: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

DHS 8022 A (11/84)
(EPA 8700-22)

84 89641

BOE-C6-0218281

State of California—Health and Welfare Agency

RESALE

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. CAD086510005 — Manifest Document No.

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Co.
190th & Normandie Ave.
Torrance, CA 90502

4. Generator's Phone (213-533-6677

A. State Manifest Document Number 84924126

B. State Generator's ID

5. Transporter 1 Company Name: Industrial Service Co.

6. US EPA ID Number: CAD099452708

C. State Transporter's ID 64061

D. Transporter's Phone

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID 262-9747

F. Transporter's Phone

9. Designated Facility Name and Site Address
INDUSTRIAL SERVICE
1700 S. Soto Lane
CA 90023

10. US EPA ID Number: CAD099452708

G. State Facility's ID

H. Facility's Phone

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Oil NOS Petroleum Combustiable NA 1270	001	TT	09690	P	221
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Waste Oil
Waste Hydraulic

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
#27
Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Donald C. Gerber sb — Signature — Date (Month Day Year): 02 17 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: John Shulaw Jr — Signature — Date (Month Day Year): 02 17 86

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date (Month Day Year)

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date (Month Day Year)

84924126

YELLOW: GENERATOR RETAINS

DHS 8022 A (11/84)
(EPA 8700-22)

84 89641

BOE-C6-0218282