State of California—Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5
Manifest Document No.
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Dougles Aircrafft Company
190th ST & Normandie Ave. Torrance CA 90502
4. Generator's Phone (213) 533-6677

A. State Manifest Document Number 84827674
B. State Generator's ID

5. Transporter 1 Company Name: J.C. Liquid Waste Disposal
6. US EPA ID Number: C A D 0 5 8 0 1 8 3 6
C. State Transporter's ID 64157
D. Transporter's Phone 213 268 3137

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
IT Corp.
896 Waterbird Way
Martinez, CA 94553
10. US EPA ID Number: C A D 0 0 0 0 9 4 7 7 1
G. State Facility's ID C A D 0 0 0 0 9 4 7 7 1
H. Facility's Phone 415 228-5100

GENERATOR

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid NOS Corrosive NA 1760	0 0 1	TT	0 4 5 0 0	G	112
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Sulfuric Acid 13 %
Sodium Dichromate 3 %
Chromic Acid 1 %
Water 83 %

K. Handling Codes for Wastes Listed Above
15/06

15. Special Handling Instructions and Additional Information
Guide# 60
Use gloves, goggles, respirator- May cause sever burns to skin and eyes.
Profile# 4633

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Donald E Gerber
Signature: Donald E Gerber
Date (Month Day Year): 10 21 86

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Dan T Romero 58055
Signature: Dan T Romero
Date (Month Day Year): 10 21 86

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date (Month Day Year)

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Richard J Baie
Signature: Richard J. Baie
Date (Month Day Year): 10 21 86

YELLOW: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

DHS 8022 A (11/84)
(EPA 8700-22)

84 89641

84827674

BOE-C6-0218528

6BZ281629 ~~96/202 86/101-0347~~ 21/21-63426

State of California — Health and Welfare Agency

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD086510005 | Manifest Document No.: | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Company
190th ST & Normandie Ave. Torrance CA 90502

4. Generator's Phone (213) 533-6677

A. State Manifest Document Number: 84827674

B. State Generator's ID:

5. Transporter 1 Company Name: J.C.Liquid Waste Disposal

6. US EPA ID Number: CAD058018367

C. State Transporter's ID: 64157

D. Transporter's Phone: 213 268 3137

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
IT Corp.
896 Waterbird Way
Martinez, CA 94553

10. US EPA ID Number: CAD000094771

G. State Facility's ID: CAD000094771

H. Facility's Phone: 415 228-5100

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid NOS Corrosive NA 1760	001	TT	04500	G	112
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Sulfuric Acid 13 %
Sodium Dichromate 3 %
Chromic Acid 1 %
Water 83 %

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Guide# 60
Use gloves, goggles, respirator- May cause sever burns to skin and eyes. Profile# 4633

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.

Printed/Typed Name: Donald E Gerber | Signature: [signature] | Date: Month 02 Day 18 Year 86

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: [illegible] 58033 | Signature: [signature] | Date: Month 02 Day 18 Year 86

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: | Signature: | Date: Month Day Year

GENERATOR

TRANSPORTER

FACILITY

84827674

DHS 8022 A (11/84)
(EPA 8700-22)

YELLOW: GENERATOR RETAINS

84 89641

BOE-C6-0218529