State of California—Health and Welfare Agency TK 195 & 9-T (15)

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD086510005 — Manifest Document No.: 000000

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Company
190th St. & Normandie Ave. Torrance, CA90502

4. Generator's Phone (213) 533-6677

A. State Manifest Document Number: 86234322

B. State Generator's ID: HA-HQ-36-005698 CAD086510005

5. Transporter 1 Company Name: IT ~~XXXX~~ Transportation

6. US EPA ID Number: CAD029654894

C. State Transporter's ID: 708099

D. Transporter's Phone: 213 830-1781

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
IT Corp.
896 Waterbird Way
Martinez, CA94553

10. US EPA ID Number: CAD000094771

G. State Facility's ID: CAD000094771

H. Facility's Phone: 415 372-5800

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid N.O.S. Corrosive NA1760	001	TT	4000	G	D002-111
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Chromic Acid 0-14%
Sulfuric Acid 0-14%
Hydrofluric -1%
NitricAcid 0-14%
Remainder Water

K. Handling Codes for Wastes Listed Above: 08/06

15. Special Handling Instructions and Additional Information
Guide #60 E.H. 3-9950 Profile # 4819
Use gloves, goggles, respirator - May cause severe burns to skin and eyes.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.
Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: Donald C Gerber — Signature: Donald Gerber — Month Day Year: 02 18 87

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: DAVID WALIZER — Signature: [signature] — Month Day Year: 2 18 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year:

19. Discrepancy Indication Space
Load is Non-EH per Bob Tomko at Douglas Aircraft 1616 02/18/87 RJB

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Rick Baie — Signature: Rick Baie — Month Day Year: 02 18 87

86234322

DHS 8022 A (11/85)
(EPA 8700—22)

YELLOW: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

BOE-C6-0218838

IT CORPORATION - ENVIRONMENTAL, VINE HILL FACILITY

INCOMPLETE AND / OR DISCREPANCY MANIFEST REPORT FORM

GENERATOR'S NAME: Douglas AirCraft

TRANSPORTER'S NAME: ITW

MANIFEST NO. 86234322

DATE: 02/18/87

State of California—Health and Welfare Agency
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Department of Health Services
Toxic Substances Control Division
Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
Manifest Document No.
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
A. State Manifest Document Number: 86499376
B. State Generator's ID
4. Generator's Phone ( )
5. Transporter 1 Company Name
6. US EPA ID Number
C. State Transporter's ID
D. Transporter's Phone
7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone
9. Designated Facility Name and Site Address
10. US EPA ID Number
G. State Facility's ID
H. Facility's Phone

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit WV/Vol	I. Waste No.
a.					
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.
Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.
Printed/Typed Name | Signature | Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Month Day Year

GENERATOR — TRANSPORTER — FACILITY

86 499376

DHS 8022 A (11/85)
(EPA 8700--22)

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento CA 95812

IDENTIFY SPECIFIC INCOMPLETION AND /OR DISCREPANCY:

Load is Non EH

NAME & TITLE OF GENERATOR COMPANY'S AUTHORIZED AGENT GRANTING APPROVAL:

Bob Tomko

DATE AND TIME CONTACT MADE:

1616 02/18/87

NAME OR TRANSPORTING COMPANY'S DISPATCHER- IF USED:

SIGNATURE OF PERSON RESOLVING INCOMPLETENESS DISCREPANCY: [signature]

C6-700-87-IT-0069

21722-71816

State of California—Health and Welfare Agency TK 195 & 9-T

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. *(Form designed for use on elite (12-pitch) typewriter.)*

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: CAD086510005 — Manifest Document No.: 000000
2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Douglas Aircraft Company
190th St. & Normandie Ave. Torrance, CA90502

4. Generator's Phone (213) 533-6677

A. State Manifest Document Number: 86234322

B. State Generator's ID: HA-HQ-36-005698 CAD086510005

5. Transporter 1 Company Name: IT ~~XXXX~~ Transportation
6. US EPA ID Number: CAD029654894

C. State Transporter's ID: 708099

D. Transporter's Phone: 213 830-1781

7. Transporter 2 Company Name:
8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
IT Corp.
896 Waterbird Way
Martinez, CA94553

10. US EPA ID Number: CAD000094771

G. State Facility's ID: CAD000094771

H. Facility's Phone: 415 372-5800

11. US DOT Description *(Including Proper Shipping Name, Hazard Class, and ID Number)*	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid N.O.S. Corrosive NA1760	001	TT	4000	G	D002-111
b.					
c.					
d.					

J. Additional Descriptions for Materials Listed Above
Chromic Acid 0-14%
Sulfuric Acid 0-14%
Hydrofluric -1%
NitricAcid 0-14%
Remainder Water

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional information
Guide #60 E.H. 3-9950 Profile # 4819
Use gloves, goggles, respirator - May cause severe burns to skin and eyes.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.
Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.

Printed/Typed Name: Donald C Gerber — Signature: [signature] — Month Day Year: 02 18 87

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: DAVID WALIZER — Signature: [signature] — Month Day Year: 2 18 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Month Day Year:

GENERATOR — TRANSPORTER — FACILITY

86234322

DHS 8022 A (11/85)
(EPA 8700—22)

YELLOW GENERATOR RETAINS

BOE-C6-0218840