U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

REC'D NOV 12 1987

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

MD CAN
DPM 68663

SECTION I

MANUFACTURER'S NAME: BURLINGTON INDUSTRIES	EMERGENCY TELEPHONE NO.: None
ADDRESS (Number, Street, City, State, and ZIP Code): 50 Chestnut Ridge Road; Montvale, NJ	
CHEMICAL NAME AND SYNONYMS: Nylon Type 6, 6 Fabric	TRADE NAME AND SYNONYMS: Burlease 51789, 52006, 41661
CHEMICAL FAMILY: Polyamide	FORMULA: N/A

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	0		BASE METAL	0	
CATALYST	0		ALLOYS	0	
VEHICLE	0		METALLIC COATINGS	0	
SOLVENTS	0		FILLER METAL PLUS COATING OR CORE FLUX	0	
ADDITIVES	0		OTHERS	0	
OTHERS	0			0	

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES	%	TLV (Units)
None.		

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	N/A	SPECIFIC GRAVITY (H_2O=1)	1.14
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)	N/A
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (_____ =1)	N/A
SOLUBILITY IN WATER	1%		
APPEARANCE AND ODOR			

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	N/A	FLAMMABLE LIMITS	Lel	Uel

EXTINGUISHING MEDIA: N/A

SPECIAL FIRE FIGHTING PROCEDURES: None

UNUSUAL FIRE AND EXPLOSION HAZARDS: None Known

(Continued on reverse side)

Form OSHA-20
Rev. May 72

OCT 21 '87 12:43 BURLINGTON-MONTVALE P.2/3

BOE-C6-0225965

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE	None established by OSHA
EFFECTS OF OVEREXPOSURE	No known effect
EMERGENCY AND FIRST AID PROCEDURES	N/A

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
INCOMPATABILITY *(Materials to avoid)*	Strong acids, alkalies and oxidizers		
HAZARDOUS DECOMPOSITION PRODUCTS	Carbon and Nitrogen Oxide		
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	N/A
WASTE DISPOSAL METHOD	Landfill or incineration in accord with all local, state and federal regulations.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION *(Specify type)*	N/A			
VENTILATION	LOCAL EXHAUST	N/A	SPECIAL	N/A
	MECHANICAL *(General)*	N/A	OTHER	N/A
PROTECTIVE GLOVES	N/A	EYE PROTECTION	N/A	
OTHER PROTECTIVE EQUIPMENT	N/A			

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	Recommend storage temperature 30°- 100°F
OTHER PRECAUTIONS	Follow good industrial hygenic handling practices.

Form OSHA-20
Rev. May 72

OCT 21 '87 12:44 BURLINGTON-MONTVALE P.3/3

BOE-C6-0225966