Bruin
E&P OPERATING, LLC

January 10, 2019

U.S. Environmental Protection Agency
Director, Air and Toxics Technical Enforcement Program
Office of Enforcement, Compliance, and Environmental Justice
Mail Code 8ENF-AT
1595 Wynkoop Street
Denver, Colorado 80202-1129

RE: NSPS Subpart OOOO Annual Report - 2018

To Whom It May Concern:

Bruin E&P Operating, LLC is submitting this annual report for its NSPS Subpart OOOO affected facility storage vessels for the reporting year 2018; i.e. October 16, 2017 – October 15, 2018 as required by 40 §CFR 60.5420(b). Table 1 provides the information required at §60.5420(b)(1)(i)-(iv). Records of deviations as required by §60.5420(b)(6)(iii) are included as an attachment.

40 CFR 60.5420(b)(6)(v) requires a statement that the requirement outlined at 40 CFR §60.5410(h)(2) and (3) have been met for each affected facility storage vessel. Bruin E&P Operating, LLC has successfully reduced emissions by more than 95 percent for each affected facility storage vessel.

If there are any questions or concerns about this report, please call me at (701) 575-9931 or contact me by email at jtraster@bruinep.com.

Sincerely,

Julia Traster Rowe

Julia Traster Rowe
Environmental Specialist

Attachments

Cc: Dustin Grosulak - HSE Manager
Kennon Doyal – Chief Operations Officer
Mike Obrigewitch – Production Superintendent
Tim McGhee – EVP Land, Regulatory, and HSE
Kurt Butler – Completions and Production Manager

Table 1
§60.5420(b)(1)(i-iv)

(i) Company Name: Company Address:	Bruin E&P LLC 602 Sawyer Street Suite 410 Houston, Tx. 77007							
(ii) Affected Storage Vessel Facility Locations and Names	Facility Name	Location			Facility Status		Storage Vessels	
		Lattitude	Longitude	State	Previously Constructed	Constructed During Reporting Period	Manufacturer	Serial Number
	Antero Well Pad	47.617846 N	-102.704403 W	ND	X		True North Steel	3827T
							True North Steel	4274T
							True North Steel	4259T
							True North Steel	3863T
							True North Steel	3818T
							True North Steel	4256T
							True North Steel	4235T
							True North Steel	3823T
	Diente Well Pad	47.58761 N	-102.64500 W	ND	X		True North Steel	3843T
							True North Steel	4997
							True North Steel	5960T
							True North Steel	5069T
							True North Steel	5078T
							True North Steel	5062
							Steffes	SCT0714609
							Steffes	SCT0715325
							Steffes	SCT0714629
							Steffes	SCT0714599
							True North Steel	5075T
							True North Steel	3844T
	Sunshine Well Pad One fiberglass water tank #3-8368 was removed and replaced with a steel crude oil tank #7141F	47.618759 N	-102.740775 W	ND	X		True North Steel	6378F
							True North Steel	6383F
							True North Steel	6381F
							True North Steel	6384F
							True North Steel	7141F
							True North Steel	6382F
							True North Steel	6380F
							True North Steel	6385F
							Permian Lide	3-8342
							Permian Lide	3-8366
							Permian Lide	3-8360
							Permian Lide	3-8367
	Tabeguache Well Pad	47.603692 N	-102.647104 W	ND	X		True North Steel	7138F
							True North Steel	7140F
							True North Steel	7136F
							True North Steel	7135F
							True North Steel	7137F
							True North Steel	7139F
							True North Steel	7141F
							Permian Lide	3-8666
							Permian Lide	3-8667
							Permian Lide	3-8665
							Permian Lide	3-8676
							Permian Lide	3-8661
	Sherman Well Pad	47.632657 N	-102.689198 W	ND	X		True North Steel	6376F
							True North Steel	6377F
							True North Steel	6379F
							True North Steel	6373F
							True North Steel	6375F
							True North Steel	6374F
							True North Steel	6372F
							Permian Lide	8-8352
							Permian Lide	3-8341
							Permian Lide	3-8357
							Permian Lide	3-8353
							Permian Lide	3-8343

Table 1
§60.5420(b)(1)(i-iv)

(I) Company Name: Company Address:	Bruin E&P LLC 602 Sawyer Street Suite 410 Houston, Tx. 77007							
		Location			Facility Status		Storage Vessels	
(II) Affected Storage Vessel Facility Locations and Names	Facility Name	Lattitude	Longitude	State	Previously Constructed	Constructed During Reporting Period	Manufacturer	Serial Number
(III) Reporting Period		October 16, 2017 - October 15, 2018						
(Iv) Responsible Official Certification:		Based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete.						
Name:	Kennon Doyal	Title:	Chief Operating Officer					
Signature:	Kennon Doyal	Date:	1/10/19					

§60.5420(b)(6)(iii)
RECORDS OF DEVIATIONS
Attachment
(Summary of Inspection Findings)

Summary of Inspection Findings October 16, 2017 – October 15, 2018	
Antero	Leaking Hatches and PRV were detected and repaired in: Oct '17, Nov '17, Mar '18, Aug '18, and Sept '18. The PRV was removed in Apr '18.
Diente	Leaking Hatches were detected and repaired in: Oct '17, Nov '17, Jan '18, Mar '18, May '18, Jul '18, Aug '18, Sept '18, and Oct '18. A hole in a fiberglass tank was found and repaired in Feb '18. A leaking vent line connection was found and repaired in Apr '18. The PRV was removed in Apr '18.
Sunshine	Leaking Hatches were detected and repaired in: Oct '17, Nov '17, Jan '18, Feb '18, Mar '18, May '18, Jun '18, and Sept '18. The PRV was removed in Apr '18.
Tabeguache	Leaking Hatches were detected and repaired in: Oct '17, Nov '17, Mar '18, May '18, Jul '18, Aug '18, and Sept '18. The PRV was removed in Apr '18.
Sherman	Leaking Hatches and PRV were detected and repaired in: Oct '17, Nov '17, Dec '17, Jan '18, May '18, June '18, Sept '18, and Nov '18. The PRV was removed in Mar '18.