- Low point bleeders for all four compressors when your blind compressor there are high point bleeders before suction pots after leaves discharge pot no bleeder point before blind.
  DC 4-14-2010

KS 4/28/10

- Sarco pot set up for DeBrv B/O block valves dont open/close
- Low pres condisate line B/O another leak above LV-59A replace?
- P-1119 Discharge block bad and check valve
- P-1188 seal flush leak
- steam leak up in pipeway above resin sample leak in multiple places cannot issolate
- P-1168A seal flush leak 4s/c always accumulates along seal flush line into pump
- Replace suction & Discharge temp probes on all compressors still waiting on the ones for K-1171A

11 TC533 LEAKS BY TO E1107: 44mBPD ON 11F1501 WHEN VALVE is CLOSED

- PV-972 control does not hold leaks by
- Block valve downstream PV972 broke

6/14/10 KS

P1119 suction valve leaks by.
P1119 1st valve to P.O. on suction line leaks by per Crash.

K1100A 1st Stg outlet bleeder → relief/P1171B - one valve leaks by, broken wheel.

P1101C Suction valve needs fix - near impossible to isolate pump. DD 10/26/10

1/6/11