41420 10331 102364

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number IND 005 462 601	2. Page 1 of 1	3. Emergency Response Phone (219) 399-2492	4. Manifest Tracking Number 020192014 JJK

5. Generator's Name and Mailing Address ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	1	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (219)242-9834
Trailer # 220

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Tim Sugrony
Signature: Tim Sugrony
Month 1 Day 29 Year 20

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Transporter signature (for exports only):
Port of entry/exit:
Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Venditti
Signature:
Month 01 Day 29 Year 20
Transporter 2 Printed/Typed Name
Signature
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: LEONARD F. ITRY
Signature:
Month 01 Day 29 Year 20

GENERATOR
INT'L
TRANSPORTER
DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

103409

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 02189926 3 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	001	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (219)242-9834

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: ANNETTE PRICE
Signature: Annette Price
Month 4 Day 20 Year 20

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: David Peterson
Signature:
Month 4 Day 20 Year 20
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Steve Parke
Signature:
Month 04 Day 10 Year 20

EPA Form 8700-22 (Rev. 12-17). Previous editions are obsolete. DESIGNATED FACILITY TO EPA's e-MANIFEST SYSTEM

103615

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 02189947I JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	001	DT	15	Y	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Haico (219)242-9834

Dump-220

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable International and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: ANNIETTE PRICE
Signature:
Month 4 Day 28 Year 20

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Transporter signature (for exports only):
Port of entry/exit:
Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 4 Day 28 Year 20
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

18b. Alternate Facility (or Generator)
Manifest Reference Number:
U.S. EPA ID Number:
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Shawn Rabe
Signature:
Month 04 Day 28 Year 20

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO EPA's e-MANIFEST SYSTEM

104116

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021900954 JJK

5. Generator's Name and Mailing Address ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	001	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (219)242-9834
Trailer # 222

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: ANNETTE PRICE | Signature | Month 6 | Day 10 | Year 20

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Vendiff | Signature | Month 06 | Day 10 | Year 20
Transporter 2 Printed/Typed Name | Signature | Month | Day | Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) | Month | Day | Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki | Signature | Month 6 | Day 10 | Year 20

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

V

104259

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021898202 JJK

5. Generator's Name and Mailing Address
ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address
ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	001	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (219)242-9834

Dump-220

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Tim Susorenig
Signature: Tim Susorenig
Month 6 Day 22 Year 20

GENERATOR

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature
Month 6 Day 22 Year 20
Transporter 2 Printed/Typed Name
Signature
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Stephen DeLoy
Signature
Month 6 Day 22 Year 20

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

104356

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021298074 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	1	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (219)242-9934

Am P-222

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Tim Susorney
Signature: Tim Susorney
Month 6 Day 29 Year 20

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Port of entry/exit:
Transporter signature (for exports only):
Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 6 Day 29 Year 20

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy

18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: Steve Parker
Signature:
Month 06 Day 29 Year 20

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

104630

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021908194 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399-3189~~
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, ((F006)), ERG #171	01	DT	20	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (215)242-9834

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: A. CRAWFORD
Signature:
Month 7 Day 17 Year 20

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Marcus Barnes
Signature:
Month 07 Day 17 Year 20
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Stephen Dolan
Signature:
Month 7 Day 17 Year 20

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

104478

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 402 601	1	(219) 399-2492	021082318 JJK

5. Generator's Name and Mailing Address ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	1	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Nalco (219)242-9834

Trailer # 220

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Carl Geib
Signature: Carl Geib
Month 7 Day 9 Year 20

GENERATOR

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Venditti
Signature:
Month 07 Day 09 Year 20
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month 7 Day 9 Year 20

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

104959

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 022162200 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address):

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. ,(Chromium), 9, PGIII, (F006), ERG #171	001	DT	15	T	F006	D007	
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
. 10331 / CENTRAL TREATMENT PLANT SLUDGE / Emergency Contact: Kevin Martin w/Naico (219)242-9834

Trailer # 220

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: ENRIQUE FERNANDEZ
Signature:
Month 8 Day 7 Year 2020

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Port of entry/exit:
Date leaving U.S.:
Transporter signature (for exports only):

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Venditti
Signature:
Month 08 Day 07 Year 20
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Steve Pache
Signature:
Month 09 Day 07 Year 20

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO EPA's e-MANIFEST SYSTEM

28 - 00 - 4638500